



Shenzhen Xtooltech Co., Ltd

SUZUKI Function List V9.50

Tips and Instructions:

The programming function only supports H6PRO, H6PRO Master Edition products.

* This feature is new.

✓ This feature is supported.

This feature is not supported.

※ This feature is partially supported.

| Destination | Model | System Name | Read ECU Information | Read Trouble Code | Clear Trouble Code | Live Data | Actuation Test | Special Functions |
|-------------|-----------|--------------|----------------------|-------------------|--------------------|-----------|----------------|---|
| JAPAN | Landy C25 | ECM | √ | √ | √ | √ | √ | SP334,SP523,SP385,SP383,SP210,SP209,SP219,SP205,SP242,SP226,SP227,SP228,SP229,SP230,SP231,SP217,SP215,SP206,SP234,SP235,SP240,SP218,SP232,SP221,SP222,SP214,SP223,SP611,SP612,SP613,SP220,SP212,SP237,SP211,SP213,SP224,SP200,SP225,SP216,SP201,SP202,SP203,SP239,SP236,SP233,SP668,SP669,SP670,SP679,SP238,SP629,SP243,SP241,SP683,SP684,SP680,SP714,SP715 |
| JAPAN | Landy C25 | TCM | √ | √ | √ | √ | √ | |
| JAPAN | Landy C25 | ABS/ESP | √ | √ | √ | √ | √ | |
| JAPAN | Landy C25 | PAS | √ | √ | √ | √ | √ | |
| JAPAN | Landy C25 | SRS | √ | √ | √ | √ | √ | |
| JAPAN | Landy C25 | BCM | √ | √ | √ | √ | √ | |
| JAPAN | Landy C25 | I-KEY | √ | √ | √ | √ | √ | |
| JAPAN | Landy C25 | IPDM E/R | √ | √ | √ | √ | √ | |
| JAPAN | Landy C25 | IPC | √ | √ | √ | √ | √ | |
| JAPAN | Landy C25 | ASD-L | √ | √ | √ | √ | √ | |
| JAPAN | Landy C25 | ASD-R | √ | √ | √ | √ | √ | |
| JAPAN | Landy C25 | ALC | √ | √ | √ | √ | √ | |
| JAPAN | Landy C25 | MOTOR-ASSIST | √ | √ | √ | √ | √ | |
| JAPAN | Landy C25 | AFS | √ | √ | √ | √ | √ | |
| Canada | Equator | ECM | √ | √ | √ | √ | √ | SP334,SP523,SP385,SP383,SP210,SP209,SP219,SP205,SP242,SP226,SP227,SP228,SP229,SP230,SP231,SP217,SP215,SP206,SP234,SP235,SP240,SP218,SP232,SP221,SP222,SP214,SP223,SP611,SP612,SP613,SP220,SP212,SP237,SP211,SP213,SP224,SP200,SP225,SP216,SP201,SP202,SP203,SP239,SP236,SP233,SP668,SP669,SP670,SP679,SP238,SP629,SP243,SP241,SP683,SP684,SP680,SP714,SP715 |
| Canada | Equator | TCM | √ | √ | √ | √ | √ | |
| Canada | Equator | ABS/ESP | √ | √ | √ | √ | √ | |
| Canada | Equator | SRS | √ | √ | √ | √ | √ | |
| Canada | Equator | BCM | √ | √ | √ | √ | √ | |
| Canada | Equator | 4WD | √ | √ | √ | √ | √ | |
| Canada | Equator | IPDM E/R | √ | √ | √ | √ | √ | |
| Canada | Equator | IPC | √ | √ | √ | √ | √ | |
| Canada | Equator | DIFFLOCK | √ | √ | √ | √ | √ | |

| | | | | | | | | |
|--------|--------|----------------------------------|---|---|---|---|---|--|
| Canada | others | ECM | √ | √ | √ | √ | √ | SP334, SP523, SP385, SP383, SP210, SP209, SP219, SP205, SP242, SP226, SP227, SP228, SP229, SP230, SP231, SP217, SP215, SP206, SP234, SP235, SP240, SP218, SP232, SP221, SP222, SP214, SP223, SP611, SP612, SP613, SP220, SP212, SP237, SP211, SP213, SP224, SP200, SP225, SP216, SP201, SP202, SP203, SP239, SP236, SP233, SP668, SP669, SP670, SP679, SP238, SP629, SP243, SP241, SP683, SP684, SP680, SP714, SP715 |
| Canada | others | TCM | √ | √ | √ | √ | √ | SP561, SP562, SP563, SP564, SP565, SP566, SP567, SP568, SP569, SP570, SP571, SP572, SP573, SP529, SP528, SP530, SP531, SP532, SP321, SP322, SP323, SP324, SP618, SP713, SP326, SP316, SP325, SP617, SP319, SP320, SP318, SP315 |
| Canada | others | ABS/ESP | √ | √ | √ | √ | √ | SP354, SP355, SP360, SP358, SP353, SP349, SP350, SP352, SP359, SP351, SP356, SP170, SP172, SP176, SP179, SP174, SP177, SP175, SP178, SP171, SP173 |
| Canada | others | PAS | √ | √ | √ | √ | √ | SP255 |
| Canada | others | SRS | √ | √ | √ | √ | √ | |
| Canada | others | AC | √ | √ | √ | √ | √ | |
| Canada | others | AC2 | √ | √ | √ | √ | √ | |
| Canada | others | BCM | √ | √ | √ | √ | √ | SP380, SP375, SP378, SP381, SP379, SP377, SP376, SP196, SP192, SP191, SP195 |
| Canada | others | OCM | √ | √ | √ | √ | √ | |
| Canada | others | 4WD | √ | √ | √ | √ | √ | |
| Canada | others | IMMOBILIZER-ON-DIAG | √ | √ | √ | √ | √ | SP303 |
| Canada | others | IMMOBILIZER-ON-DIAG | √ | √ | √ | √ | √ | |
| Canada | others | EMCD | √ | √ | √ | √ | √ | |
| Canada | others | EV MOTOR | √ | √ | √ | √ | √ | |
| Canada | others | EV AC | √ | √ | √ | √ | √ | |
| Canada | others | TPMS | √ | √ | √ | √ | √ | SP331, SP533 |
| Canada | others | IPC | √ | √ | √ | √ | √ | SP298, SP297, SP616, SP293, SP295, SP614, SP300, SP615, SP662, SP296, SP301 |
| Canada | others | ALC | √ | √ | √ | √ | √ | SP189 |
| Canada | others | SCC | √ | √ | √ | √ | √ | |
| Canada | others | ACCM | √ | √ | √ | √ | √ | SP182, SP183 |
| Canada | others | CNG/LPG | √ | √ | √ | √ | √ | |
| Canada | others | ICM | √ | √ | √ | √ | √ | SP265, SP266, SP268, SP269, SP270, SP267 |
| Canada | others | RBS | √ | √ | √ | √ | √ | SP310, SP719, SP718, SP309 |
| Canada | others | BMU | √ | √ | √ | √ | √ | |
| Canada | others | TCU | √ | √ | √ | √ | √ | SP328, SP329, SP330, SP682 |
| Canada | others | ADM | √ | √ | √ | √ | √ | SP185, SP186, SP187, SP660, SP661 |
| Canada | others | SCAM | √ | √ | √ | √ | √ | SP313, SP314, SP312 |
| Canada | others | ISG | √ | √ | √ | √ | √ | |
| Canada | others | CSW | √ | √ | √ | √ | √ | |
| Canada | others | GW | √ | √ | √ | √ | √ | SP256 |
| Canada | others | HCU | √ | √ | √ | √ | √ | SP257, SP258, SP259 |
| Canada | others | HVBMU | √ | √ | √ | √ | √ | SP260, SP261, SP622, SP262 |
| Canada | others | INV | √ | √ | √ | √ | √ | |
| Canada | others | Acoustic Vehicle Alerting System | √ | √ | √ | √ | √ | |
| Canada | others | MFL | √ | √ | √ | √ | √ | SP307 |
| Canada | others | Head-Up Display | √ | √ | √ | √ | √ | |

| | | | | | | | | |
|--------|---------|---------------------|---|---|---|---|---|--|
| Canada | others | CGW | √ | √ | √ | √ | √ | |
| Canada | others | Sonar | √ | √ | √ | √ | √ | SP671 |
| Canada | others | Blind Spot Monitor | √ | √ | √ | √ | √ | SP674 |
| Canada | others | Auto-On Headlight | √ | √ | √ | √ | √ | SP717 |
| Canada | others | Dosing Control Unit | √ | √ | √ | √ | √ | |
| US | Equator | ECM | √ | √ | √ | √ | √ | SP334, SP523, SP385, SP383, SP210, SP209, SP219, SP205, SP242, SP226, SP227, SP228, SP229, SP230, SP231, SP217, SP215, SP206, SP234, SP235, SP240, SP218, SP232, SP221, SP222, SP214, SP223, SP611, SP612, SP613, SP220, SP212, SP237, SP211, SP213, SP224, SP200, SP225, SP216, SP201, SP202, SP203, SP239, SP236, SP233, SP668, SP669, SP670, SP679, SP238, SP629, SP243, SP241, SP683, SP684, SP680, SP714, SP715 |
| US | Equator | TCM | √ | √ | √ | √ | √ | |
| US | Equator | ABS/ESP | √ | √ | √ | √ | √ | |
| US | Equator | SRS | √ | √ | √ | √ | √ | |
| US | Equator | BCM | √ | √ | √ | √ | √ | |
| US | Equator | 4WD | √ | √ | √ | √ | √ | |
| US | Equator | IPDM E/R | √ | √ | √ | √ | √ | |
| US | Equator | IPC | √ | √ | √ | √ | √ | |
| US | Equator | DIFFLOCK | √ | √ | √ | √ | √ | |
| US | others | ECM | √ | √ | √ | √ | √ | SP334, SP523, SP385, SP383, SP210, SP209, SP219, SP205, SP242, SP226, SP227, SP228, SP229, SP230, SP231, SP217, SP215, SP206, SP234, SP235, SP240, SP218, SP232, SP221, SP222, SP214, SP223, SP611, SP612, SP613, SP220, SP212, SP237, SP211, SP213, SP224, SP200, SP225, SP216, SP201, SP202, SP203, SP239, SP236, SP233, SP668, SP669, SP670, SP679, SP238, SP629, SP243, SP241, SP683, SP684, SP680, SP714, SP715 |
| US | others | TCM | √ | √ | √ | √ | √ | SP561, SP562, SP563, SP564, SP565, SP566, SP567, SP568, SP569, SP570, SP571, SP572, SP573, SP529, SP528, SP530, SP531, SP532, SP321, SP322, SP323, SP324, SP618, SP713, SP326, SP316, SP325, SP617, SP319, SP320, SP318, SP315 |
| US | others | ABS/ESP | √ | √ | √ | √ | √ | SP354, SP355, SP360, SP358, SP353, SP349, SP350, SP352, SP359, SP351, SP356, SP170, SP172, SP176, SP179, SP174, SP177, SP175, SP178, SP171, SP173 |
| US | others | PAS | √ | √ | √ | √ | √ | SP255 |
| US | others | SRS | √ | √ | √ | √ | √ | |
| US | others | AC | √ | √ | √ | √ | √ | |
| US | others | BCM | √ | √ | √ | √ | √ | SP380, SP375, SP378, SP381, SP379, SP377, SP376, SP196, SP192, SP191, SP195 |
| US | others | OCM | √ | √ | √ | √ | √ | |
| US | others | 4WD | √ | √ | √ | √ | √ | |
| US | others | IMMOBILIZER-ON-DIAG | √ | √ | √ | √ | √ | SP303 |
| US | others | IMMOBILIZER-ON-DIAG | √ | √ | √ | √ | √ | |
| US | others | EMCD | √ | √ | √ | √ | √ | |
| US | others | EV MOTOR | √ | √ | √ | √ | √ | |
| US | others | EV AC | √ | √ | √ | √ | √ | |
| US | others | TPMS | √ | √ | √ | √ | √ | SP331, SP533 |
| US | others | IPC | √ | √ | √ | √ | √ | SP298, SP297, SP616, SP293, SP295, SP614, SP300, SP615, SP662, SP296, SP301 |

| | | | | | | | | |
|-------|----------|----------------------------------|---|---|---|---|---|--|
| US | others | ALC | √ | √ | √ | √ | √ | SP189 |
| US | others | SCC | √ | √ | √ | √ | √ | |
| US | others | ACCM | √ | √ | √ | √ | √ | SP182,SP183 |
| US | others | CNG/LPG | √ | √ | √ | √ | √ | |
| US | others | ICM | √ | √ | √ | √ | √ | SP265,SP266,SP268,SP269,SP270,SP267 |
| US | others | RBS | √ | √ | √ | √ | √ | SP310,SP719,SP718,SP309 |
| US | others | BMU | √ | √ | √ | √ | √ | |
| US | others | TCU | √ | √ | √ | √ | √ | SP328, SP329, SP330, SP682 |
| US | others | ADM | √ | √ | √ | √ | √ | SP185,SP186,SP187,SP660,SP661 |
| US | others | SCAM | √ | √ | √ | √ | √ | SP313, SP314, SP312 |
| US | others | ISG | √ | √ | √ | √ | √ | |
| US | others | CSW | √ | √ | √ | √ | √ | |
| US | others | GW | √ | √ | √ | √ | √ | SP256 |
| US | others | HCU | √ | √ | √ | √ | √ | SP257, SP258, SP259 |
| US | others | HVBMU | √ | √ | √ | √ | √ | SP260,SP261,SP622,SP262 |
| US | others | INV | √ | √ | √ | √ | √ | |
| US | others | Acoustic Vehicle Alerting System | √ | √ | √ | √ | √ | |
| US | others | MFL | √ | √ | √ | √ | √ | SP307 |
| US | others | Head-Up Display | √ | √ | √ | √ | √ | |
| US | others | CGW | √ | √ | √ | √ | √ | |
| US | others | Sonar | √ | √ | √ | √ | √ | SP671 |
| US | others | Blind Spot Monitor | √ | √ | √ | √ | √ | SP674 |
| US | others | Auto-On Headlight | √ | √ | √ | √ | √ | SP717 |
| US | others | Dosing Control Unit | √ | √ | √ | √ | √ | |
| Other | Wagon R+ | ECM | √ | √ | √ | √ | √ | SP334, SP523, SP385, SP383, SP210, SP209, SP219, SP205, SP242, SP226, SP227, SP228, SP229, SP230, SP231, SP217, SP215, SP206, SP234, SP235, SP240, SP218, SP232, SP221, SP222, SP214, SP223, SP611, SP612, SP613, SP220, SP212, SP237, SP211, SP213, SP224, SP200, SP225, SP216, SP201, SP202, SP203, SP239, SP236, SP233, SP668, SP669, SP670, SP679, SP238, SP629, SP243, SP241, SP683, SP684, SP680, SP714, SP715 |
| Other | Wagon R+ | ABS/ESP | √ | √ | √ | √ | √ | SP354,SP355,SP360,SP358,SP353,SP349,SP350,SP352,SP359,SP351,SP356,SP170,SP172,SP176,SP179,SP174,SP177,SP175,SP178,SP171,SP173 |
| Other | Wagon R+ | PAS | √ | √ | √ | √ | √ | SP255 |
| Other | Wagon R+ | SRS | √ | √ | √ | √ | √ | |
| Other | Wagon R+ | AC | √ | √ | √ | √ | √ | |
| Other | Wagon R+ | AC2 | √ | √ | √ | √ | √ | |
| Other | Wagon R+ | BCM | √ | √ | √ | √ | √ | SP380,SP375,SP378,SP381,SP379,SP377,SP376,SP196,SP192,SP191,SP195 |
| Other | Wagon R+ | OCM | √ | √ | √ | √ | √ | |
| Other | Wagon R+ | 4WD | √ | √ | √ | √ | √ | |
| Other | Wagon R+ | IMMOBILIZER-ON-DIAG | √ | √ | √ | √ | √ | SP303 |
| Other | Wagon R+ | IMMOBILIZER-ON-DIAG | √ | √ | √ | √ | √ | |
| Other | Wagon R+ | EMCD | √ | √ | √ | √ | √ | |
| Other | Wagon R+ | TPMS | √ | √ | √ | √ | √ | SP331, SP533 |
| Other | Wagon R+ | IPC | √ | √ | √ | √ | √ | SP298,SP297,SP616,SP293,SP295,SP614,SP300,SP615,SP662,SP296,SP301 |
| Other | Wagon R+ | ALC | √ | √ | √ | √ | √ | SP189 |
| Other | Wagon R+ | SCC | √ | √ | √ | √ | √ | |

| | | | | | | | | |
|-------|----------|----------------------------------|---|---|---|---|---|--|
| Other | Wagon R+ | ACCM | √ | √ | √ | √ | √ | SP182, SP183 |
| Other | Wagon R+ | CNG/LPG | √ | √ | √ | √ | √ | |
| Other | Wagon R+ | ICM | √ | √ | √ | √ | √ | SP265, SP266, SP268, SP269, SP270, SP267 |
| Other | Wagon R+ | RBS | √ | √ | √ | √ | √ | SP310, SP719, SP718, SP309 |
| Other | Wagon R+ | TCM | √ | √ | √ | √ | √ | SP561, SP562, SP563, SP564, SP565, SP566, SP567, SP568, SP569, SP570, SP571, SP572, SP573, SP529, SP528, SP530, SP531, SP532, SP321, SP322, SP323, SP324, SP618, SP713, SP326, SP316, SP325, SP617, SP319, SP320, SP318, SP315 |
| Other | Wagon R+ | EV MOTOR | √ | √ | √ | √ | √ | |
| Other | Wagon R+ | EV AC | √ | √ | √ | √ | √ | |
| Other | Wagon R+ | BMU | √ | √ | √ | √ | √ | |
| Other | Wagon R+ | TCU | √ | √ | √ | √ | √ | SP328, SP329, SP330, SP682 |
| Other | Wagon R+ | ADM | √ | √ | √ | √ | √ | SP185, SP186, SP187, SP660, SP661 |
| Other | Wagon R+ | SCAM | √ | √ | √ | √ | √ | SP313, SP314, SP312 |
| Other | Wagon R+ | ISG | √ | √ | √ | √ | √ | |
| Other | Wagon R+ | CSW | √ | √ | √ | √ | √ | |
| Other | Wagon R+ | GW | √ | √ | √ | √ | √ | SP256 |
| Other | Wagon R+ | HCU | √ | √ | √ | √ | √ | SP257, SP258, SP259 |
| Other | Wagon R+ | HVBMU | √ | √ | √ | √ | √ | SP260, SP261, SP622, SP262 |
| Other | Wagon R+ | INV | √ | √ | √ | √ | √ | |
| Other | Wagon R+ | Acoustic Vehicle Alerting System | √ | √ | √ | √ | √ | |
| Other | Wagon R+ | MFL | √ | √ | √ | √ | √ | SP307 |
| Other | Wagon R+ | Head-Up Display | √ | √ | √ | √ | √ | |
| Other | Wagon R+ | CGW | √ | √ | √ | √ | √ | |
| Other | Wagon R+ | Sonar | √ | √ | √ | √ | √ | SP671 |
| Other | Wagon R+ | Blind Spot Monitor | √ | √ | √ | √ | √ | SP674 |
| Other | Wagon R+ | Auto-On Headlight | √ | √ | √ | √ | √ | SP717 |
| Other | Wagon R+ | Dosing Control Unit | √ | √ | √ | √ | √ | |
| Other | Baleno | ECM | √ | √ | √ | √ | √ | SP334, SP523, SP385, SP383, SP210, SP209, SP219, SP205, SP242, SP226, SP227, SP228, SP229, SP230, SP231, SP217, SP215, SP206, SP234, SP235, SP240, SP218, SP232, SP221, SP222, SP214, SP223, SP611, SP612, SP613, SP220, SP212, SP237, SP211, SP213, SP224, SP200, SP225, SP216, SP201, SP202, SP203, SP239, SP236, SP233, SP668, SP669, SP670, SP679, SP238, SP629, SP243, SP241, SP683, SP684, SP680, SP714, SP715 |
| Other | Baleno | ABS/ESP | √ | √ | √ | √ | √ | SP354, SP355, SP360, SP358, SP353, SP349, SP350, SP352, SP359, SP351, SP356, SP170, SP172, SP176, SP179, SP174, SP177, SP175, SP178, SP171, SP173 |
| Other | Baleno | PAS | √ | √ | √ | √ | √ | SP255 |
| Other | Baleno | SRS | √ | √ | √ | √ | √ | |
| Other | Baleno | BCM | √ | √ | √ | √ | √ | SP380, SP375, SP378, SP381, SP379, SP377, SP376, SP196, SP192, SP191, SP195 |
| Other | Baleno | IPC | √ | √ | √ | √ | √ | SP298, SP297, SP616, SP293, SP295, SP614, SP300, SP615, SP662, SP296, SP301 |
| Other | Baleno | CSW | √ | √ | √ | √ | √ | |
| Other | Baleno | CGW | √ | √ | √ | √ | √ | |
| Other | Baleno | TCM | √ | √ | √ | √ | √ | SP561, SP562, SP563, SP564, SP565, SP566, SP567, SP568, SP569, SP570, SP571, SP572, SP573, SP529, SP528, SP530, SP531, SP532, SP321, SP322, SP323, SP324, SP618, SP713, SP326, SP316, SP325, SP617, SP319, SP320, SP318, SP315 |

| | | | | | | | | |
|-------|---------------|----------------------------------|---|---|---|---|---|--|
| Other | Baleno | AC | √ | √ | √ | √ | √ | |
| Other | Baleno | AC2 | √ | √ | √ | √ | √ | |
| Other | Baleno | OCM | √ | √ | √ | √ | √ | |
| Other | Baleno | 4WD | √ | √ | √ | √ | √ | |
| Other | Baleno | IMMOBILIZER-ON-DIAG | √ | √ | √ | √ | √ | SP303 |
| Other | Baleno | IMMOBILIZER-ON-DIAG | √ | √ | √ | √ | √ | |
| Other | Baleno | EMCD | √ | √ | √ | √ | √ | |
| Other | Baleno | TPMS | √ | √ | √ | √ | √ | SP331,SP533 |
| Other | Baleno | ALC | √ | √ | √ | √ | √ | SP189 |
| Other | Baleno | SCC | √ | √ | √ | √ | √ | |
| Other | Baleno | ACCM | √ | √ | √ | √ | √ | SP182,SP183 |
| Other | Baleno | CNG/LPG | √ | √ | √ | √ | √ | |
| Other | Baleno | ICM | √ | √ | √ | √ | √ | SP265, SP266, SP268, SP269, SP270, SP267 |
| Other | Baleno | RBS | √ | √ | √ | √ | √ | SP310, SP719, SP718, SP309 |
| Other | Baleno | OCM | √ | √ | √ | √ | √ | |
| Other | Baleno | EV MOTOR | √ | √ | √ | √ | √ | |
| Other | Baleno | EV AC | √ | √ | √ | √ | √ | |
| Other | Baleno | ACCM | √ | √ | √ | √ | √ | SP182,SP183 |
| Other | Baleno | BMU | √ | √ | √ | √ | √ | |
| Other | Baleno | TCU | √ | √ | √ | √ | √ | SP328,SP329,SP330,SP682 |
| Other | Baleno | ADM | √ | √ | √ | √ | √ | SP185,SP186,SP187,SP660,SP661 |
| Other | Baleno | SCAM | √ | √ | √ | √ | √ | SP313, SP314, SP312 |
| Other | Baleno | ISG | √ | √ | √ | √ | √ | |
| Other | Baleno | GW | √ | √ | √ | √ | √ | SP256 |
| Other | Baleno | HCU | √ | √ | √ | √ | √ | SP257,SP258,SP259 |
| Other | Baleno | HVBMU | √ | √ | √ | √ | √ | SP260, SP261, SP622, SP262 |
| Other | Baleno | INV | √ | √ | √ | √ | √ | |
| Other | Baleno | Acoustic Vehicle Alerting System | √ | √ | √ | √ | √ | |
| Other | Baleno | MFL | √ | √ | √ | √ | √ | SP307 |
| Other | Baleno | Head-Up Display | √ | √ | √ | √ | √ | |
| Other | Baleno | Sonar | √ | √ | √ | √ | √ | SP671 |
| Other | Baleno | Blind Spot Monitor | √ | √ | √ | √ | √ | SP674 |
| Other | Baleno | Auto-On Headlight | √ | √ | √ | √ | √ | SP717 |
| Other | Baleno | Dosing Control Unit | √ | √ | √ | √ | √ | |
| Other | CIAZ(AVB413D) | ECM | √ | √ | √ | √ | √ | SP334, SP523, SP385, SP383, SP210, SP209, SP219, SP205, SP242, SP226, SP227, SP228, SP229, SP230, SP231, SP217, SP215, SP206, SP234, SP235, SP240, SP218, SP232, SP221, SP222, SP214, SP223, SP611, SP612, SP613, SP220, SP212, SP237, SP211, SP213, SP224, SP200, SP225, SP216, SP201, SP202, SP203, SP239, SP236, SP233, SP668, SP669, SP670, SP679, SP238, SP629, SP243, SP241, SP683, SP684, SP680, SP714, SP715 |
| Other | CIAZ(AVB413D) | ABS/ESP | √ | √ | √ | √ | √ | SP354, SP355, SP360, SP358, SP353, SP349, SP350, SP352, SP359, SP351, SP356, SP170, SP172, SP176, SP179, SP174, SP177, SP175, SP178, SP171, SP173 |
| Other | CIAZ(AVB413D) | PAS | √ | √ | √ | √ | √ | SP255 |
| Other | CIAZ(AVB413D) | SRS | √ | √ | √ | √ | √ | |
| Other | CIAZ(AVB413D) | AC | √ | √ | √ | √ | √ | |
| Other | CIAZ(AVB413D) | BCM | √ | √ | √ | √ | √ | SP380, SP375, SP378, SP381, SP379, SP377, SP376, SP196, SP192, SP191, SP195 |

| | | | | | | | | |
|-------|---------------|----------------------------------|---|---|---|---|---|---|
| Other | CIAZ(AVB413D) | IMMOBILIZER-ON-DIAG | √ | √ | √ | √ | √ | SP303 |
| Other | CIAZ(AVB413D) | IPC | √ | √ | √ | √ | √ | SP298, SP297, SP616, SP293, SP295, SP614, SP300, SP615, SP662, SP296, SP301 |
| Other | CIAZ(AVB413D) | TCM | √ | √ | √ | √ | √ | SP561,SP562,SP563,SP564,SP565,SP566,SP567,SP568,SP569,SP570,SP571,SP572,SP573,SP529,SP528,SP530,SP531,SP532,SP321,SP322,SP323,SP324,SP618,SP713,SP326,SP316,SP325,SP617,SP319,SP320,SP318,SP315 |
| Other | CIAZ(AVB413D) | AC2 | √ | √ | √ | √ | √ | |
| Other | CIAZ(AVB413D) | OCM | √ | √ | √ | √ | √ | |
| Other | CIAZ(AVB413D) | 4WD | √ | √ | √ | √ | √ | |
| Other | CIAZ(AVB413D) | IMMOBILIZER-ON-DIAG | √ | √ | √ | √ | √ | |
| Other | CIAZ(AVB413D) | EMCD | √ | √ | √ | √ | √ | |
| Other | CIAZ(AVB413D) | EV MOTOR | √ | √ | √ | √ | √ | |
| Other | CIAZ(AVB413D) | EV AC | √ | √ | √ | √ | √ | |
| Other | CIAZ(AVB413D) | TPMS | √ | √ | √ | √ | √ | SP331,SP533 |
| Other | CIAZ(AVB413D) | ALC | √ | √ | √ | √ | √ | SP189 |
| Other | CIAZ(AVB413D) | SCC | √ | √ | √ | √ | √ | |
| Other | CIAZ(AVB413D) | ACCM | √ | √ | √ | √ | √ | SP182,SP183 |
| Other | CIAZ(AVB413D) | CNG/LPG | √ | √ | √ | √ | √ | |
| Other | CIAZ(AVB413D) | ICM | √ | √ | √ | √ | √ | SP265,SP266,SP268,SP269,SP270,SP267 |
| Other | CIAZ(AVB413D) | RBS | √ | √ | √ | √ | √ | SP310,SP719,SP718,SP309 |
| Other | CIAZ(AVB413D) | BMU | √ | √ | √ | √ | √ | |
| Other | CIAZ(AVB413D) | TCU | √ | √ | √ | √ | √ | SP328, SP329, SP330, SP682 |
| Other | CIAZ(AVB413D) | ADM | √ | √ | √ | √ | √ | SP185, SP186, SP187, SP660, SP661 |
| Other | CIAZ(AVB413D) | SCAM | √ | √ | √ | √ | √ | SP313, SP314, SP312 |
| Other | CIAZ(AVB413D) | ISG | √ | √ | √ | √ | √ | |
| Other | CIAZ(AVB413D) | CSW | √ | √ | √ | √ | √ | |
| Other | CIAZ(AVB413D) | GW | √ | √ | √ | √ | √ | SP256 |
| Other | CIAZ(AVB413D) | HCU | √ | √ | √ | √ | √ | SP257, SP258, SP259 |
| Other | CIAZ(AVB413D) | HVBMU | √ | √ | √ | √ | √ | SP260,SP261,SP622,SP262 |
| Other | CIAZ(AVB413D) | INV | √ | √ | √ | √ | √ | |
| Other | CIAZ(AVB413D) | Acoustic Vehicle Alerting System | √ | √ | √ | √ | √ | |
| Other | CIAZ(AVB413D) | MFL | √ | √ | √ | √ | √ | SP307 |
| Other | CIAZ(AVB413D) | Head-Up Display | √ | √ | √ | √ | √ | |
| Other | CIAZ(AVB413D) | CGW | √ | √ | √ | √ | √ | |
| Other | CIAZ(AVB413D) | Sonar | √ | √ | √ | √ | √ | SP671 |
| Other | CIAZ(AVB413D) | Blind Spot Monitor | √ | √ | √ | √ | √ | SP674 |
| Other | CIAZ(AVB413D) | Auto-On Headlight | √ | √ | √ | √ | √ | SP717 |
| Other | CIAZ(AVB413D) | Dosing Control Unit | √ | √ | √ | √ | √ | |
| Other | Ertiga | ECM | √ | √ | √ | √ | √ | SP334,SP523,SP385,SP383,SP210,SP209,SP219,SP205,SP242,SP226,SP227,SP228,SP229,SP230,SP231,SP217,SP215,SP206,SP234,SP235,SP240,SP218,SP232,SP221,SP222,SP214,SP223,SP611,SP612,SP613,SP220,SP212,SP237,SP211,SP213,SP224,SP200,SP225,SP216,SP201,SP202,SP203,SP239,SP236,SP233,SP668,SP669,SP670,SP679,SP238,SP629,SP243,SP241,SP683,SP684,SP680,SP714,SP715 |
| Other | Ertiga | TCM | √ | √ | √ | √ | √ | SP561,SP562,SP563,SP564,SP565,SP566,SP567,SP568,SP569,SP570,SP571,SP572,SP573,SP529,SP528,SP530,SP531,SP532,SP321,SP322,SP323,SP324,SP618,SP713,SP326,SP316,SP325,SP617,SP319,SP320,SP318,SP315 |

| | | | | | | | | |
|-------|--------------|----------------------------------|---|---|---|---|---|---|
| Other | Ertiga | ABS/ESP | √ | √ | √ | √ | √ | SP354,SP355,SP360,SP358,SP353,SP349,SP350,SP352,SP359,SP351,SP356,SP170,SP172,SP176,SP179,SP174,SP177,SP175,SP178,SP171,SP173 |
| Other | Ertiga | PAS | √ | √ | √ | √ | √ | SP255 |
| Other | Ertiga | SRS | √ | √ | √ | √ | √ | |
| Other | Ertiga | AC | √ | √ | √ | √ | √ | |
| Other | Ertiga | AC2 | √ | √ | √ | √ | √ | |
| Other | Ertiga | BCM | √ | √ | √ | √ | √ | SP380, SP375, SP378, SP381, SP379, SP377, SP376, SP196, SP192, SP191, SP195 |
| Other | Ertiga | OCM | √ | √ | √ | √ | √ | |
| Other | Ertiga | 4WD | √ | √ | √ | √ | √ | |
| Other | Ertiga | IMMOBILIZER-ON-DIAG | √ | √ | √ | √ | √ | SP303 |
| Other | Ertiga | IMMOBILIZER-ON-DIAG | √ | √ | √ | √ | √ | |
| Other | Ertiga | EMCD | √ | √ | √ | √ | √ | |
| Other | Ertiga | EV MOTOR | √ | √ | √ | √ | √ | |
| Other | Ertiga | EV AC | √ | √ | √ | √ | √ | |
| Other | Ertiga | TPMS | √ | √ | √ | √ | √ | SP331, SP533 |
| Other | Ertiga | IPC | √ | √ | √ | √ | √ | SP298,SP297,SP616,SP293,SP295,SP614,SP300,SP615,SP662,SP296,SP301 |
| Other | Ertiga | ALC | √ | √ | √ | √ | √ | SP189 |
| Other | Ertiga | SCC | √ | √ | √ | √ | √ | |
| Other | Ertiga | ACCM | √ | √ | √ | √ | √ | SP182,SP183 |
| Other | Ertiga | CNG/LPG | √ | √ | √ | √ | √ | |
| Other | Ertiga | ICM | √ | √ | √ | √ | √ | SP265,SP266,SP268,SP269,SP270,SP267 |
| Other | Ertiga | RBS | √ | √ | √ | √ | √ | SP310,SP719,SP718,SP309 |
| Other | Ertiga | BMU | √ | √ | √ | √ | √ | |
| Other | Ertiga | TCU | √ | √ | √ | √ | √ | SP328,SP329,SP330,SP682 |
| Other | Ertiga | ADM | √ | √ | √ | √ | √ | SP185,SP186,SP187,SP660,SP661 |
| Other | Ertiga | SCAM | √ | √ | √ | √ | √ | SP313,SP314,SP312 |
| Other | Ertiga | ISG | √ | √ | √ | √ | √ | |
| Other | Ertiga | CSW | √ | √ | √ | √ | √ | |
| Other | Ertiga | GW | √ | √ | √ | √ | √ | SP256 |
| Other | Ertiga | HCU | √ | √ | √ | √ | √ | SP257, SP258, SP259 |
| Other | Ertiga | HVBMU | √ | √ | √ | √ | √ | SP260, SP261, SP622, SP262 |
| Other | Ertiga | INV | √ | √ | √ | √ | √ | |
| Other | Ertiga | Acoustic Vehicle Alerting System | √ | √ | √ | √ | √ | |
| Other | Ertiga | MFL | √ | √ | √ | √ | √ | SP307 |
| Other | Ertiga | Head-Up Display | √ | √ | √ | √ | √ | |
| Other | Ertiga | CGW | √ | √ | √ | √ | √ | |
| Other | Ertiga | Sonar | √ | √ | √ | √ | √ | SP671 |
| Other | Ertiga | Blind Spot Monitor | √ | √ | √ | √ | √ | SP674 |
| Other | Ertiga | Auto-On Headlight | √ | √ | √ | √ | √ | SP717 |
| Other | Ertiga | Dosing Control Unit | √ | √ | √ | √ | √ | |
| Other | Grand Vitara | ECM | √ | √ | √ | √ | √ | SP334,SP523,SP385,SP383,SP210,SP209,SP219,SP205,SP242,SP226,SP227,SP228,SP229,SP230,SP231,SP217,SP215,SP206,SP234,SP235,SP240,SP218,SP232,SP221,SP222,SP214,SP223,SP611,SP612,SP613,SP220,SP212,SP237,SP211,SP213,SP224,SP200,SP225,SP216,SP201,SP202,SP203,SP239,SP236,SP233,SP668,SP669,SP670,SP679,SP238,SP629,SP243,SP241,SP683,SP684,SP680,SP714,SP715 |

| | | | | | | | | |
|-------|--------------|----------------------------------|---|---|---|---|---|---|
| Other | Grand Vitara | TCM | √ | √ | √ | √ | √ | SP561,SP562,SP563,SP564,SP565,SP566,SP567,SP568,SP569,SP570,SP571,SP572,SP573,SP529,SP528,SP530,SP531,SP532,SP321,SP322,SP323,SP324,SP618,SP713,SP326,SP316,SP325,SP617,SP319,SP320,SP318,SP315 |
| Other | Grand Vitara | ABS/ESP | √ | √ | √ | √ | √ | SP354,SP355,SP360,SP358,SP353,SP349,SP350,SP352,SP359,SP351,SP356,SP170,SP172,SP176,SP179,SP174,SP177,SP175,SP178,SP171,SP173 |
| Other | Grand Vitara | PAS | √ | √ | √ | √ | √ | SP255 |
| Other | Grand Vitara | SRS | √ | √ | √ | √ | √ | |
| Other | Grand Vitara | AC | √ | √ | √ | √ | √ | |
| Other | Grand Vitara | AC2 | √ | √ | √ | √ | √ | |
| Other | Grand Vitara | BCM | √ | √ | √ | √ | √ | SP380,SP375,SP378,SP381,SP379,SP377,SP376,SP196,SP192,SP191,SP195 |
| Other | Grand Vitara | OCM | √ | √ | √ | √ | √ | |
| Other | Grand Vitara | 4WD | √ | √ | √ | √ | √ | |
| Other | Grand Vitara | IMMOBILIZER-ON-DIAG | √ | √ | √ | √ | √ | SP303 |
| Other | Grand Vitara | IMMOBILIZER-ON-DIAG | √ | √ | √ | √ | √ | |
| Other | Grand Vitara | EMCD | √ | √ | √ | √ | √ | |
| Other | Grand Vitara | TPMS | √ | √ | √ | √ | √ | SP331, SP533 |
| Other | Grand Vitara | ALC | √ | √ | √ | √ | √ | SP189 |
| Other | Grand Vitara | SCC | √ | √ | √ | √ | √ | |
| Other | Grand Vitara | ACCM | √ | √ | √ | √ | √ | SP182, SP183 |
| Other | Grand Vitara | CNG/LPG | √ | √ | √ | √ | √ | |
| Other | Grand Vitara | ICM | √ | √ | √ | √ | √ | SP265, SP266, SP268, SP269, SP270, SP267 |
| Other | Grand Vitara | RBS | √ | √ | √ | √ | √ | SP310, SP719, SP718, SP309 |
| Other | Grand Vitara | EV MOTOR | √ | √ | √ | √ | √ | |
| Other | Grand Vitara | EV AC | √ | √ | √ | √ | √ | |
| Other | Grand Vitara | BMU | √ | √ | √ | √ | √ | |
| Other | Grand Vitara | TCU | √ | √ | √ | √ | √ | SP328,SP329,SP330,SP682 |
| Other | Grand Vitara | ADM | √ | √ | √ | √ | √ | SP185,SP186,SP187,SP660,SP661 |
| Other | Grand Vitara | SCAM | √ | √ | √ | √ | √ | SP313, SP314, SP312 |
| Other | Grand Vitara | ISG | √ | √ | √ | √ | √ | |
| Other | Grand Vitara | CSW | √ | √ | √ | √ | √ | |
| Other | Grand Vitara | GW | √ | √ | √ | √ | √ | SP256 |
| Other | Grand Vitara | HCU | √ | √ | √ | √ | √ | SP257, SP258, SP259 |
| Other | Grand Vitara | HVBMU | √ | √ | √ | √ | √ | SP260, SP261, SP622, SP262 |
| Other | Grand Vitara | INV | √ | √ | √ | √ | √ | |
| Other | Grand Vitara | Acoustic Vehicle Alerting System | √ | √ | √ | √ | √ | |
| Other | Grand Vitara | MFL | √ | √ | √ | √ | √ | SP307 |
| Other | Grand Vitara | Head-Up Display | √ | √ | √ | √ | √ | |
| Other | Grand Vitara | CGW | √ | √ | √ | √ | √ | |
| Other | Grand Vitara | Sonar | √ | √ | √ | √ | √ | SP671 |
| Other | Grand Vitara | Blind Spot Monitor | √ | √ | √ | √ | √ | SP674 |
| Other | Grand Vitara | Auto-On Headlight | √ | √ | √ | √ | √ | SP717 |
| Other | Grand Vitara | Dosing Control Unit | √ | √ | √ | √ | √ | |

| | | | | | | | | |
|-------|-------|---------------------|---|---|---|---|---|--|
| Other | Ignis | ECM | √ | √ | √ | √ | √ | SP334, SP523, SP385, SP383, SP210, SP209, SP219, SP205, SP242, SP226, SP227, SP228, SP229, SP230, SP231, SP217, SP215, SP206, SP234, SP235, SP240, SP218, SP232, SP221, SP222, SP214, SP223, SP611, SP612, SP613, SP220, SP212, SP237, SP211, SP213, SP224, SP200, SP225, SP216, SP201, SP202, SP203, SP239, SP236, SP233, SP668, SP669, SP670, SP679, SP238, SP629, SP243, SP241, SP683, SP684, SP680, SP714, SP715 |
| Other | Ignis | TCM | √ | √ | √ | √ | √ | SP561, SP562, SP563, SP564, SP565, SP566, SP567, SP568, SP569, SP570, SP571, SP572, SP573, SP529, SP528, SP530, SP531, SP532, SP321, SP322, SP323, SP324, SP618, SP713, SP326, SP316, SP325, SP617, SP319, SP320, SP318, SP315 |
| Other | Ignis | ABS/ESP | √ | √ | √ | √ | √ | SP354, SP355, SP360, SP358, SP353, SP349, SP350, SP352, SP359, SP351, SP356, SP170, SP172, SP176, SP179, SP174, SP177, SP175, SP178, SP171, SP173 |
| Other | Ignis | PAS | √ | √ | √ | √ | √ | SP255 |
| Other | Ignis | SRS | √ | √ | √ | √ | √ | |
| Other | Ignis | AC | √ | √ | √ | √ | √ | |
| Other | Ignis | AC2 | √ | √ | √ | √ | √ | |
| Other | Ignis | BCM | √ | √ | √ | √ | √ | |
| Other | Ignis | OCM | √ | √ | √ | √ | √ | |
| Other | Ignis | 4WD | √ | √ | √ | √ | √ | |
| Other | Ignis | IMMOBILIZER-ON-DIAG | √ | √ | √ | √ | √ | SP303 |
| Other | Ignis | IMMOBILIZER-ON-DIAG | √ | √ | √ | √ | √ | |
| Other | Ignis | EMCD | √ | √ | √ | √ | √ | |
| Other | Ignis | TPMS | √ | √ | √ | √ | √ | SP331, SP533 |
| Other | Ignis | IPC | √ | √ | √ | √ | √ | SP298, SP297, SP616, SP293, SP295, SP614, SP300, SP615, SP662, SP296, SP301 |
| Other | Ignis | ALC | √ | √ | √ | √ | √ | SP189 |
| Other | Ignis | SCC | √ | √ | √ | √ | √ | |
| Other | Ignis | ACCM | √ | √ | √ | √ | √ | SP182, SP183 |
| Other | Ignis | CNG/LPG | √ | √ | √ | √ | √ | |
| Other | Ignis | ICM | √ | √ | √ | √ | √ | SP265, SP266, SP268, SP269, SP270, SP267 |
| Other | Ignis | RBS | √ | √ | √ | √ | √ | SP310, SP719, SP718, SP309 |
| Other | Ignis | OCM | √ | √ | √ | √ | √ | |
| Other | Ignis | EMCD | √ | √ | √ | √ | √ | |
| Other | Ignis | EV MOTOR | √ | √ | √ | √ | √ | |
| Other | Ignis | EV AC | √ | √ | √ | √ | √ | |
| Other | Ignis | ALC | √ | √ | √ | √ | √ | SP189 |
| Other | Ignis | ICM | √ | √ | √ | √ | √ | SP265, SP266, SP268, SP269, SP270, SP267 |
| Other | Ignis | BMU | √ | √ | √ | √ | √ | |
| Other | Ignis | TCU | √ | √ | √ | √ | √ | SP328, SP329, SP330, SP682 |
| Other | Ignis | ADM | √ | √ | √ | √ | √ | SP185, SP186, SP187, SP660, SP661 |
| Other | Ignis | SCAM | √ | √ | √ | √ | √ | SP313, SP314, SP312 |
| Other | Ignis | ISG | √ | √ | √ | √ | √ | |
| Other | Ignis | CSW | √ | √ | √ | √ | √ | |
| Other | Ignis | GW | √ | √ | √ | √ | √ | SP256 |
| Other | Ignis | HCU | √ | √ | √ | √ | √ | SP257, SP258, SP259 |
| Other | Ignis | HVBMU | √ | √ | √ | √ | √ | SP260, SP261, SP622, SP262 |
| Other | Ignis | INV | √ | √ | √ | √ | √ | |

| | | | | | | | | |
|-------|----------------|----------------------------------|---|---|---|---|---|---|
| Other | Ignis | Acoustic Vehicle Alerting System | √ | √ | √ | √ | √ | |
| Other | Ignis | MFL | √ | √ | √ | √ | √ | SP307 |
| Other | Ignis | Head-Up Display | √ | √ | √ | √ | √ | |
| Other | Ignis | CGW | √ | √ | √ | √ | √ | |
| Other | Ignis | Sonar | √ | √ | √ | √ | √ | SP671 |
| Other | Ignis | Blind Spot Monitor | √ | √ | √ | √ | √ | SP674 |
| Other | Ignis | Auto-On Headlight | √ | √ | √ | √ | √ | SP717 |
| Other | Ignis | Dosing Control Unit | √ | √ | √ | √ | √ | |
| Other | IGNIS(ATM413D) | ECM | √ | √ | √ | √ | √ | SP334,SP523,SP385,SP383,SP210,SP209,SP219,SP205,SP242,SP226,SP227,SP228,SP229,SP230,SP231,SP217,SP215,SP206,SP234,SP235,SP240,SP218,SP232,SP221,SP222,SP214,SP223,SP611,SP612,SP613,SP220,SP212,SP237,SP211,SP213,SP224,SP200,SP225,SP216,SP201,SP202,SP203,SP239,SP236,SP233,SP668,SP669,SP670,SP679,SP238,SP629,SP243,SP241,SP683,SP684,SP680,SP714,SP715 |
| Other | IGNIS(ATM413D) | TCM | √ | √ | √ | √ | √ | SP321, SP322, SP323, SP324, SP618, SP713, SP326, SP316, SP325, SP617, SP319, SP320, SP318, SP315 |
| Other | IGNIS(ATM413D) | ABS/ESP | √ | √ | √ | √ | √ | SP170,SP172,SP176,SP179,SP174,SP177,SP175,SP178,SP171,SP173 |
| Other | IGNIS(ATM413D) | PAS | √ | √ | √ | √ | √ | SP255 |
| Other | IGNIS(ATM413D) | SRS | √ | √ | √ | √ | √ | |
| Other | IGNIS(ATM413D) | AC | √ | √ | √ | √ | √ | |
| Other | IGNIS(ATM413D) | BCM | √ | √ | √ | √ | √ | SP196, SP192, SP191, SP195 |
| Other | IGNIS(ATM413D) | IMMOBILIZER-ON-DIAG | √ | √ | √ | √ | √ | SP303 |
| Other | IGNIS(ATM413D) | IPC | √ | √ | √ | √ | √ | SP298, SP297, SP616, SP293, SP295, SP614, SP300, SP615, SP662, SP296, SP301 |
| Other | IGNIS(ATM413D) | ALC | √ | √ | √ | √ | √ | SP189 |
| Other | Jimny DDIS | ECM | √ | √ | √ | √ | √ | SP334,SP523,SP385,SP383,SP210,SP209,SP219,SP205,SP242,SP226,SP227,SP228,SP229,SP230,SP231,SP217,SP215,SP206,SP234,SP235,SP240,SP218,SP232,SP221,SP222,SP214,SP223,SP611,SP612,SP613,SP220,SP212,SP237,SP211,SP213,SP224,SP200,SP225,SP216,SP201,SP202,SP203,SP239,SP236,SP233,SP668,SP669,SP670,SP679,SP238,SP629,SP243,SP241,SP683,SP684,SP680,SP714,SP715 |
| Other | Jimny DDIS | TCM | √ | √ | √ | √ | √ | SP561,SP562,SP563,SP564,SP565,SP566,SP567,SP568,SP569,SP570,SP571,SP572,SP573,SP529,SP528,SP530,SP531,SP532,SP321,SP322,SP323,SP324,SP618,SP713,SP326,SP316,SP325,SP617,SP319,SP320,SP318,SP315 |
| Other | Jimny DDIS | ABS/ESP | √ | √ | √ | √ | √ | SP354,SP355,SP360,SP358,SP353,SP349,SP350,SP352,SP359,SP351,SP356,SP170,SP172,SP176,SP179,SP174,SP177,SP175,SP178,SP171,SP173 |
| Other | Jimny DDIS | PAS | √ | √ | √ | √ | √ | SP255 |
| Other | Jimny DDIS | SRS | √ | √ | √ | √ | √ | |
| Other | Jimny DDIS | AC | √ | √ | √ | √ | √ | |
| Other | Jimny DDIS | AC2 | √ | √ | √ | √ | √ | |
| Other | Jimny DDIS | BCM | √ | √ | √ | √ | √ | SP380,SP375,SP378,SP381,SP379,SP377,SP376,SP196,SP192,SP191,SP195 |
| Other | Jimny DDIS | OCM | √ | √ | √ | √ | √ | |
| Other | Jimny DDIS | 4WD | √ | √ | √ | √ | √ | |

| | | | | | | | | |
|-------|------------|----------------------------------|---|---|---|---|---|--|
| Other | Jimny DDIS | IMMOBILIZER-ON-DIAG | √ | √ | √ | √ | √ | SP303 |
| Other | Jimny DDIS | IMMOBILIZER-ON-DIAG | √ | √ | √ | √ | √ | |
| Other | Jimny DDIS | EMCD | √ | √ | √ | √ | √ | |
| Other | Jimny DDIS | TPMS | √ | √ | √ | √ | √ | SP331,SP533 |
| Other | Jimny DDIS | IPC | √ | √ | √ | √ | √ | SP298,SP297,SP616,SP293,SP295,SP614,SP300,SP615,SP662,SP296,SP301 |
| Other | Jimny DDIS | ALC | √ | √ | √ | √ | √ | SP189 |
| Other | Jimny DDIS | SCC | √ | √ | √ | √ | √ | |
| Other | Jimny DDIS | ACCM | √ | √ | √ | √ | √ | SP182, SP183 |
| Other | Jimny DDIS | CNG/LPG | √ | √ | √ | √ | √ | |
| Other | Jimny DDIS | ICM | √ | √ | √ | √ | √ | SP265, SP266, SP268, SP269, SP270, SP267 |
| Other | Jimny DDIS | RBS | √ | √ | √ | √ | √ | SP310, SP719, SP718, SP309 |
| Other | Jimny DDIS | EV MOTOR | √ | √ | √ | √ | √ | |
| Other | Jimny DDIS | EV AC | √ | √ | √ | √ | √ | |
| Other | Jimny DDIS | BMU | √ | √ | √ | √ | √ | |
| Other | Jimny DDIS | TCU | √ | √ | √ | √ | √ | SP328, SP329, SP330, SP682 |
| Other | Jimny DDIS | ADM | √ | √ | √ | √ | √ | SP185, SP186, SP187, SP660, SP661 |
| Other | Jimny DDIS | SCAM | √ | √ | √ | √ | √ | SP313, SP314, SP312 |
| Other | Jimny DDIS | ISG | √ | √ | √ | √ | √ | |
| Other | Jimny DDIS | CSW | √ | √ | √ | √ | √ | |
| Other | Jimny DDIS | GW | √ | √ | √ | √ | √ | SP256 |
| Other | Jimny DDIS | HCU | √ | √ | √ | √ | √ | SP257, SP258, SP259 |
| Other | Jimny DDIS | HVBMU | √ | √ | √ | √ | √ | SP260, SP261, SP622, SP262 |
| Other | Jimny DDIS | INV | √ | √ | √ | √ | √ | |
| Other | Jimny DDIS | Acoustic Vehicle Alerting System | √ | √ | √ | √ | √ | |
| Other | Jimny DDIS | MFL | √ | √ | √ | √ | √ | SP307 |
| Other | Jimny DDIS | Head-Up Display | √ | √ | √ | √ | √ | |
| Other | Jimny DDIS | CGW | √ | √ | √ | √ | √ | |
| Other | Jimny DDIS | Sonar | √ | √ | √ | √ | √ | SP671 |
| Other | Jimny DDIS | Blind Spot Monitor | √ | √ | √ | √ | √ | SP674 |
| Other | Jimny DDIS | Auto-On Headlight | √ | √ | √ | √ | √ | SP717 |
| Other | Jimny DDIS | Dosing Control Unit | √ | √ | √ | √ | √ | |
| Other | Liana | ECM | √ | √ | √ | √ | √ | SP334, SP523, SP385, SP383, SP210, SP209, SP219, SP205, SP242, SP226, SP227, SP228, SP229, SP230, SP231, SP217, SP215, SP206, SP234, SP235, SP240, SP218, SP232, SP221, SP222, SP214, SP223, SP611, SP612, SP613, SP220, SP212, SP237, SP211, SP213, SP224, SP200, SP225, SP216, SP201, SP202, SP203, SP239, SP236, SP233, SP668, SP669, SP670, SP679, SP238, SP629, SP243, SP241, SP683, SP684, SP680, SP714, SP715 |
| Other | Liana | TCM | √ | √ | √ | √ | √ | SP561,SP562,SP563,SP564,SP565,SP566,SP567,SP568,SP569,SP570,SP571,SP572,SP573,SP529,SP528,SP530,SP531,SP532,SP321,SP322,SP323,SP324,SP618,SP713,SP326,SP316,SP325,SP617,SP319,SP320,SP318,SP315 |
| Other | Liana | ABS/ESP | √ | √ | √ | √ | √ | SP354, SP355, SP360, SP358, SP353, SP349, SP350, SP352, SP359, SP351, SP356, SP170, SP172, SP176, SP179, SP174, SP177, SP175, SP178, SP171, SP173 |
| Other | Liana | PAS | √ | √ | √ | √ | √ | SP255 |
| Other | Liana | SRS | √ | √ | √ | √ | √ | |
| Other | Liana | AC | √ | √ | √ | √ | √ | |
| Other | Liana | AC2 | √ | √ | √ | √ | √ | |

| | | | | | | | | |
|-------|-------|----------------------------------|---|---|---|---|---|---|
| Other | Liana | BCM | √ | √ | √ | √ | √ | SP380, SP375, SP378, SP381, SP379, SP377, SP376 SP196, SP192, SP191, SP195 |
| Other | Liana | OCM | √ | √ | √ | √ | √ | |
| Other | Liana | 4WD | √ | √ | √ | √ | √ | |
| Other | Liana | IMMOBILIZER-ON-DIAG | √ | √ | √ | √ | √ | SP303 |
| Other | Liana | IMMOBILIZER-ON-DIAG | √ | √ | √ | √ | √ | |
| Other | Liana | EMCD | √ | √ | √ | √ | √ | |
| Other | Liana | TPMS | √ | √ | √ | √ | √ | SP331,SP533 |
| Other | Liana | IPC | √ | √ | √ | √ | √ | SP298,SP297,SP616,SP293,SP295,SP614,SP300,SP615,SP662,SP296,SP301 |
| Other | Liana | ALC | √ | √ | √ | √ | √ | SP189 |
| Other | Liana | SCC | √ | √ | √ | √ | √ | |
| Other | Liana | ACCM | √ | √ | √ | √ | √ | SP182, SP183 |
| Other | Liana | CNG/LPG | √ | √ | √ | √ | √ | |
| Other | Liana | ICM | √ | √ | √ | √ | √ | SP265,SP266,SP268,SP269,SP270,SP267 |
| Other | Liana | RBS | √ | √ | √ | √ | √ | SP310,SP719,SP718,SP309 |
| Other | Liana | EV MOTOR | √ | √ | √ | √ | √ | |
| Other | Liana | EV AC | √ | √ | √ | √ | √ | |
| Other | Liana | BMU | √ | √ | √ | √ | √ | |
| Other | Liana | TCU | √ | √ | √ | √ | √ | SP328, SP329, SP330, SP682 |
| Other | Liana | ADM | √ | √ | √ | √ | √ | SP185,SP186,SP187,SP660,SP661 |
| Other | Liana | SCAM | √ | √ | √ | √ | √ | SP313,SP314,SP312 |
| Other | Liana | ISG | √ | √ | √ | √ | √ | |
| Other | Liana | CSW | √ | √ | √ | √ | √ | |
| Other | Liana | GW | √ | √ | √ | √ | √ | SP256 |
| Other | Liana | HCU | √ | √ | √ | √ | √ | SP257, SP258, SP259 |
| Other | Liana | HVBMU | √ | √ | √ | √ | √ | SP260,SP261,SP622,SP262 |
| Other | Liana | INV | √ | √ | √ | √ | √ | |
| Other | Liana | Acoustic Vehicle Alerting System | √ | √ | √ | √ | √ | |
| Other | Liana | MFL | √ | √ | √ | √ | √ | SP307 |
| Other | Liana | Head-Up Display | √ | √ | √ | √ | √ | |
| Other | Liana | CGW | √ | √ | √ | √ | √ | |
| Other | Liana | Sonar | √ | √ | √ | √ | √ | SP671 |
| Other | Liana | Blind Spot Monitor | √ | √ | √ | √ | √ | SP674 |
| Other | Liana | Auto-On Headlight | √ | √ | √ | √ | √ | SP717 |
| Other | Liana | Dosing Control Unit | √ | √ | √ | √ | √ | |
| Other | Ritz | ECM | √ | √ | √ | √ | √ | SP334,SP523,SP385,SP383,SP210,SP209,SP219,SP205,SP242,SP226,SP227,SP228,SP229,SP230,SP231,SP217,SP215,SP206,SP234,SP235,SP240,SP218,SP232,SP221,SP222,SP214,SP223,SP611,SP612,SP613,SP220,SP212,SP237,SP211,SP213,SP224,SP200,SP225,SP216,SP201,SP202,SP203,SP239,SP236,SP233,SP668,SP669,SP670,SP679,SP238,SP629,SP243,SP241,SP683,SP684,SP680,SP714,SP715 |
| Other | Ritz | TCM | √ | √ | √ | √ | √ | SP561, SP562, SP563, SP564, SP565, SP566, SP567, SP568, SP569, SP570, SP571, SP572, SP573, SP529, SP528, SP530, SP531, SP532, SP321, SP322, SP323, SP324, SP618, SP713, SP326, SP316, SP325, SP617, SP319, SP320, SP318, SP315 |

| | | | | | | | | |
|-------|---------|----------------------------------|---|---|---|---|---|---|
| Other | Ritz | ABS/ESP | √ | √ | √ | √ | √ | SP354,SP355,SP360,SP358,SP353,SP349,SP350,SP352,SP359,SP351,SP356,SP170,SP172,SP176,SP179,SP174,SP177,SP175,SP178,SP171,SP173 |
| Other | Ritz | PAS | √ | √ | √ | √ | √ | SP255 |
| Other | Ritz | SRS | √ | √ | √ | √ | √ | |
| Other | Ritz | AC | √ | √ | √ | √ | √ | |
| Other | Ritz | AC2 | √ | √ | √ | √ | √ | |
| Other | Ritz | BCM | √ | √ | √ | √ | √ | SP380,SP375,SP378,SP381,SP379,SP377,SP376,SP196,SP192,SP191,SP195 |
| Other | Ritz | OCM | √ | √ | √ | √ | √ | |
| Other | Ritz | 4WD | √ | √ | √ | √ | √ | |
| Other | Ritz | IMMOBILIZER-ON-DIAG | √ | √ | √ | √ | √ | SP303 |
| Other | Ritz | IMMOBILIZER-ON-DIAG | √ | √ | √ | √ | √ | |
| Other | Ritz | EMCD | √ | √ | √ | √ | √ | |
| Other | Ritz | TPMS | √ | √ | √ | √ | √ | SP331,SP533 |
| Other | Ritz | IPC | √ | √ | √ | √ | √ | SP298,SP297,SP616,SP293,SP295,SP614,SP300,SP615,SP662,SP296,SP301 |
| Other | Ritz | ALC | √ | √ | √ | √ | √ | SP189 |
| Other | Ritz | SCC | √ | √ | √ | √ | √ | |
| Other | Ritz | ACCM | √ | √ | √ | √ | √ | SP182,SP183 |
| Other | Ritz | CNG/LPG | √ | √ | √ | √ | √ | |
| Other | Ritz | ICM | √ | √ | √ | √ | √ | SP265, SP266, SP268, SP269, SP270, SP267 |
| Other | Ritz | RBS | √ | √ | √ | √ | √ | SP310, SP719, SP718, SP309 |
| Other | Ritz | EV MOTOR | √ | √ | √ | √ | √ | |
| Other | Ritz | EV AC | √ | √ | √ | √ | √ | |
| Other | Ritz | BMU | √ | √ | √ | √ | √ | |
| Other | Ritz | TCU | √ | √ | √ | √ | √ | SP328,SP329,SP330,SP682 |
| Other | Ritz | ADM | √ | √ | √ | √ | √ | SP185, SP186, SP187, SP660, SP661 |
| Other | Ritz | SCAM | √ | √ | √ | √ | √ | SP313, SP314, SP312 |
| Other | Ritz | ISG | √ | √ | √ | √ | √ | |
| Other | Ritz | CSW | √ | √ | √ | √ | √ | |
| Other | Ritz | GW | √ | √ | √ | √ | √ | SP256 |
| Other | Ritz | HCU | √ | √ | √ | √ | √ | SP257,SP258,SP259 |
| Other | Ritz | HVBMU | √ | √ | √ | √ | √ | SP260, SP261, SP622, SP262 |
| Other | Ritz | INV | √ | √ | √ | √ | √ | |
| Other | Ritz | Acoustic Vehicle Alerting System | √ | √ | √ | √ | √ | |
| Other | Ritz | MFL | √ | √ | √ | √ | √ | SP307 |
| Other | Ritz | Head-Up Display | √ | √ | √ | √ | √ | |
| Other | Ritz | CGW | √ | √ | √ | √ | √ | |
| Other | Ritz | Sonar | √ | √ | √ | √ | √ | SP671 |
| Other | Ritz | Blind Spot Monitor | √ | √ | √ | √ | √ | SP674 |
| Other | Ritz | Auto-On Headlight | √ | √ | √ | √ | √ | SP717 |
| Other | Ritz | Dosing Control Unit | √ | √ | √ | √ | √ | |
| Other | Samurai | ECM | √ | √ | √ | √ | √ | SP334,SP523,SP385,SP383,SP210,SP209,SP219,SP205,SP242,SP226,SP227,SP228,SP229,SP230,SP231,SP217,SP215,SP206,SP234,SP235,SP240,SP218,SP232,SP221,SP222,SP214,SP223,SP611,SP612,SP613,SP220,SP212,SP237,SP211,SP213,SP224,SP200,SP225,SP216,SP201,SP202,SP203,SP239,SP236,SP233,SP668,SP669,SP670,SP679,SP238,SP629,SP243,SP241,SP683,SP684,SP680,SP714,SP715 |

| | | | | | | | | |
|-------|---------|----------------------------------|---|---|---|---|---|---|
| Other | Samurai | TCM | √ | √ | √ | √ | √ | SP561,SP562,SP563,SP564,SP565,SP566,SP567,SP568,SP569,SP570,SP571,SP572,SP573,SP529,SP528,SP530,SP531,SP532,SP321,SP322,SP323,SP324,SP618,SP713,SP326,SP316,SP325,SP617,SP319,SP320,SP318,SP315 |
| Other | Samurai | ABS/ESP | √ | √ | √ | √ | √ | SP354,SP355,SP360,SP358,SP353,SP349,SP350,SP352,SP359,SP351,SP356,SP170,SP172,SP176,SP179,SP174,SP177,SP175,SP178,SP171,SP173 |
| Other | Samurai | PAS | √ | √ | √ | √ | √ | SP255 |
| Other | Samurai | SRS | √ | √ | √ | √ | √ | |
| Other | Samurai | AC | √ | √ | √ | √ | √ | |
| Other | Samurai | AC2 | √ | √ | √ | √ | √ | |
| Other | Samurai | BCM | √ | √ | √ | √ | √ | SP380,SP375,SP378,SP381,SP379,SP377,SP376,SP196,SP192,SP191,SP195 |
| Other | Samurai | OCM | √ | √ | √ | √ | √ | |
| Other | Samurai | 4WD | √ | √ | √ | √ | √ | |
| Other | Samurai | IMMOBILIZER-ON-DIAG | √ | √ | √ | √ | √ | SP303 |
| Other | Samurai | IMMOBILIZER-ON-DIAG | √ | √ | √ | √ | √ | |
| Other | Samurai | EMCD | √ | √ | √ | √ | √ | |
| Other | Samurai | TPMS | √ | √ | √ | √ | √ | SP331, SP533 |
| Other | Samurai | IPC | √ | √ | √ | √ | √ | SP298,SP297,SP616,SP293,SP295,SP614,SP300,SP615,SP662,SP296,SP301 |
| Other | Samurai | ALC | √ | √ | √ | √ | √ | SP189 |
| Other | Samurai | SCC | √ | √ | √ | √ | √ | |
| Other | Samurai | ACCM | √ | √ | √ | √ | √ | SP182,SP183 |
| Other | Samurai | CNG/LPG | √ | √ | √ | √ | √ | |
| Other | Samurai | ICM | √ | √ | √ | √ | √ | SP265, SP266, SP268, SP269, SP270, SP267 |
| Other | Samurai | RBS | √ | √ | √ | √ | √ | SP310, SP719, SP718, SP309 |
| Other | Samurai | EV MOTOR | √ | √ | √ | √ | √ | |
| Other | Samurai | EV AC | √ | √ | √ | √ | √ | |
| Other | Samurai | BMU | √ | √ | √ | √ | √ | |
| Other | Samurai | TCU | √ | √ | √ | √ | √ | SP328, SP329, SP330, SP682 |
| Other | Samurai | ADM | √ | √ | √ | √ | √ | SP185,SP186,SP187,SP660,SP661 |
| Other | Samurai | SCAM | √ | √ | √ | √ | √ | SP313, SP314, SP312 |
| Other | Samurai | ISG | √ | √ | √ | √ | √ | |
| Other | Samurai | CSW | √ | √ | √ | √ | √ | |
| Other | Samurai | GW | √ | √ | √ | √ | √ | SP256 |
| Other | Samurai | HCU | √ | √ | √ | √ | √ | SP257,SP258,SP259 |
| Other | Samurai | HVBMU | √ | √ | √ | √ | √ | SP260, SP261, SP622, SP262 |
| Other | Samurai | INV | √ | √ | √ | √ | √ | |
| Other | Samurai | Acoustic Vehicle Alerting System | √ | √ | √ | √ | √ | |
| Other | Samurai | MFL | √ | √ | √ | √ | √ | SP307 |
| Other | Samurai | Head-Up Display | √ | √ | √ | √ | √ | |
| Other | Samurai | CGW | √ | √ | √ | √ | √ | |
| Other | Samurai | Sonar | √ | √ | √ | √ | √ | SP671 |
| Other | Samurai | Blind Spot Monitor | √ | √ | √ | √ | √ | SP674 |
| Other | Samurai | Auto-On Headlight | √ | √ | √ | √ | √ | SP717 |
| Other | Samurai | Dosing Control Unit | √ | √ | √ | √ | √ | |

| | | | | | | | | |
|-------|--------|-------------------------------------|---|---|---|---|---|---|
| Other | Splash | ECM | √ | √ | √ | √ | √ | SP334,SP523,SP385,SP383,SP210,SP209,SP219,S P205,SP242,SP226,SP227,SP228,SP229,SP230,SP 231,SP217,SP215,SP206,SP234,SP235,SP240,SP2 18,SP232,SP221,SP222,SP214,SP223,SP611,SP61 2,SP613,SP220,SP212,SP237,SP211,SP213,SP224, SP200,SP225,SP216,SP201,SP202,SP203,SP239,S P236,SP233,SP668,SP669,SP670,SP679,SP238,SP 629,SP243,SP241,SP683,SP684,SP680,SP714,SP7 15 |
| Other | Splash | TCM | √ | √ | √ | √ | √ | SP561,SP562,SP563,SP564,SP565,SP566,SP567,S P568,SP569,SP570,SP571,SP572,SP573,SP529,SP 528,SP530,SP531,SP532,SP321,SP322,SP323,SP3 24,SP618,SP713,SP326,SP316,SP325,SP617,SP31 9,SP320,SP318,SP315 |
| Other | Splash | ABS/ESP | √ | √ | √ | √ | √ | SP354,SP355,SP360,SP358,SP353,SP349,SP350,S P352,SP359,SP351,SP356,SP170,SP172,SP176,SP 179,SP174,SP177,SP175,SP178,SP171,SP173 |
| Other | Splash | PAS | √ | √ | √ | √ | √ | SP255 |
| Other | Splash | SRS | √ | √ | √ | √ | √ | |
| Other | Splash | AC | √ | √ | √ | √ | √ | |
| Other | Splash | AC2 | √ | √ | √ | √ | √ | |
| Other | Splash | BCM | √ | √ | √ | √ | √ | SP380,SP375,SP378,SP381,SP379,SP377,SP376,S P196,SP192,SP191,SP195 |
| Other | Splash | OCM | √ | √ | √ | √ | √ | |
| Other | Splash | 4WD | √ | √ | √ | √ | √ | |
| Other | Splash | IMMOBILIZER-ON- DIAG | √ | √ | √ | √ | √ | SP303 |
| Other | Splash | IMMOBILIZER-ON- DIAG | √ | √ | √ | √ | √ | |
| Other | Splash | EMCD | √ | √ | √ | √ | √ | |
| Other | Splash | TPMS | √ | √ | √ | √ | √ | SP331, SP533 |
| Other | Splash | IPC | √ | √ | √ | √ | √ | SP298, SP297, SP616, SP293, SP295, SP614, SP300 SP615, SP662, SP296, SP301 |
| Other | Splash | ALC | √ | √ | √ | √ | √ | SP189 |
| Other | Splash | SCC | √ | √ | √ | √ | √ | |
| Other | Splash | ACCM | √ | √ | √ | √ | √ | SP182, SP183 |
| Other | Splash | CNG/LPG | √ | √ | √ | √ | √ | |
| Other | Splash | ICM | √ | √ | √ | √ | √ | SP265, SP266, SP268, SP269, SP270, SP267 |
| Other | Splash | RBS | √ | √ | √ | √ | √ | SP310, SP719, SP718, SP309 |
| Other | Splash | EV MOTOR | √ | √ | √ | √ | √ | |
| Other | Splash | EV AC | √ | √ | √ | √ | √ | |
| Other | Splash | BMU | √ | √ | √ | √ | √ | |
| Other | Splash | TCU | √ | √ | √ | √ | √ | SP328,SP329,SP330,SP682 |
| Other | Splash | ADM | √ | √ | √ | √ | √ | SP185, SP186, SP187, SP660, SP661 |
| Other | Splash | SCAM | √ | √ | √ | √ | √ | SP313, SP314, SP312 |
| Other | Splash | ISG | √ | √ | √ | √ | √ | |
| Other | Splash | CSW | √ | √ | √ | √ | √ | |
| Other | Splash | GW | √ | √ | √ | √ | √ | SP256 |
| Other | Splash | HCU | √ | √ | √ | √ | √ | SP257,SP258,SP259 |
| Other | Splash | HVBMU | √ | √ | √ | √ | √ | SP260,SP261,SP622,SP262 |
| Other | Splash | INV | √ | √ | √ | √ | √ | |
| Other | Splash | Acoustic Vehicle Alerting System | √ | √ | √ | √ | √ | |
| Other | Splash | MFL | √ | √ | √ | √ | √ | SP307 |
| Other | Splash | Head-Up Display | √ | √ | √ | √ | √ | |
| Other | Splash | CGW | √ | √ | √ | √ | √ | |

| | | | | | | | | |
|-------|--------|---------------------|---|---|---|---|---|---|
| Other | Splash | Sonar | √ | √ | √ | √ | √ | SP671 |
| Other | Splash | Blind Spot Monitor | √ | √ | √ | √ | √ | SP674 |
| Other | Splash | Auto-On Headlight | √ | √ | √ | √ | √ | SP717 |
| Other | Splash | Dosing Control Unit | √ | √ | √ | √ | √ | |
| Other | Swift | ECM | √ | √ | √ | √ | √ | SP334,SP523,SP385,SP383,SP210,SP209,SP219,SP205,SP242,SP226,SP227,SP228,SP229,SP230,SP231,SP217,SP215,SP206,SP234,SP235,SP240,SP218,SP232,SP221,SP222,SP214,SP223,SP611,SP612,SP613,SP220,SP212,SP237,SP211,SP213,SP224,SP200,SP225,SP216,SP201,SP202,SP203,SP239,SP236,SP233,SP668,SP669,SP670,SP679,SP238,SP629,SP243,SP241,SP683,SP684,SP680,SP714,SP715 |
| Other | Swift | TCM | √ | √ | √ | √ | √ | SP561, SP562, SP563, SP564, SP565, SP566, SP567, SP568, SP569, SP570, SP571, SP572, SP573, SP529, SP528, SP530, SP531, SP532, SP321, SP322, SP323, SP324, SP618, SP713, SP326, SP316, SP325, SP617, SP319, SP320, SP318, SP315 |
| Other | Swift | ABS/ESP | √ | √ | √ | √ | √ | SP354, SP355, SP360, SP358, SP353, SP349, SP350, SP352, SP359, SP351, SP356, SP170, SP172, SP176, SP179, SP174, SP177, SP175, SP178, SP171, SP173 |
| Other | Swift | PAS | √ | √ | √ | √ | √ | SP255 |
| Other | Swift | SRS | √ | √ | √ | √ | √ | |
| Other | Swift | AC | √ | √ | √ | √ | √ | |
| Other | Swift | AC2 | √ | √ | √ | √ | √ | |
| Other | Swift | BCM | √ | √ | √ | √ | √ | SP380,SP375,SP378,SP381,SP379,SP377,SP376,SP196,SP192,SP191,SP195 |
| Other | Swift | OCM | √ | √ | √ | √ | √ | |
| Other | Swift | 4WD | √ | √ | √ | √ | √ | |
| Other | Swift | IMMOBILIZER-ON-DIAG | √ | √ | √ | √ | √ | SP303 |
| Other | Swift | IMMOBILIZER-ON-DIAG | √ | √ | √ | √ | √ | |
| Other | Swift | EMCD | √ | √ | √ | √ | √ | |
| Other | Swift | TPMS | √ | √ | √ | √ | √ | SP331, SP533 |
| Other | Swift | IPC | √ | √ | √ | √ | √ | SP298, SP297, SP616, SP293, SP295, SP614, SP300, SP615, SP662, SP296, SP301 |
| Other | Swift | ALC | √ | √ | √ | √ | √ | SP189 |
| Other | Swift | SCC | √ | √ | √ | √ | √ | |
| Other | Swift | ACCM | √ | √ | √ | √ | √ | SP182, SP183 |
| Other | Swift | CNG/LPG | √ | √ | √ | √ | √ | |
| Other | Swift | ICM | √ | √ | √ | √ | √ | SP265, SP266, SP268, SP269, SP270, SP267 |
| Other | Swift | RBS | √ | √ | √ | √ | √ | SP310, SP719, SP718, SP309 |
| Other | Swift | EV MOTOR | √ | √ | √ | √ | √ | |
| Other | Swift | EV AC | √ | √ | √ | √ | √ | |
| Other | Swift | BMU | √ | √ | √ | √ | √ | |
| Other | Swift | TCU | √ | √ | √ | √ | √ | SP328,SP329,SP330,SP682 |
| Other | Swift | ADM | √ | √ | √ | √ | √ | SP185, SP186, SP187, SP660, SP661 |
| Other | Swift | SCAM | √ | √ | √ | √ | √ | SP313,SP314,SP312 |
| Other | Swift | ISG | √ | √ | √ | √ | √ | |
| Other | Swift | CSW | √ | √ | √ | √ | √ | |
| Other | Swift | GW | √ | √ | √ | √ | √ | SP256 |
| Other | Swift | HCU | √ | √ | √ | √ | √ | SP257,SP258,SP259 |
| Other | Swift | HVBMU | √ | √ | √ | √ | √ | SP260,SP261,SP622,SP262 |
| Other | Swift | INV | √ | √ | √ | √ | √ | |

| | | | | | | | | |
|-------|----------------|----------------------------------|---|---|---|---|---|---|
| Other | Swift | Acoustic Vehicle Alerting System | √ | √ | √ | √ | √ | |
| Other | Swift | MFL | √ | √ | √ | √ | √ | SP307 |
| Other | Swift | Head-Up Display | √ | √ | √ | √ | √ | |
| Other | Swift | CGW | √ | √ | √ | √ | √ | |
| Other | Swift | Sonar | √ | √ | √ | √ | √ | SP671 |
| Other | Swift | Blind Spot Monitor | √ | √ | √ | √ | √ | SP674 |
| Other | Swift | Auto-On Headlight | √ | √ | √ | √ | √ | SP717 |
| Other | Swift | Dosing Control Unit | √ | √ | √ | √ | √ | |
| Other | Swift(AZI413D) | ECM | √ | √ | √ | √ | √ | SP334,SP523,SP385,SP383,SP210,SP209,SP219,SP205,SP242,SP226,SP227,SP228,SP229,SP230,SP231,SP217,SP215,SP206,SP234,SP235,SP240,SP218,SP232,SP221,SP222,SP214,SP223,SP611,SP612,SP613,SP220,SP212,SP237,SP211,SP213,SP224,SP200,SP225,SP216,SP201,SP202,SP203,SP239,SP236,SP233,SP668,SP669,SP670,SP679,SP238,SP629,SP243,SP241,SP683,SP684,SP680,SP714,SP715 |
| Other | Swift(AZI413D) | TCM | √ | √ | √ | √ | √ | SP321,SP322,SP323,SP324,SP618,SP713,SP326,SP316,SP325,SP617,SP319,SP320,SP318,SP315 |
| Other | Swift(AZI413D) | ABS/ESP | √ | √ | √ | √ | √ | SP170,SP172,SP176,SP179,SP174,SP177,SP175,SP178,SP171,SP173 |
| Other | Swift(AZI413D) | PAS | √ | √ | √ | √ | √ | SP255 |
| Other | Swift(AZI413D) | SRS | √ | √ | √ | √ | √ | |
| Other | Swift(AZI413D) | AC | √ | √ | √ | √ | √ | |
| Other | Swift(AZI413D) | BCM | √ | √ | √ | √ | √ | SP196,SP192,SP191,SP195 |
| Other | Swift(AZI413D) | IMMOBILIZER-ON-DIAG | √ | √ | √ | √ | √ | SP303 |
| Other | Swift(AZI413D) | IPC | √ | √ | √ | √ | √ | SP298,SP297,SP616,SP293,SP295,SP614,SP300,SP615,SP662,SP296,SP301 |
| Other | SX4 | ECM | √ | √ | √ | √ | √ | SP334,SP523,SP385,SP383,SP210,SP209,SP219,SP205,SP242,SP226,SP227,SP228,SP229,SP230,SP231,SP217,SP215,SP206,SP234,SP235,SP240,SP218,SP232,SP221,SP222,SP214,SP223,SP611,SP612,SP613,SP220,SP212,SP237,SP211,SP213,SP224,SP200,SP225,SP216,SP201,SP202,SP203,SP239,SP236,SP233,SP668,SP669,SP670,SP679,SP238,SP629,SP243,SP241,SP683,SP684,SP680,SP714,SP715 |
| Other | SX4 | TCM | √ | √ | √ | √ | √ | SP561, SP562, SP563, SP564, SP565, SP566, SP567, SP568, SP569, SP570, SP571, SP572, SP573, SP529, SP528, SP530, SP531, SP532, SP321, SP322, SP323, SP324, SP618, SP713, SP326, SP316, SP325, SP617, SP319, SP320, SP318, SP315 |
| Other | SX4 | ABS/ESP | √ | √ | √ | √ | √ | SP354,SP355,SP360,SP358,SP353,SP349,SP350,SP352,SP359,SP351,SP356,SP170,SP172,SP176,SP179,SP174,SP177,SP175,SP178,SP171,SP173 |
| Other | SX4 | PAS | √ | √ | √ | √ | √ | SP255 |
| Other | SX4 | SRS | √ | √ | √ | √ | √ | |
| Other | SX4 | AC | √ | √ | √ | √ | √ | |
| Other | SX4 | BCM | √ | √ | √ | √ | √ | SP380, SP375, SP378, SP381, SP379, SP377, SP376, SP196, SP192, SP191, SP195 |
| Other | SX4 | IMMOBILIZER-ON-DIAG | √ | √ | √ | √ | √ | |
| Other | SX4 | AC2 | √ | √ | √ | √ | √ | |
| Other | SX4 | OCM | √ | √ | √ | √ | √ | |

| | | | | | | | | |
|-------|--------------|----------------------------------|---|---|---|---|---|---|
| Other | SX4 | 4WD | √ | √ | √ | √ | √ | |
| Other | SX4 | IMMOBILIZER-ON-DIAG | √ | √ | √ | √ | √ | SP303 |
| Other | SX4 | EMCD | √ | √ | √ | √ | √ | |
| Other | SX4 | TPMS | √ | √ | √ | √ | √ | SP331,SP533 |
| Other | SX4 | IPC | √ | √ | √ | √ | √ | SP298,SP297,SP616,SP293,SP295,SP614,SP300,SP615,SP662,SP296,SP301 |
| Other | SX4 | ALC | √ | √ | √ | √ | √ | SP189 |
| Other | SX4 | SCC | √ | √ | √ | √ | √ | |
| Other | SX4 | ACCM | √ | √ | √ | √ | √ | SP182,SP183 |
| Other | SX4 | CNG/LPG | √ | √ | √ | √ | √ | |
| Other | SX4 | ICM | √ | √ | √ | √ | √ | SP265, SP266, SP268, SP269, SP270, SP267 |
| Other | SX4 | RBS | √ | √ | √ | √ | √ | SP310,SP719,SP718,SP309 |
| Other | SX4 | EV MOTOR | √ | √ | √ | √ | √ | |
| Other | SX4 | EV AC | √ | √ | √ | √ | √ | |
| Other | SX4 | BMU | √ | √ | √ | √ | √ | |
| Other | SX4 | TCU | √ | √ | √ | √ | √ | SP328, SP329, SP330, SP682 |
| Other | SX4 | ADM | √ | √ | √ | √ | √ | SP185,SP186,SP187,SP660,SP661 |
| Other | SX4 | SCAM | √ | √ | √ | √ | √ | SP313, SP314, SP312 |
| Other | SX4 | ISG | √ | √ | √ | √ | √ | |
| Other | SX4 | CSW | √ | √ | √ | √ | √ | |
| Other | SX4 | GW | √ | √ | √ | √ | √ | SP256 |
| Other | SX4 | HCU | √ | √ | √ | √ | √ | SP257,SP258,SP259 |
| Other | SX4 | HVBMU | √ | √ | √ | √ | √ | SP260, SP261, SP622, SP262 |
| Other | SX4 | INV | √ | √ | √ | √ | √ | |
| Other | SX4 | Acoustic Vehicle Alerting System | √ | √ | √ | √ | √ | |
| Other | SX4 | MFL | √ | √ | √ | √ | √ | SP307 |
| Other | SX4 | Head-Up Display | √ | √ | √ | √ | √ | |
| Other | SX4 | CGW | √ | √ | √ | √ | √ | |
| Other | SX4 | Sonar | √ | √ | √ | √ | √ | SP671 |
| Other | SX4 | Blind Spot Monitor | √ | √ | √ | √ | √ | SP674 |
| Other | SX4 | Auto-On Headlight | √ | √ | √ | √ | √ | SP717 |
| Other | SX4 | Dosing Control Unit | √ | √ | √ | √ | √ | |
| Other | SX4(AKN413D) | ECM | √ | √ | √ | √ | √ | SP334,SP523,SP385,SP383,SP210,SP209,SP219,SP205,SP242,SP226,SP227,SP228,SP229,SP230,SP231,SP217,SP215,SP206,SP234,SP235,SP240,SP218,SP232,SP221,SP222,SP214,SP223,SP611,SP612,SP613,SP220,SP212,SP237,SP211,SP213,SP224,SP200,SP225,SP216,SP201,SP202,SP203,SP239,SP236,SP233,SP668,SP669,SP670,SP679,SP238,SP629,SP243,SP241,SP683,SP684,SP680,SP714,SP715 |
| Other | SX4(AKN413D) | ABS/ESP | √ | √ | √ | √ | √ | SP170,SP172,SP176,SP179,SP174,SP177,SP175,SP178,SP171,SP173 |
| Other | SX4(AKN413D) | PAS | √ | √ | √ | √ | √ | SP255 |
| Other | SX4(AKN413D) | SRS | √ | √ | √ | √ | √ | |
| Other | SX4(AKN413D) | AC | √ | √ | √ | √ | √ | |
| Other | SX4(AKN413D) | BCM | √ | √ | √ | √ | √ | SP196,SP192,SP191,SP195 |
| Other | SX4(AKN413D) | IMMOBILIZER-ON-DIAG | √ | √ | √ | √ | √ | SP303 |
| Other | SX4(AKN413D) | IPC | √ | √ | √ | √ | √ | SP298,SP297,SP616,SP293,SP295,SP614,SP300,SP615,SP662,SP296,SP301 |
| Other | SX4(AKN413D) | ALC | √ | √ | √ | √ | √ | SP189 |
| Other | SX4(AKN413D) | GW | √ | √ | √ | √ | √ | SP256 |

| | | | | | | | | |
|-------|--------|----------------------------------|---|---|---|---|---|---|
| Other | Vitara | ECM | √ | √ | √ | √ | √ | SP334,SP523,SP385,SP383,SP210,SP209,SP219,SP205,SP242,SP226,SP227,SP228,SP229,SP230,SP231,SP217,SP215,SP206,SP234,SP235,SP240,SP218,SP232,SP221,SP222,SP214,SP223,SP611,SP612,SP613,SP220,SP212,SP237,SP211,SP213,SP224,SP200,SP225,SP216,SP201,SP202,SP203,SP239,SP236,SP233,SP668,SP669,SP670,SP679,SP238,SP629,SP243,SP241,SP683,SP684,SP680,SP714,SP715 |
| Other | Vitara | TCM | √ | √ | √ | √ | √ | SP561, SP562, SP563, SP564, SP565, SP566, SP567, SP568, SP569, SP570, SP571, SP572, SP573, SP529, SP528, SP530, SP531, SP532, SP321, SP322, SP323, SP324, SP618, SP713, SP326, SP316, SP325, SP617, SP319, SP320, SP318, SP315 |
| Other | Vitara | ABS/ESP | √ | √ | √ | √ | √ | SP354, SP355, SP360, SP358, SP353, SP349, SP350, SP352, SP359, SP351, SP356, SP170, SP172, SP176, SP179, SP174, SP177, SP175, SP178, SP171, SP173 |
| Other | Vitara | PAS | √ | √ | √ | √ | √ | SP255 |
| Other | Vitara | SRS | √ | √ | √ | √ | √ | |
| Other | Vitara | AC | √ | √ | √ | √ | √ | |
| Other | Vitara | AC2 | √ | √ | √ | √ | √ | |
| Other | Vitara | BCM | √ | √ | √ | √ | √ | SP380, SP375, SP378, SP381, SP379, SP377, SP376, SP196, SP192, SP191, SP195 |
| Other | Vitara | OCM | √ | √ | √ | √ | √ | |
| Other | Vitara | 4WD | √ | √ | √ | √ | √ | |
| Other | Vitara | IMMOBILIZER-ON-DIAG | √ | √ | √ | √ | √ | SP303 |
| Other | Vitara | IMMOBILIZER-ON-DIAG | √ | √ | √ | √ | √ | |
| Other | Vitara | EMCD | √ | √ | √ | √ | √ | |
| Other | Vitara | TPMS | √ | √ | √ | √ | √ | SP331,SP533 |
| Other | Vitara | IPC | √ | √ | √ | √ | √ | SP298, SP297, SP616, SP293, SP295, SP614, SP300, SP615, SP662, SP296, SP301 |
| Other | Vitara | ALC | √ | √ | √ | √ | √ | SP189 |
| Other | Vitara | SCC | √ | √ | √ | √ | √ | |
| Other | Vitara | CNG/LPG | √ | √ | √ | √ | √ | |
| Other | Vitara | ICM | √ | √ | √ | √ | √ | SP265, SP266, SP268, SP269, SP270, SP267 |
| Other | Vitara | RBS | √ | √ | √ | √ | √ | SP310, SP719, SP718, SP309 |
| Other | Vitara | ACCM | √ | √ | √ | √ | √ | SP182,SP183 |
| Other | Vitara | EV MOTOR | √ | √ | √ | √ | √ | |
| Other | Vitara | EV AC | √ | √ | √ | √ | √ | |
| Other | Vitara | BMU | √ | √ | √ | √ | √ | |
| Other | Vitara | TCU | √ | √ | √ | √ | √ | SP328, SP329, SP330, SP682 |
| Other | Vitara | ADM | √ | √ | √ | √ | √ | SP185, SP186, SP187, SP660, SP661 |
| Other | Vitara | SCAM | √ | √ | √ | √ | √ | SP313, SP314, SP312 |
| Other | Vitara | ISG | √ | √ | √ | √ | √ | |
| Other | Vitara | CSW | √ | √ | √ | √ | √ | |
| Other | Vitara | GW | √ | √ | √ | √ | √ | SP256 |
| Other | Vitara | HCU | √ | √ | √ | √ | √ | SP257,SP258,SP259 |
| Other | Vitara | HVBMU | √ | √ | √ | √ | √ | SP260, SP261, SP622, SP262 |
| Other | Vitara | INV | √ | √ | √ | √ | √ | |
| Other | Vitara | Acoustic Vehicle Alerting System | √ | √ | √ | √ | √ | |
| Other | Vitara | MFL | √ | √ | √ | √ | √ | SP307 |
| Other | Vitara | Head-Up Display | √ | √ | √ | √ | √ | |
| Other | Vitara | CGW | √ | √ | √ | √ | √ | |

| | | | | | | | | |
|-------|---------------|---------------------|---|---|---|---|---|--|
| Other | Vitara | Sonar | √ | √ | √ | √ | √ | SP671 |
| Other | Vitara | Blind Spot Monitor | √ | √ | √ | √ | √ | SP674 |
| Other | Vitara | Auto-On Headlight | √ | √ | √ | √ | √ | SP717 |
| Other | Vitara | Dosing Control Unit | √ | √ | √ | √ | √ | |
| Other | VITARA BREZZA | ECM | √ | √ | √ | √ | √ | SP334,SP523,SP385,SP383,SP210,SP209,SP219,SP205,SP242,SP226,SP227,SP228,SP229,SP230,SP231,SP217,SP215,SP206,SP234,SP235,SP240,SP218,SP232,SP221,SP222,SP214,SP223,SP611,SP612,SP613,SP220,SP212,SP237,SP211,SP213,SP224,SP200,SP225,SP216,SP201,SP202,SP203,SP239,SP236,SP233,SP668,SP669,SP670,SP679,SP238,SP629,SP243,SP241,SP683,SP684,SP680,SP714,SP715 |
| Other | VITARA BREZZA | ABS/ESP | √ | √ | √ | √ | √ | SP170, SP172, SP176, SP179, SP174, SP177, SP175, SP178, SP171, SP173 |
| Other | VITARA BREZZA | PAS | √ | √ | √ | √ | √ | SP255 |
| Other | VITARA BREZZA | SRS | √ | √ | √ | √ | √ | |
| Other | VITARA BREZZA | AC | √ | √ | √ | √ | √ | |
| Other | VITARA BREZZA | BCM | √ | √ | √ | √ | √ | SP196, SP192, SP191, SP195 |
| Other | VITARA BREZZA | IMMOBILIZER-ON-DIAG | √ | √ | √ | √ | √ | SP303 |
| Other | VITARA BREZZA | IPC | √ | √ | √ | √ | √ | SP298, SP297, SP616, SP293, SP295, SP614, SP300, SP615, SP662, SP296, SP301 |
| Other | XL-7 | ECM | √ | √ | √ | √ | √ | SP334, SP523, SP385, SP383, SP210, SP209, SP219, SP205, SP242, SP226, SP227, SP228, SP229, SP230, SP231, SP217, SP215, SP206, SP234, SP235, SP240, SP218, SP232, SP221, SP222, SP214, SP223, SP611, SP612, SP613, SP220, SP212, SP237, SP211, SP213, SP224, SP200, SP225, SP216, SP201, SP202, SP203, SP239, SP236, SP233, SP668, SP669, SP670, SP679, SP238, SP629, SP243, SP241, SP683, SP684, SP680, SP714, SP715 |
| Other | XL-7 | TCM | √ | √ | √ | √ | √ | SP561, SP562, SP563, SP564, SP565, SP566, SP567, SP568, SP569, SP570, SP571, SP572, SP573, SP579, SP528, SP530, SP531, SP532, SP321, SP322, SP323, SP324, SP618, SP713, SP326, SP316, SP325, SP617, SP319, SP320, SP318, SP315 |
| Other | XL-7 | ABS/ESP | √ | √ | √ | √ | √ | SP354, SP355, SP360, SP358, SP353, SP349, SP350, SP352, SP359, SP351, SP356, SP170, SP172, SP176, SP179, SP174, SP177, SP175, SP178, SP171, SP173 |
| Other | XL-7 | PAS | √ | √ | √ | √ | √ | SP255 |
| Other | XL-7 | SRS | √ | √ | √ | √ | √ | |
| Other | XL-7 | AC | √ | √ | √ | √ | √ | |
| Other | XL-7 | AC2 | √ | √ | √ | √ | √ | |
| Other | XL-7 | BCM | √ | √ | √ | √ | √ | SP380, SP375, SP378, SP381, SP379, SP377, SP376, SP196, SP192, SP191, SP195 |
| Other | XL-7 | OCM | √ | √ | √ | √ | √ | |
| Other | XL-7 | 4WD | √ | √ | √ | √ | √ | |
| Other | XL-7 | IMMOBILIZER-ON-DIAG | √ | √ | √ | √ | √ | SP303 |
| Other | XL-7 | IMMOBILIZER-ON-DIAG | √ | √ | √ | √ | √ | |
| Other | XL-7 | EMCD | √ | √ | √ | √ | √ | |
| Other | XL-7 | TPMS | √ | √ | √ | √ | √ | SP331, SP533 |
| Other | XL-7 | IPC | √ | √ | √ | √ | √ | SP298, SP297, SP616, SP293, SP295, SP614, SP300, SP615, SP662, SP296, SP301 |
| Other | XL-7 | ALC | √ | √ | √ | √ | √ | SP189 |

| | | | | | | | | |
|-------|--------|----------------------------------|---|---|---|---|---|--|
| Other | XL-7 | SCC | √ | √ | √ | √ | √ | |
| Other | XL-7 | ACCM | √ | √ | √ | √ | √ | SP182, SP183 |
| Other | XL-7 | CNG/LPG | √ | √ | √ | √ | √ | |
| Other | XL-7 | ICM | √ | √ | √ | √ | √ | SP265, SP266, SP268, SP269, SP270, SP267 |
| Other | XL-7 | RBS | √ | √ | √ | √ | √ | SP310, SP719, SP718, SP309 |
| Other | XL-7 | EV MOTOR | √ | √ | √ | √ | √ | |
| Other | XL-7 | EV AC | √ | √ | √ | √ | √ | |
| Other | XL-7 | BMU | √ | √ | √ | √ | √ | |
| Other | XL-7 | TCU | √ | √ | √ | √ | √ | SP328, SP329, SP330, SP682 |
| Other | XL-7 | ADM | √ | √ | √ | √ | √ | SP185, SP186, SP187, SP660, SP661 |
| Other | XL-7 | SCAM | √ | √ | √ | √ | √ | SP313, SP314, SP312 |
| Other | XL-7 | ISG | √ | √ | √ | √ | √ | |
| Other | XL-7 | CSW | √ | √ | √ | √ | √ | |
| Other | XL-7 | GW | √ | √ | √ | √ | √ | SP256 |
| Other | XL-7 | HCU | √ | √ | √ | √ | √ | SP257, SP258, SP259 |
| Other | XL-7 | HVBMU | √ | √ | √ | √ | √ | SP260, SP261, SP622, SP262 |
| Other | XL-7 | INV | √ | √ | √ | √ | √ | |
| Other | XL-7 | Acoustic Vehicle Alerting System | √ | √ | √ | √ | √ | |
| Other | XL-7 | MFL | √ | √ | √ | √ | √ | SP307 |
| Other | XL-7 | Head-Up Display | √ | √ | √ | √ | √ | |
| Other | XL-7 | CGW | √ | √ | √ | √ | √ | |
| Other | XL-7 | Sonar | √ | √ | √ | √ | √ | SP671 |
| Other | XL-7 | Blind Spot Monitor | √ | √ | √ | √ | √ | SP674 |
| Other | XL-7 | Auto-On Headlight | √ | √ | √ | √ | √ | SP717 |
| Other | XL-7 | Dosing Control Unit | √ | √ | √ | √ | √ | |
| Other | others | ECM | √ | √ | √ | √ | √ | SP334, SP523, SP385, SP383, SP210, SP209, SP219, SP205, SP242, SP226, SP227, SP228, SP229, SP230, SP231, SP217, SP215, SP206, SP234, SP235, SP240, SP218, SP232, SP221, SP222, SP214, SP223, SP611, SP612, SP613, SP220, SP212, SP237, SP211, SP213, SP224, SP200, SP225, SP216, SP201, SP202, SP203, SP239, SP236, SP233, SP668, SP669, SP670, SP679, SP238, SP629, SP243, SP241, SP683, SP684, SP680, SP714, SP715 |
| Other | others | TCM | √ | √ | √ | √ | √ | SP561, SP562, SP563, SP564, SP565, SP566, SP567, SP568, SP569, SP570, SP571, SP572, SP573, SP529, SP528, SP530, SP531, SP532, SP321, SP322, SP323, SP324, SP618, SP713, SP326, SP316, SP325, SP617, SP319, SP320, SP318, SP315 |
| Other | others | ABS/ESP | √ | √ | √ | √ | √ | SP354, SP355, SP360, SP358, SP353, SP349, SP350, SP352, SP359, SP351, SP356, SP170, SP172, SP176, SP179, SP174, SP177, SP175, SP178, SP171, SP173 |
| Other | others | PAS | √ | √ | √ | √ | √ | SP255 |
| Other | others | SRS | √ | √ | √ | √ | √ | |
| Other | others | AC | √ | √ | √ | √ | √ | |
| Other | others | AC2 | √ | √ | √ | √ | √ | |
| Other | others | BCM | √ | √ | √ | √ | √ | SP380, SP375, SP378, SP381, SP379, SP377, SP376, SP196, SP192, SP191, SP195 |
| Other | others | OCM | √ | √ | √ | √ | √ | |
| Other | others | 4WD | √ | √ | √ | √ | √ | |
| Other | others | IMMOBILIZER-ON-DIAG | √ | √ | √ | √ | √ | SP303 |
| Other | others | IMMOBILIZER-ON-DIAG | √ | √ | √ | √ | √ | |

| | | | | | | | | |
|-------|-----------|----------------------------------|---|---|---|---|---|--|
| Other | others | EMCD | √ | √ | √ | √ | √ | |
| Other | others | EV MOTOR | √ | √ | √ | √ | √ | |
| Other | others | EV AC | √ | √ | √ | √ | √ | |
| Other | others | TPMS | √ | √ | √ | √ | √ | SP331, SP533 |
| Other | others | IPC | √ | √ | √ | √ | √ | SP298, SP297, SP616, SP293, SP295, SP614, SP300, SP615, SP662, SP296, SP301 |
| Other | others | ALC | √ | √ | √ | √ | √ | SP189 |
| Other | others | SCC | √ | √ | √ | √ | √ | |
| Other | others | ACCM | √ | √ | √ | √ | √ | SP182, SP183 |
| Other | others | CNG/LPG | √ | √ | √ | √ | √ | |
| Other | others | ICM | √ | √ | √ | √ | √ | SP265, SP266, SP268, SP269, SP270, SP267 |
| Other | others | RBS | √ | √ | √ | √ | √ | SP310, SP719, SP718, SP309 |
| Other | others | BMU | √ | √ | √ | √ | √ | |
| Other | others | TCU | √ | √ | √ | √ | √ | SP328, SP329, SP330, SP682 |
| Other | others | ADM | √ | √ | √ | √ | √ | SP185, SP186, SP187, SP660, SP661 |
| Other | others | SCAM | √ | √ | √ | √ | √ | SP313, SP314, SP312 |
| Other | others | ISG | √ | √ | √ | √ | √ | |
| Other | others | CSW | √ | √ | √ | √ | √ | |
| Other | others | GW | √ | √ | √ | √ | √ | SP256 |
| Other | others | HCU | √ | √ | √ | √ | √ | SP257, SP258, SP259 |
| Other | others | HVBMU | √ | √ | √ | √ | √ | SP260, SP261, SP622, SP262 |
| Other | others | INV | √ | √ | √ | √ | √ | |
| Other | others | Acoustic Vehicle Alerting System | √ | √ | √ | √ | √ | |
| Other | others | MFL | √ | √ | √ | √ | √ | SP307 |
| Other | others | Head-Up Display | √ | √ | √ | √ | √ | |
| Other | others | CGW | √ | √ | √ | √ | √ | |
| Other | others | Sonar | √ | √ | √ | √ | √ | SP671 |
| Other | others | Blind Spot Monitor | √ | √ | √ | √ | √ | SP674 |
| Other | others | Auto-On Headlight | √ | √ | √ | √ | √ | SP717 |
| Other | others | Dosing Control Unit | √ | √ | √ | √ | √ | |
| JAPAN | Landy C27 | ECM | √ | √ | √ | √ | √ | SP334, SP523, SP385, SP383, SP210, SP209, SP219, SP205, SP242, SP226, SP227, SP228, SP229, SP230, SP231, SP217, SP215, SP206, SP234, SP235, SP240, SP218, SP232, SP221, SP222, SP214, SP223, SP611, SP612, SP613, SP220, SP212, SP237, SP211, SP213, SP224, SP200, SP225, SP216, SP201, SP202, SP203, SP239, SP236, SP233, SP668, SP669, SP670, SP679, SP238, SP629, SP243, SP241, SP683, SP684, SP680, SP714, SP715 |
| JAPAN | Landy C27 | TCM | √ | √ | √ | √ | √ | |
| JAPAN | Landy C27 | ABS/ESP | √ | √ | √ | √ | √ | |
| JAPAN | Landy C27 | PAS | √ | √ | √ | √ | √ | |
| JAPAN | Landy C27 | SRS | √ | √ | √ | √ | √ | |
| JAPAN | Landy C27 | AC | √ | √ | √ | √ | √ | |
| JAPAN | Landy C27 | BCM | √ | √ | √ | √ | √ | |
| JAPAN | Landy C27 | IPDM E/R | √ | √ | √ | √ | √ | |
| JAPAN | Landy C27 | IPC | √ | √ | √ | √ | √ | |
| JAPAN | Landy C27 | ASD-L | √ | √ | √ | √ | √ | |
| JAPAN | Landy C27 | ASD-R | √ | √ | √ | √ | √ | |
| JAPAN | Landy C27 | AVM | √ | √ | √ | √ | √ | |
| JAPAN | Landy C27 | ADAS2 | √ | √ | √ | √ | √ | |
| JAPAN | Landy C27 | Fr-Camera | √ | √ | √ | √ | √ | |
| JAPAN | Landy C27 | Sonar | √ | √ | √ | √ | √ | |
| JAPAN | Landy C27 | Gateway2 | √ | √ | √ | √ | √ | |

| | | | | | | | | |
|-------|-----------|-----------|---|---|---|---|---|--|
| JAPAN | Landy C26 | ECM | √ | √ | √ | √ | √ | SP334, SP523, SP385, SP383, SP210, SP209, SP219, SP205, SP242, SP226, SP227, SP228, SP229, SP230, SP231, SP217, SP215, SP206, SP234, SP235, SP240, SP218, SP232, SP221, SP222, SP214, SP223, SP611, SP612, SP613, SP220, SP212, SP237, SP211, SP213, SP224, SP200, SP225, SP216, SP201, SP202, SP203, SP239, SP236, SP233, SP668, SP669, SP670, SP679, SP238, SP629, SP243, SP241, SP683, SP684, SP680, SP714, SP715 |
| JAPAN | Landy C26 | TCM | √ | √ | √ | √ | √ | |
| JAPAN | Landy C26 | ABS/ESP | √ | √ | √ | √ | √ | |
| JAPAN | Landy C26 | PAS | √ | √ | √ | √ | √ | |
| JAPAN | Landy C26 | SRS | √ | √ | √ | √ | √ | |
| JAPAN | Landy C26 | AC | √ | √ | √ | √ | √ | |
| JAPAN | Landy C26 | BCM | √ | √ | √ | √ | √ | |
| JAPAN | Landy C26 | IPDM E/R | √ | √ | √ | √ | √ | |
| JAPAN | Landy C26 | IPC | √ | √ | √ | √ | √ | |
| JAPAN | Landy C26 | ASD-L | √ | √ | √ | √ | √ | |
| JAPAN | Landy C26 | ASD-R | √ | √ | √ | √ | √ | |
| JAPAN | Landy C26 | ALC | √ | √ | √ | √ | √ | |
| JAPAN | Landy C26 | AVM | √ | √ | √ | √ | √ | |
| JAPAN | Landy C26 | ADAS | √ | √ | √ | √ | √ | |
| JAPAN | Landy C26 | Fr-Camera | √ | √ | √ | √ | √ | |
| JAPAN | Landy C26 | Sonar | √ | √ | √ | √ | √ | |
| JAPAN | EV EVERY | ECM | √ | √ | √ | √ | √ | SP334, SP523, SP385, SP383, SP210, SP209, SP219, SP205, SP242, SP226, SP227, SP228, SP229, SP230, SP231, SP217, SP215, SP206, SP234, SP235, SP240, SP218, SP232, SP221, SP222, SP214, SP223, SP611, SP612, SP613, SP220, SP212, SP237, SP211, SP213, SP224, SP200, SP225, SP216, SP201, SP202, SP203, SP239, SP236, SP233, SP668, SP669, SP670, SP679, SP238, SP629, SP243, SP241, SP683, SP684, SP680, SP714, SP715 |
| JAPAN | EV EVERY | ABS/ESP | √ | √ | √ | √ | √ | SP354, SP355, SP360, SP358, SP353, SP349, SP350, SP352, SP359, SP351, SP356, SP170, SP172, SP176, SP179, SP174, SP177, SP175, SP178, SP171, SP173 |
| JAPAN | EV EVERY | PAS | √ | √ | √ | √ | √ | SP255 |
| JAPAN | EV EVERY | SRS | √ | √ | √ | √ | √ | |
| JAPAN | EV EVERY | AC | √ | √ | √ | √ | √ | |
| JAPAN | EV EVERY | BCM | √ | √ | √ | √ | √ | SP380, SP375, SP378, SP381, SP379, SP377, SP376 |
| JAPAN | EV EVERY | EV MOTOR | √ | √ | √ | √ | √ | SP196, SP192, SP191, SP195 |
| JAPAN | EV EVERY | EV AC | √ | √ | √ | √ | √ | |
| JAPAN | others | ECM | √ | √ | √ | √ | √ | SP334, SP523, SP385, SP383, SP210, SP209, SP219, SP205, SP242, SP226, SP227, SP228, SP229, SP230, SP231, SP217, SP215, SP206, SP234, SP235, SP240, SP218, SP232, SP221, SP222, SP214, SP223, SP611, SP612, SP613, SP220, SP212, SP237, SP211, SP213, SP224, SP200, SP225, SP216, SP201, SP202, SP203, SP239, SP236, SP233, SP668, SP669, SP670, SP679, SP238, SP629, SP243, SP241, SP683, SP684, SP680, SP714, SP715 |
| JAPAN | others | TCM | √ | √ | √ | √ | √ | SP529, SP528, SP530, SP531, SP532, SP321, SP322, SP323, SP324, SP618, SP713, SP326, SP316, SP325, SP617, SP319, SP320, SP318, SP315 |

| | | | | | | | | |
|-------|---------------|----------------------------------|---|---|---|---|---|--|
| JAPAN | others | ABS/ESP | √ | √ | √ | √ | √ | SP354, SP355, SP360, SP358, SP353, SP349, SP350, SP352, SP359, SP351, SP356, SP170, SP172, SP176, SP179, SP174, SP177, SP175, SP178, SP171, SP173 |
| JAPAN | others | PAS | √ | √ | √ | √ | √ | SP255 |
| JAPAN | others | SRS | √ | √ | √ | √ | √ | |
| JAPAN | others | AC | √ | √ | √ | √ | √ | |
| JAPAN | others | BCM | √ | √ | √ | √ | √ | SP196, SP192, SP191, SP195 |
| JAPAN | others | IMMOBILIZER-ON-DIAG | √ | √ | √ | √ | √ | SP303 |
| JAPAN | others | EMCD | √ | √ | √ | √ | √ | |
| JAPAN | others | IPC | √ | √ | √ | √ | √ | SP298, SP297, SP616, SP293, SP295, SP614, SP300, SP615, SP662, SP296, SP301 |
| JAPAN | others | ALC | √ | √ | √ | √ | √ | SP189 |
| JAPAN | others | ACCM | √ | √ | √ | √ | √ | SP182, SP183 |
| JAPAN | others | CNG/LPG | √ | √ | √ | √ | √ | |
| JAPAN | others | ICM | √ | √ | √ | √ | √ | SP265, SP266, SP268, SP269, SP270, SP267 |
| JAPAN | others | RBS | √ | √ | √ | √ | √ | SP310, SP719, SP718, SP309 |
| JAPAN | others | BMU | √ | √ | √ | √ | √ | |
| JAPAN | others | ADM | √ | √ | √ | √ | √ | SP185, SP186, SP187, SP660, SP661 |
| JAPAN | others | SCAM | √ | √ | √ | √ | √ | SP313, SP314, SP312 |
| JAPAN | others | ISG | √ | √ | √ | √ | √ | |
| JAPAN | others | CSW | √ | √ | √ | √ | √ | |
| JAPAN | others | HCU | √ | √ | √ | √ | √ | SP257, SP258, SP259 |
| JAPAN | others | HVBMU | √ | √ | √ | √ | √ | SP260, SP261, SP622, SP262 |
| JAPAN | others | INV | √ | √ | √ | √ | √ | |
| JAPAN | others | Acoustic Vehicle Alerting System | √ | √ | √ | √ | √ | |
| JAPAN | others | MFL | √ | √ | √ | √ | √ | SP307 |
| JAPAN | others | Head-Up Display | √ | √ | √ | √ | √ | |
| JAPAN | others | CGW | √ | √ | √ | √ | √ | |
| JAPAN | others | Sonar | √ | √ | √ | √ | √ | SP671 |
| JAPAN | others | Blind Spot Monitor | √ | √ | √ | √ | √ | SP674 |
| JAPAN | others | Auto-On Headlight | √ | √ | √ | √ | √ | SP717 |
| Other | VITARA BREZZA | ECM | √ | √ | √ | √ | √ | SP334, SP523, SP385, SP383, SP210, SP209, SP219, SP205, SP242, SP226, SP227, SP228, SP229, SP230, SP231, SP217, SP215, SP206, SP234, SP235, SP240, SP218, SP232, SP221, SP222, SP214, SP223, SP611, SP612, SP613, SP220, SP212, SP237, SP211, SP213, SP224, SP200, SP225, SP216, SP201, SP202, SP203, SP239, SP236, SP233, SP668, SP669, SP670, SP679, SP238, SP629, SP243, SP241, SP683, SP684, SP680, SP714, SP715 |
| Other | VITARA BREZZA | TCM | √ | √ | √ | √ | √ | SP321, SP322, SP323, SP324, SP618, SP713, SP326, SP316, SP325, SP617, SP319, SP320, SP318, SP315 |
| Other | VITARA BREZZA | ABS/ESP | √ | √ | √ | √ | √ | SP354, SP355, SP360, SP358, SP353, SP349, SP350, SP352, SP359, SP351, SP356, SP170, SP172, SP176, SP179, SP174, SP177, SP175, SP178, SP171, SP173 |
| Other | VITARA BREZZA | PAS | √ | √ | √ | √ | √ | SP255 |
| Other | VITARA BREZZA | SRS | √ | √ | √ | √ | √ | |
| Other | VITARA BREZZA | AC | √ | √ | √ | √ | √ | |
| Other | VITARA BREZZA | BCM | √ | √ | √ | √ | √ | SP196, SP192, SP191, SP195 |
| Other | VITARA BREZZA | IMMOBILIZER-ON-DIAG | √ | √ | √ | √ | √ | SP303 |

| | | | | | | | | |
|-------|----------------|---------------------|---|---|---|---|---|--|
| Other | VITARA BREZZA | IPC | √ | √ | √ | √ | √ | SP298, SP297, SP616, SP293, SP295, SP614, SP300, SP615, SP662, SP296, SP301 |
| Other | CIAZ(AVB413D) | ECM | √ | √ | √ | √ | √ | SP334, SP523, SP385, SP383, SP210, SP209, SP219, SP205, SP242, SP226, SP227, SP228, SP229, SP230, SP231, SP217, SP215, SP206, SP234, SP235, SP240, SP218, SP232, SP221, SP222, SP214, SP223, SP611, SP612, SP613, SP220, SP212, SP237, SP211, SP213, SP224, SP200, SP225, SP216, SP201, SP202, SP203, SP239, SP236, SP233, SP668, SP669, SP670, SP679, SP238, SP629, SP243, SP241, SP683, SP684, SP680, SP714, SP715 |
| Other | CIAZ(AVB413D) | ABS/ESP | √ | √ | √ | √ | √ | SP170, SP172, SP176, SP179, SP174, SP177, SP175, SP178, SP171, SP173 |
| Other | CIAZ(AVB413D) | PAS | √ | √ | √ | √ | √ | SP255 |
| Other | CIAZ(AVB413D) | SRS | √ | √ | √ | √ | √ | |
| Other | CIAZ(AVB413D) | AC | √ | √ | √ | √ | √ | |
| Other | CIAZ(AVB413D) | BCM | √ | √ | √ | √ | √ | SP196, SP192, SP191, SP195 |
| Other | CIAZ(AVB413D) | IMMOBILIZER-ON-DIAG | √ | √ | √ | √ | √ | SP303 |
| Other | CIAZ(AVB413D) | IPC | √ | √ | √ | √ | √ | SP298, SP297, SP616, SP293, SP295, SP614, SP300, SP615, SP662, SP296, SP301 |
| Other | CIAZ(AVB413D) | ALC | √ | √ | √ | √ | √ | SP189 |
| Other | CIAZ(AVB413D) | GW | √ | √ | √ | √ | √ | SP256 |
| Other | Swift(AZI413D) | ECM | √ | √ | √ | √ | √ | SP334, SP523, SP385, SP383, SP210, SP209, SP219, SP205, SP242, SP226, SP227, SP228, SP229, SP230, SP231, SP217, SP215, SP206, SP234, SP235, SP240, SP218, SP232, SP221, SP222, SP214, SP223, SP611, SP612, SP613, SP220, SP212, SP237, SP211, SP213, SP224, SP200, SP225, SP216, SP201, SP202, SP203, SP239, SP236, SP233, SP668, SP669, SP670, SP679, SP238, SP629, SP243, SP241, SP683, SP684, SP680, SP714, SP715 |
| Other | Swift(AZI413D) | ABS/ESP | √ | √ | √ | √ | √ | SP354, SP355, SP360, SP358, SP353, SP349, SP350, SP352, SP359, SP351, SP356, SP170, SP172, SP176, SP179, SP174, SP177, SP175, SP178, SP171, SP173 |
| Other | Swift(AZI413D) | PAS | √ | √ | √ | √ | √ | SP255 |
| Other | Swift(AZI413D) | SRS | √ | √ | √ | √ | √ | |
| Other | Swift(AZI413D) | AC | √ | √ | √ | √ | √ | |
| Other | Swift(AZI413D) | BCM | √ | √ | √ | √ | √ | SP380, SP375, SP378, SP381, SP379, SP377, SP376, SP196, SP192, SP191, SP195 |
| Other | Swift(AZI413D) | IMMOBILIZER-ON-DIAG | √ | √ | √ | √ | √ | SP303 |
| Other | Swift(AZI413D) | IPC | √ | √ | √ | √ | √ | SP298, SP297, SP616, SP293, SP295, SP614, SP300, SP615, SP662, SP296, SP301 |
| Other | Swift(AZI413D) | ICM | √ | √ | √ | √ | √ | SP265, SP266, SP268, SP269, SP270, SP267 |
| Other | Swift(AZI413D) | CGW | √ | √ | √ | √ | √ | |
| Other | D13A | ECM | √ | √ | √ | √ | √ | SP334, SP523, SP385, SP383, SP210, SP209, SP219, SP205, SP242, SP226, SP227, SP228, SP229, SP230, SP231, SP217, SP215, SP206, SP234, SP235, SP240, SP218, SP232, SP221, SP222, SP214, SP223, SP611, SP612, SP613, SP220, SP212, SP237, SP211, SP213, SP224, SP200, SP225, SP216, SP201, SP202, SP203, SP239, SP236, SP233, SP668, SP669, SP670, SP679, SP238, SP629, SP243, SP241, SP683, SP684, SP680, SP714, SP715 |

| | | | | | | | | |
|-------|------|---------------------|---|---|---|---|---|---|
| Other | D13A | ABS/ESP | √ | √ | √ | √ | √ | SP354, SP355, SP360, SP358, SP353, SP349, SP350, SP352, SP359, SP351, SP356, SP170, SP172, SP176, SP179, SP174, SP177, SP175, SP178, SP171, SP173 |
| Other | D13A | PAS | √ | √ | √ | √ | √ | SP255 |
| Other | D13A | SRS | √ | √ | √ | √ | √ | |
| Other | D13A | BCM | √ | √ | √ | √ | √ | SP380, SP375, SP378, SP381, SP379, SP377, SP376, SP196, SP192, SP191, SP195 |
| Other | D13A | IPC | √ | √ | √ | √ | √ | SP380, SP375, SP378, SP381, SP379, SP377, SP376, SP196, SP192, SP191, SP195 |
| Other | D13A | GW | √ | √ | √ | √ | √ | SP256 |
| Other | D13A | TCM | √ | √ | √ | √ | √ | SP529, SP528, SP530, SP531, SP532, SP321, SP322, SP323, SP324, SP618, SP713, SP326, SP316, SP325, SP617, SP319, SP320, SP318, SP315 |
| Other | D13A | AC | √ | √ | √ | √ | √ | |
| Other | D13A | AC2 | √ | √ | √ | √ | √ | |
| Other | D13A | OCM | √ | √ | √ | √ | √ | |
| Other | D13A | 4WD | √ | √ | √ | √ | √ | |
| Other | D13A | IMMOBILIZER-ON-DIAG | √ | √ | √ | √ | √ | SP303 |
| Other | D13A | IMMOBILIZER-ON-DIAG | √ | √ | √ | √ | √ | |
| Other | D13A | EMCD | √ | √ | √ | √ | √ | |
| Other | D13A | TPMS | √ | √ | √ | √ | √ | SP331, SP533 |
| Other | D13A | ALC | √ | √ | √ | √ | √ | SP189 |
| Other | D13A | SCC | √ | √ | √ | √ | √ | |
| Other | D13A | ACCM | √ | √ | √ | √ | √ | SP182, SP183 |
| Other | D13A | CNG/LPG | √ | √ | √ | √ | √ | |
| Other | D13A | ICM | √ | √ | √ | √ | √ | SP265, SP266, SP268, SP269, SP270, SP267 |
| Other | D13A | RBS | √ | √ | √ | √ | √ | SP310, SP719, SP718, SP309 |

Special Functions List

| No. | Functions Name | System Name |
|--------|---|-------------|
| SPSP1 | Steering angle sensor adjustment | ABS/ESP |
| SPSP2 | Temperature compensation | AC |
| SPSP3 | Rec memory settings | AC |
| SPSP4 | Fre memory settings | AC |
| SPSP5 | Mode mode wind configuration | AC |
| SPSP6 | Gas sensor sensitivity adjustment | AC |
| SPSP7 | Operation setting for clean SW operation | AC |
| SPSP8 | Temperature compensation | AC |
| SPSP9 | Target evaporator temperature upper | AC |
| SPSP10 | Operating condition setting of idling stop system | AC |
| SPSP11 | Intake switching | AC |
| SPSP12 | Decrease in wind | AC |
| SPSP13 | HVAC test | AC |
| SPSP15 | C/U parts number | Airbag |
| SPSP16 | Passenger airbag | Airbag |
| SPSP17 | NON-VIEWABLE AREA REMINDER | AVM |
| SPSP18 | CALIBRATING CAMERA IMAGE (FRONT CAMERA) | AVM |
| SPSP19 | CALIBRATING CAMERA IMAGE (PASS-SIDE CAMERA) | AVM |
| SPSP20 | CALIBRATING CAMERA IMAGE (DR-SIDE CAMERA) | AVM |
| SPSP21 | CALIBRATING CAMERA IMAGE (REAR CAMERA) | AVM |
| SPSP22 | FINE TUNING OF BIRDS-EYE VIEW | AVM |
| SPSP23 | PREDICTIVE COURSE LINE DISPLAY | AVM |
| SPSP24 | INITIALIZE CAMERA IMAGE CALIBRATION | AVM |
| SPSP26 | Lock door lock lock | BCM |
| SPSP27 | Answer back buzzer | BCM |
| SPSP28 | Battery break alarm | BCM |
| SPSP29 | Headlamp auto light | BCM |
| SPSP30 | Lock / unlock feature | BCM |
| SPSP31 | Room lamp timer lighting condition setting | BCM |
| SPSP32 | Engine start | BCM |
| SPSP33 | Room Lamp OFF Time Set | BCM |
| SPSP34 | Detection of vehicle speed wiper | BCM |

| | | |
|--------|--|-----------|
| SPSP35 | Room Lamp ON Time Set | BCM |
| SPSP36 | Room lamp battery saver set | BCM |
| SPSP37 | Headlamp battery saver set | BCM |
| SPSP38 | Autolite logic settings | BCM |
| SPSP39 | Auto door lock | BCM |
| SPSP40 | Auto door unlock feature | BCM |
| SPSP41 | Auto door lock / unlock | BCM |
| SPSP42 | Indoor antenna diagnosis | BCM |
| SPSP43 | Auto lock control | BCM |
| SPSP44 | Key lock prevention function | BCM |
| SPSP45 | Show function ranking | BCM |
| SPSP46 | Room lamp timer operating time setting | BCM |
| SPSP47 | Fog lamp override | BCM |
| SPSP49 | SIGNATURE LIGHT SETTING | BCM |
| SPSP51 | Answer back hazard | BCM |
| SPSP52 | Intelligent key ID | BCM |
| SPSP53 | Answer back key lock | BCM |
| SPSP54 | Reset Setting Value | BCM |
| SPSP55 | Answer back hazard | BCM |
| SPSP56 | Room lamp timer | BCM |
| SPSP57 | Answer backkey key lock function | BCM |
| SPSP58 | AUTO AIM | Fr-Camera |
| SPSP62 | Volume settings | Sonar |
| SPSP64 | G sensor calibration | TCM |
| SPSP65 | ENGINE BRAKE ADJ. | TCM |
| SPSP66 | CONFORM CVTF DETERIORTN | TCM |
| SPSP67 | WRITE IP CHARA - REPLACEMENT AT/CVT | TCM |
| SPSP68 | ERASE LEARNING VALUE | TCM |
| SPSP69 | Electric oil pump | TCM |
| SPSP70 | Calibration data | TCM |
| SPSP71 | Steering angle sensor adjustment | AFS |
| SPSP72 | Detection of vehicle speed wiper | BCM |
| SPSP73 | Room Lamp ON Time Set | BCM |
| SPSP74 | Headlamp battery saver set | BCM |
| SPSP75 | Room Lamp ON Time Set | BCM |

| | | |
|---------|--|--------------------|
| SPSP76 | Lock door lock lock | BCM |
| SPSP77 | Reset Setting Value | BCM |
| SPSP78 | Room lamp timer | BCM |
| SPSP79 | Room Lamp OFF Time Set | BCM |
| SPSP80 | Room lamp battery saver set | BCM |
| SPSP81 | Theft Alm Trg | BCM |
| SPSP82 | Door Lock-Unlock Set | BCM |
| SPSP83 | Anti-Lock Out Set | BCM |
| SPSP84 | Hazard Lamp Set | BCM |
| SPSP85 | Multi Answer Back Set | BCM |
| SPSP86 | Auto Lock Set | BCM |
| SPSP87 | Panic Alm Set | BCM |
| SPSP88 | Security Alarm Set | BCM |
| SPSP89 | Custom A/Light Setting | BCM |
| SPSP90 | Ill Delay Set | BCM |
| SPSP91 | Retained PWR Set | BCM |
| SPSP92 | Multi Remote Ent | BCM |
| SPSP93 | Set I/L D-UNLCK INTCON | BCM |
| SPSP94 | Room Lamp Timer Set | BCM |
| SPSP95 | ID Read | BCM |
| SPSP96 | ID Regist | BCM |
| SPSP97 | Head Lamp Battery Saver SET | BCM |
| SPSP98 | Wiper Speed Setting | BCM |
| SPSP99 | Change settings | BCM |
| SPSP100 | Change settings | BCM |
| SPSP101 | Headlamp auto light | BCM |
| SPSP102 | Reset Setting Value | BCM |
| SPSP103 | Room lamp timer | BCM |
| SPSP104 | Room lamp timer lighting condition setting | BCM |
| SPSP105 | Room Lamp OFF Time Set | BCM |
| SPSP106 | Idle Air Vol Learn | Engine/ Powertrain |
| SPSP107 | SRT Status | Engine/ Powertrain |
| SPSP108 | EVAP System Close | Engine/ Powertrain |
| SPSP109 | VIN Read | Engine/ Powertrain |
| SPSP110 | Data exchange at CPU exchange | Engine/ Powertrain |
| SPSP111 | Data exchange at CPU exchange | Engine/ Powertrain |

| | | |
|---------|--------------------------------------|--------------------|
| SPSP112 | Battery discharge current | Engine/ Powertrain |
| SPSP113 | Air fuel ratio initial learning | Engine/ Powertrain |
| SPSP114 | Idling stop | Engine/ Powertrain |
| SPSP115 | Cool fan | Engine/ Powertrain |
| SPSP116 | Integrated battery discharge current | Engine/ Powertrain |
| SPSP117 | Sub starter & generator counter | Engine/ Powertrain |
| SPSP118 | CLSD THL POS LEARN | Engine/ Powertrain |
| SPSP119 | Self-Learning Cont | Engine/ Powertrain |
| SPSP120 | Fuel Pressure Release | Engine/ Powertrain |
| SPSP121 | Self-Learning Cont | Engine/ Powertrain |
| SPSP122 | Fuel Pressure Release | Engine/ Powertrain |
| SPSP123 | DTC Work Support | Engine/ Powertrain |
| SPSP124 | Idle Air Vol Learn | Engine/ Powertrain |
| SPSP125 | VIN Registration | Engine/ Powertrain |
| SPSP126 | Answer back hazard | I-KEY |
| SPSP127 | Engine start | I-KEY |
| SPSP128 | Answer back buzzer | I-KEY |
| SPSP129 | Intelligent key ID | I-KEY |
| SPSP130 | Battery break alarm | I-KEY |
| SPSP131 | Answer back key lock | I-KEY |
| SPSP132 | Answer backkey key lock function | I-KEY |
| SPSP133 | Fetch from window | I-KEY |
| SPSP134 | Auto lock timer | I-KEY |
| SPSP135 | Power slide door | I-KEY |
| SPSP136 | Lock / unlock feature | I-KEY |
| SPSP146 | Electric oil pump | TCM |
| SPSP147 | Cvtf degradability verification | TCM |
| SPSP148 | Engine brake adjustment | TCM |
| SPSP149 | G sensor calibration | TCM |
| SPSP150 | Calibration data | TCM |
| SPSP151 | Calibration data erasure | TCM |
| SPSP152 | C/U parts number | 4WD |
| SPSP153 | ST Angle Sensor Adjustment | ABS/ESP |
| SPSP154 | Decel G Sen Calibration | ABS/ESP |
| SPSP155 | C/U parts number | ABS/ESP |
| SPSP156 | Passenger airbag | Airbag |

| | | |
|---------|--|-------------------------|
| SPSP157 | C/U Identification Number | Airbag |
| SPSP158 | Height sensor initialization | Headlight Auto Leveling |
| SPSP162 | C/U parts number | Headlight Auto Leveling |
| SPSP163 | Intake air volume | Engine/ Powertrain |
| SPSP164 | Air fuel ratio learning | Engine/ Powertrain |
| SPSP166 | All learning value storage | Motor Assist AT |
| SPSP167 | DTC Work Support | TCM |
| SPSP170 | Hydraulic control test | ABS/ESP |
| SPSP171 | Hydraulic control test | ABS/ESP |
| SPSP172 | ESP Function Setting | ABS/ESP |
| SPSP173 | Sensor Calibration | ABS/ESP |
| SPSP174 | Hydraulic control test | ABS/ESP |
| SPSP175 | Sensor Calibration | ABS/ESP |
| SPSP176 | Sensor Calibration | ABS/ESP |
| SPSP177 | Hydraulic control test | ABS/ESP |
| SPSP178 | Hydraulic control test | ABS/ESP |
| SPSP179 | Sensor Calibration | ABS/ESP |
| SPSP182 | Aoming adjustment | ACCM |
| SPSP183 | Seat belt drive | ACCM |
| SPSP185 | Calibration | ADM |
| SPSP186 | Display Calibration Marker Range | ADM |
| SPSP187 | Long Shot Image Forced Display | ADM |
| SPSP189 | Height Sensor Initial Setting | Headlight Auto Leveling |
| SPSP191 | Dead Lock Control Test | BCM |
| SPSP192 | Configuration | BCM |
| SPSP194 | Steering angle sensor calibration | BCM |
| SPSP195 | Remote starter Code Registration | BCM |
| SPSP196 | TPS ID registration | BCM |
| SPSP200 | Oil change request light reset | Engine/ Powertrain |
| SPSP201 | EGR-1 Data Initialization | Engine/ Powertrain |
| SPSP202 | A/F sensor parameter initialization | Engine/ Powertrain |
| SPSP203 | DPF condition parameter Initialization | Engine/ Powertrain |
| SPSP205 | Initialize MAF sensor data | Engine/ Powertrain |
| SPSP206 | EGR-1 Data Initialization | Engine/ Powertrain |

| | | |
|---------|---|--------------------|
| SPSP209 | Vehicle variant registration | Engine/ Powertrain |
| SPSP210 | Injector calibration code | Engine/ Powertrain |
| SPSP211 | Regeneration | Engine/ Powertrain |
| SPSP212 | Vehicle variant registration | Engine/ Powertrain |
| SPSP213 | Initialize differential pressure sensor data | Engine/ Powertrain |
| SPSP214 | Initialize MAF sensor data | Engine/ Powertrain |
| SPSP215 | Initialize differential pressure sensor data | Engine/ Powertrain |
| SPSP216 | VIN Registration | Engine/ Powertrain |
| SPSP217 | Regeneration | Engine/ Powertrain |
| SPSP218 | DPF condition parameter Initialization | Engine/ Powertrain |
| SPSP219 | ECM replacement | Engine/ Powertrain |
| SPSP220 | Injector calibration code | Engine/ Powertrain |
| SPSP221 | Initialize flywheel data | Engine/ Powertrain |
| SPSP222 | Initialize A/F sensor data | Engine/ Powertrain |
| SPSP223 | Initialize rail pressure sensor | Engine/ Powertrain |
| SPSP224 | Initialize DPF data | Engine/ Powertrain |
| SPSP225 | Initialize overpressure valve | Engine/ Powertrain |
| SPSP226 | DPF driving pattern parameter initialization | Engine/ Powertrain |
| SPSP227 | A/F sensor dew point initialization | Engine/ Powertrain |
| SPSP228 | Fuel injection system part parameter initialization | Engine/ Powertrain |
| SPSP229 | DPF regeneration parameter Initialization | Engine/ Powertrain |
| SPSP230 | Reset driven distance with Fuel Filter Warning Light ON | Engine/ Powertrain |
| SPSP231 | Freeze Frame Data Clear | Engine/ Powertrain |
| SPSP232 | EGR-2 Data Initialization | Engine/ Powertrain |
| SPSP233 | Fuel Injection System Part Parameter Initialization | Engine/ Powertrain |
| SPSP234 | Throttle Valve Test | Engine/ Powertrain |
| SPSP235 | Turbocharger Test | Engine/ Powertrain |
| SPSP236 | Brake Stroke Sensor Zero Point Initialization | Engine/ Powertrain |
| SPSP237 | ECM replacement | Engine/ Powertrain |
| SPSP238 | Injector calibration code | Engine/ Powertrain |
| SPSP239 | VIN Registration | Engine/ Powertrain |
| SPSP240 | A/F sensor parameter initialization | Engine/ Powertrain |
| SPSP241 | ECM replacement | Engine/ Powertrain |
| SPSP242 | Oil change request light reset | Engine/ Powertrain |

| | | |
|---------|---|---|
| SPSP243 | VIN Registration | Engine/ Powertrain |
| SPSP246 | Injector calibration code | Engine/ Powertrain |
| SPSP247 | ECM replacement | Engine/ Powertrain |
| SPSP248 | Initialize EGR valve data | Engine/ Powertrain |
| SPSP249 | Initialize inlet throttle valve data | Engine/ Powertrain |
| SPSP250 | Initialize Diesel PF data | Engine/ Powertrain |
| SPSP251 | High Pressure Test | Engine/ Powertrain |
| SPSP252 | Run Up Test | Engine/ Powertrain |
| SPSP253 | Regeneration | Engine/ Powertrain |
| SPSP254 | Oil change request light reset | Engine/ Powertrain |
| SPSP258 | Vehicle Collision Detect History Flag Clear | Hybrid Control Unit |
| SPSP259 | INV Short Circuit of Valve arm detection History Flag Clear | Hybrid Control Unit |
| SPSP260 | Cell Voltage Monitoring Integrated Circuit Starting | HV Battery Management |
| SPSP261 | Power Pack Replacement | HV Battery Management |
| SPSP262 | High Voltage Battery Controller Replacement | HV Battery Management |
| SPSP265 | Starter Driving Counter Registration | Engine Auto Stop and Start |
| SPSP266 | Starter Driving Counter Reset | Engine Auto Stop and Start |
| SPSP267 | Brake pressure holding inspection | Engine Auto Stop and Start |
| SPSP268 | Starter Data Copy | Engine Auto Stop and Start |
| SPSP269 | Starter Data Reset | Engine Auto Stop and Start |
| SPSP270 | Slope Sensor / G Sensor Calibration | Engine Auto Stop and Start |
| SPSP293 | Meter Configuration | Combination Meter / Meter/M&A |
| SPSP295 | Meter Configuration | Combination Meter / Meter/M&A |
| SPSP296 | Oil Change Reminder Light Configuration | Combination Meter / Meter/M&A |
| SP297 | Oil Change Reminder Light Reset | Combination Meter / Meter/M&A |
| SP298 | Oil Change Reminder Light Configuration | Combination Meter / Meter/M&A |
| SP300 | Meter Configuration | Combination Meter / Meter/M&A |
| SP301 | Configuration | Combination Meter / Meter/M&A |
| SP303 | Configuration | Keyless Start |
| SP305 | TPS ID registration | Keyless Start |
| SP307 | Aiming Adjustment | Dual Sensor Brake Support |
| SP309 | Fault diagnosis information clear | Dual Camera Brake Support / Adaptive Cruise Control |
| SP310 | Aiming | Dual Camera Brake Support / Adaptive Cruise Control |
| SP312 | Clear Aiming Adjustment Value | Dual Camera Brake Support |

| | | |
|-------|------------------------------------|--|
| SP313 | Aiming Adjustment | Dual Camera Brake Support |
| SP314 | Aiming Readjustment | Dual Camera Brake Support |
| SP315 | Learning Value Initialization | TCM |
| SP316 | Learning Value Initialization | TCM |
| SP318 | Learning Value Initialization | TCM |
| SP319 | Electric Oil Pump Air Bleeding | TCM |
| SP320 | Slope Sensor Calibration | TCM |
| SP321 | All Learning Value Initialization | TCM |
| SP322 | Clutch Assembly Initialization | TCM |
| SP323 | Shift Tower Initialization | TCM |
| SP324 | Oil Discharge | TCM |
| SP325 | 2nd Start-off Control | TCM |
| SP326 | Neutral Position Calibration | TCM |
| SP328 | Telematics Control Unit Inspection | Distance based on Global Navigation Satell |
| SP329 | SOS Switch Inspection | Distance based on Global Navigation Satell |
| SP330 | Configuration | Distance based on Global Navigation Satell |
| SP331 | TPS ID registration | TPMS |
| SP334 | VIN Registration | Engine/ Powertrain |
| SP340 | Keyless Start System | Immobi and/or Keyless System |
| SP343 | Solenoid Test | ABS/ESP |
| SP344 | Pump Motor | ABS/ESP |
| SP345 | Relay Test | ABS/ESP |
| SP346 | Lamp Test | ABS/ESP |
| SP349 | ESP Function Setting | ABS/ESP |
| SP350 | Sensor Calibration | ABS/ESP |
| SP351 | Sensor Calibration | ABS/ESP |
| SP352 | Hydraulic control test | ABS/ESP |
| SP353 | Sensor Calibration | ABS/ESP |
| SP354 | Hydraulic control test | ABS/ESP |
| SP355 | Hydraulic control test | ABS/ESP |
| SP356 | ESP Function Setting | ABS/ESP |
| SP358 | Hydraulic control test | ABS/ESP |
| SP359 | Hydraulic control test | ABS/ESP |
| SP360 | Hydraulic control test | ABS/ESP |

| | | |
|-------|---------------------------------|--------------------|
| SP362 | ABS Warning Lamp Off | ABS/ESP |
| SP363 | ETC Info Lamp Off | ABS/ESP |
| SP364 | Brake Warning Lamp Off | ABS/ESP |
| SP365 | Pump Motor | ABS/ESP |
| SP366 | Inlet solenoid | ABS/ESP |
| SP367 | Outlet solenoid | ABS/ESP |
| SP375 | Configuration | BCM |
| SP376 | Clear air bag information | BCM |
| SP377 | TPS ID registration | BCM |
| SP378 | Dead Lock CONTROL TEST | BCM |
| SP379 | TPS ID registration | BCM |
| SP380 | Dead Lock CONTROL TEST | BCM |
| SP381 | Clear air bag information | BCM |
| SP383 | VIN Registration | Engine/ Powertrain |
| SP385 | VIN Registration | Engine/ Powertrain |
| SP386 | Regeneration | Engine/ Powertrain |
| SP387 | Replace Diesel PF Pres Sen | Engine/ Powertrain |
| SP389 | Reset oil pressure light | Engine/ Powertrain |
| SP390 | Replace Diesel PF Pres Sen | Engine/ Powertrain |
| SP392 | Reset self-learnt function | Engine/ Powertrain |
| SP393 | Reset self-learnt function | Engine/ Powertrain |
| SP394 | Injector calibration code | Engine/ Powertrain |
| SP395 | Reset oil service light | Engine/ Powertrain |
| SP396 | Replace ECM (P0601 present) | Engine/ Powertrain |
| SP397 | Replace ECM | Engine/ Powertrain |
| SP398 | Replace ECM (P0601 not present) | Engine/ Powertrain |
| SP399 | Replace EGR system | Engine/ Powertrain |
| SP400 | Replace O2 sensor | Engine/ Powertrain |
| SP401 | Replace air flow meter sensor | Engine/ Powertrain |
| SP402 | Replace pre-catalyst | Engine/ Powertrain |
| SP403 | Replace Diesel PF | Engine/ Powertrain |
| SP404 | Replace DPF closed couple | Engine/ Powertrain |
| SP405 | Injector calibration code | Engine/ Powertrain |
| SP406 | Replace rail pressure sensor | Engine/ Powertrain |

| | | |
|-------|---|--------------------|
| SP407 | Replace rail pressure sensor | Engine/ Powertrain |
| SP408 | Injector calibration code | Engine/ Powertrain |
| SP409 | Injector calibration code | Engine/ Powertrain |
| SP410 | Vehicle variant registration | Engine/ Powertrain |
| SP411 | Replace EGR | Engine/ Powertrain |
| SP412 | Replace inlet throttle valve | Engine/ Powertrain |
| SP415 | ECM Setting | Engine/ Powertrain |
| SP416 | Regeneration | Engine/ Powertrain |
| SP417 | Initialize EGR valve data | Engine/ Powertrain |
| SP418 | Initialize EGR valve data | Engine/ Powertrain |
| SP419 | Injector calibration code | Engine/ Powertrain |
| SP421 | Initialize inlet throttle valve data | Engine/ Powertrain |
| SP422 | Initialize EGR valve data (For other than software ID:33920-67J12) | Engine/ Powertrain |
| SP423 | Initialize EGR valve data (For software ID:33920-67J12) | Engine/ Powertrain |
| SP424 | Initialize inlet throttle valve data (For other than software ID:33920-67J12) | Engine/ Powertrain |
| SP425 | Initialize inlet throttle valve data (For software ID:33920-67J12) | Engine/ Powertrain |
| SP426 | Initialize Diesel PF Data | Engine/ Powertrain |
| SP427 | Replace ECM | Engine/ Powertrain |
| SP428 | Clear DTC(Current P0606 D6) | Engine/ Powertrain |
| SP429 | Initialize inlet throttle valve data | Engine/ Powertrain |
| SP430 | Replace ECM | Engine/ Powertrain |
| SP431 | Initialize EGR valve data | Engine/ Powertrain |
| SP432 | Replace ECM | Engine/ Powertrain |
| SP434 | Adjust idle speed | Engine/ Powertrain |
| SP436 | Vehicle variant registration | Engine/ Powertrain |
| SP438 | Leak detection test | Engine/ Powertrain |
| SP439 | Injector calibration code | Engine/ Powertrain |
| SP441 | Injector calibration code | Engine/ Powertrain |
| SP444 | High pressure pump data Initialization | Engine/ Powertrain |
| SP445 | Vehicle variant registration | Engine/ Powertrain |
| SP446 | Injection correction data register | Engine/ Powertrain |
| SP447 | Air charge data register | Engine/ Powertrain |
| SP448 | Engine control data register | Engine/ Powertrain |
| SP449 | Fuel injector Cal codes register | Engine/ Powertrain |

| | | |
|-------|---|--------------------|
| SP450 | Adjust injection timing | Engine/ Powertrain |
| SP451 | Injection prohibition | Engine/ Powertrain |
| SP452 | Prevention of electric load | Engine/ Powertrain |
| SP453 | Vehicle variant registration | Engine/ Powertrain |
| SP454 | Leak detection test | Engine/ Powertrain |
| SP455 | EGR Valve Data Initialization | Engine/ Powertrain |
| SP456 | Fuel Injector Registration | Engine/ Powertrain |
| SP457 | Adjust idle speed | Engine/ Powertrain |
| SP459 | Replace A/F sensor | Engine/ Powertrain |
| SP460 | Injector calibration code | Engine/ Powertrain |
| SP461 | Vehicle variant registration | Engine/ Powertrain |
| SP462 | Vehicle variant registration | Engine/ Powertrain |
| SP463 | Vehicle variant registration | Engine/ Powertrain |
| SP464 | Replace ECM | Engine/ Powertrain |
| SP465 | Vehicle variant registration | Engine/ Powertrain |
| SP466 | Vehicle variant registration | Engine/ Powertrain |
| SP467 | Replace ECM | Engine/ Powertrain |
| SP468 | Replace A/F sensor | Engine/ Powertrain |
| SP469 | Vehicle variant registration | Engine/ Powertrain |
| SP470 | Replace MAF sensor | Engine/ Powertrain |
| SP471 | Vehicle variant registration | Engine/ Powertrain |
| SP472 | Injector calibration code | Engine/ Powertrain |
| SP473 | Vehicle variant registration | Engine/ Powertrain |
| SP474 | Replace MAF sensor | Engine/ Powertrain |
| SP475 | Injector calibration code | Engine/ Powertrain |
| SP476 | Replace ECM | Engine/ Powertrain |
| SP478 | Reset oil pressure light | Engine/ Powertrain |
| SP479 | Injector calibration code | Engine/ Powertrain |
| SP480 | Injector calibration code | Engine/ Powertrain |
| SP481 | Injector calibration code | Engine/ Powertrain |
| SP482 | Brake Stroke Sensor Zero Point Initialization | Engine/ Powertrain |
| SP483 | Vehicle variant registration | Engine/ Powertrain |
| SP484 | Replace Flywheel | Engine/ Powertrain |
| SP485 | Replace fuel Pres Sen | Engine/ Powertrain |

| | | |
|-------|---------------------------------------|--------------------|
| SP486 | Replace catalyst converter | Engine/ Powertrain |
| SP487 | Replace DPF | Engine/ Powertrain |
| SP488 | Replace differential Pres Sen | Engine/ Powertrain |
| SP489 | Replace Fuel Pressure Sensor | Engine/ Powertrain |
| SP490 | ECM Replacement | Engine/ Powertrain |
| SP491 | Initialize MAF Sensor Data | Engine/ Powertrain |
| SP492 | Initialize A/F Sensor Data | Engine/ Powertrain |
| SP493 | Initialize Flywheel Data | Engine/ Powertrain |
| SP494 | Initialize Fuel Pressure Sensor Data | Engine/ Powertrain |
| SP495 | Initialize rail pressure sensor | Engine/ Powertrain |
| SP497 | Regeneration | Engine/ Powertrain |
| SP498 | Vehicle variant registration | Engine/ Powertrain |
| SP499 | Reset oil pressure light | Engine/ Powertrain |
| SP523 | VIN Registration | Engine/ Powertrain |
| SP528 | Clutch Clamp Position Control | TCM |
| SP529 | Initialize Clutch and Transaxle | TCM |
| SP530 | Clutch Adjustment Control | TCM |
| SP531 | Initialize Clutch | TCM |
| SP532 | Initialize Transaxle | TCM |
| SP533 | TPS ID registration | TPMS |
| SP539 | Hydraulic control test | ABS/ESP |
| SP542 | Hydraulic control test | ABS/ESP |
| SP561 | Hydrauric Circuit Depressurization | TCM |
| SP562 | ECM Replacement | TCM |
| SP563 | TCM Replacement | TCM |
| SP564 | Hydrauric KIT Replacement | TCM |
| SP565 | Gearbox Replacement | TCM |
| SP566 | Oil Pump Replacement | TCM |
| SP567 | Electro Valve Replacement | TCM |
| SP568 | Sensor Module Replacement | TCM |
| SP569 | K1 Clutch Position Sensor Replacement | TCM |
| SP570 | K2 Clutch Position Sensor Replacement | TCM |
| SP571 | Clutches Kit Replacement | TCM |
| SP572 | Accumulator Replacement | TCM |

| | | |
|-------|---|-------------------------------|
| SP573 | SDU Replacement | TCM |
| SP576 | IDLE AIR VOL LEARN | Engine/ Powertrain |
| SP577 | CLSD THL POS LEARN | Engine/ Powertrain |
| SP578 | SELF-LEARNING CONT | Engine/ Powertrain |
| SP579 | A/F INITIAL LEARNING | Engine/ Powertrain |
| SP580 | SUB-STARTER & GENERATOR OPER COUNT CLEAR | Engine/ Powertrain |
| SP581 | CML B/DCHRG CRNT CLEAR | Engine/ Powertrain |
| SP582 | VIN REGISTRATION | Engine/ Powertrain |
| SP583 | SAVING DATA FOR REPLC CPU | Engine/ Powertrain |
| SP584 | WRITING DATA FOR REPLC CPU | Engine/ Powertrain |
| SP585 | Electric intake valve timing control learning | Engine/ Powertrain |
| SP586 | EGR Study | Engine/ Powertrain |
| SP587 | CUMULATIVE SUB-BATTERY DISCHG CURRENT CLEAR | Engine/ Powertrain |
| SP588 | DECEL G SEN CALIBRATION | ABS/ESP |
| SP589 | ST ANGLE SENSOR ADJUSTMENT | ABS/ESP |
| SP591 | MOD FUNCTION | AVM |
| SP592 | SENSOR INITIALIZE | IPDM E/R |
| SP593 | CML B/DCHRG CRNT CLEAR | IPDM E/R |
| SP594 | CAUSE OF AUTO-CANCEL 1 | ADAS |
| SP595 | CAUSE OF AUTO-CANCEL 4 | ADAS |
| SP596 | FEB OPERATION MILEAGE | ADAS |
| SP597 | (TBD)FEB Default OFF/ON SWITCH | ADAS |
| SP598 | REAR WIPER LINK WITH REVERSE SETTING | BCM |
| SP599 | AUTO AIM | Fr-Camera |
| SP600 | REC MEMORY SET | AC |
| SP601 | FRE MEMORY SET | AC |
| SP602 | BLOW SET | AC |
| SP603 | TARGET EVAPORATOR TEMP UPPER LIMIT SETTING | AC |
| SP604 | VOLUME SETTING | Sonar |
| SP611 | Injector calibration code | Engine/ Powertrain |
| SP612 | Vehicle variant registration | Engine/ Powertrain |
| SP613 | ECM replacement | Engine/ Powertrain |
| SP614 | Meter Configuration | Combination Meter / Meter/M&A |
| SP615 | Meter Configuration | Combination Meter / Meter/M&A |

| | | |
|-------|---|-------------------------------|
| SP616 | Oil Change Reminder Light Configuration | Combination Meter / Meter/M&A |
| SP617 | Learning Value Initialization | TCM |
| SP618 | Show Auto Gear Shift Learning Result | TCM |
| SP621 | CAUSE OF ENTRY CANCEL | AVM |
| SP622 | High Voltage Battery Controller Replacement | HV Battery Management |
| SP623 | CALIBRATING CAMERA IMAGE (FRONT CAMERA) | AVM |
| SP624 | CALIBRATING CAMERA IMAGE (PASS-SIDE CAMERA) | AVM |
| SP625 | CALIBRATING CAMERA IMAGE (DR-SIDE CAMERA) | AVM |
| SP626 | CALIBRATING CAMERA IMAGE (REAR CAMERA) | AVM |
| SP627 | FINE TUNING OF BIRDS-EYE VIEW | AVM |
| SP628 | C/U PartNumber | BCM |
| SP629 | ECM replacement | Engine/ Powertrain |
| SP630 | C/U PartNumber | AVM |
| SP631 | Calibration data | TCM |
| SP632 | C/U parts number | TCM |
| SP633 | C/U parts number | Engine/ Powertrain |
| SP634 | Fuel pressure removal | Engine/ Powertrain |
| SP635 | C/U parts number | IPDM E/R |
| SP636 | C/U parts number | Fr-Camera |
| SP637 | C/U parts number | Gateway2 |
| SP638 | C/U parts number | AC |
| SP639 | C/U parts number | Combination Meter / Meter/M&A |
| SP640 | C/U parts number | Sonar |
| SP641 | C/U parts number | ADAS2 |
| SP642 | C/U parts number | Auto Slide Door (Left) |
| SP643 | C/U parts number | Auto Slide Door (Right) |
| SP644 | C/U parts number | TCM |
| SP645 | C/U parts number | ABS/ESP |
| SP646 | C/U parts number | AC |
| SP647 | C/U parts number | ADAS |
| SP648 | C/U parts number | BCM |
| SP649 | C/U parts number | Fr-Camera |
| SP650 | C/U parts number | Sonar |
| SP651 | C/U parts number | Auto Slide Door (Left) |

| | | |
|-------|---|--|
| SP652 | C/U parts number | Auto Slide Door (Right) |
| SP653 | C/U parts number | BCM |
| SP654 | C/U parts number | Engine/ Powertrain |
| SP655 | C/U parts number | Power Steering |
| SP656 | C/U parts number | TCM |
| SP657 | C/U parts number | DIFFLOCK |
| SP658 | Forward clutch point learning | TCM |
| SP659 | C/U PartNumber | ABS/ESP |
| SP660 | Icon Color Setting | ADM |
| SP661 | Camera Controller Replacement | ADM |
| SP662 | Meter Configuration | Combination Meter / Meter/M&A |
| SP665 | C/U PartNumber | Airbag |
| SP668 | Injector calibration code | Engine/ Powertrain |
| SP669 | Vehicle variant registration | Engine/ Powertrain |
| SP670 | ECM replacement | Engine/ Powertrain |
| SP671 | Clear Front Ultrasonic Sensor | Sonar |
| SP674 | Aiming Adjustment | Blind Spot Monitor |
| SP675 | Sensor Calibration | Power Steering |
| SP679 | EGR Valve Learning Value Initialization | Engine/ Powertrain |
| SP680 | Vehicle variant registration | Engine/ Powertrain |
| SP682 | Microphone And Speaker Inspection | Distance based on Global Navigation Satell |
| SP683 | Initialize GPF data | Engine/ Powertrain |
| SP684 | GPF Regeneration | Engine/ Powertrain |
| SP685 | C/U PartNumber | Power Steering |
| SP686 | SIGNATURE LIGHT CUST | BCM |
| SP687 | (TBD)AUTOFOLD FUNCTION | BCM |
| SP688 | FOG LAMP OVERRIDE | BCM |
| SP689 | TWILIGHT On | BCM |
| SP690 | WIPER LINK | BCM |
| SP691 | WIPER SPEED SETTING | BCM |
| SP692 | 3-TIME FLASHER SETTING | BCM |
| SP693 | INSIDE ANT DIAGNOSIS | BCM |
| SP694 | LOCK/UNLOCK BY I-KEY | BCM |
| SP695 | ENGINE START BY I-KEY | BCM |

| | | |
|-------|---|---|
| SP696 | Auto Lock Set | BCM |
| SP697 | IGN/ACC BATTERY SAVER | BCM |
| SP698 | ANSWERBACK I-KEY LOCK UNLOCK | BCM |
| SP699 | ANSWERBACK KEYLESS LOCK UNLOCK | BCM |
| SP700 | WELCOME LIGHT OP SET | BCM |
| SP701 | RESET SETTING VALUE | BCM |
| SP702 | AUTO ACC FNCTN (AUDIO/NAVI SET AFTER IGN OFF) | BCM |
| SP703 | INTELLIGENT KEY LINK SET | BCM |
| SP704 | REMOTE ENGINE STARTER | BCM |
| SP705 | TOUCH SENSOR UNLOCK FUNCTION SETTING | BCM |
| SP707 | CUSTOM A/LIGHT SETTING | BCM |
| SP708 | SET I/L D-UNLCK INTCON | BCM |
| SP713 | Gear Shift Count Initialization for Maintenance | TCM |
| SP714 | Starter Drive Counter Reset | Engine/ Powertrain |
| SP715 | Starter Drive Counter Registration | Engine/ Powertrain |
| SP717 | Configuration | Auto-On Headlight |
| SP718 | Activation (Wake-up) | Far Brake Support / Adaptive Cruise Cont. |
| SP719 | Variant Registration | Far Brake Support / Adaptive Cruise Cont. |

XTOOL