



深圳市朗仁科技有限公司

Shenzhen Xtooltech Co., Ltd

Airbag fix up Function List V16.07

Automaker	Type1	Type2	Type3	Type4
OBD repair	General purpose	Seo	5490636	
OBD repair	Audi	4B0959655G	Clear collision record	
OBD repair	Audi	4B0959655G	Clear ECU Internal fault	
OBD repair	Audi	4B0959655R	Clear collision record	
OBD repair	Audi	4B0959655R	Clear ECU Internal fault	
OBD repair	Honda	Fit		
OBD repair	Honda	Sidi		
OBD repair	public	VW5		
OBD repair	public	VW6		
OBD repair	public	VW3		
OBD repair	BYD	Qin		
OBD repair	BYD	Tang		
OBD repair	BYD	new F3		
OBD repair	BYD	F3		
OBD repair	BYD	F3R		
OBD repair	BYD	F3CK		
OBD repair	BYD	F3DM		
OBD repair	BYD	F0		
OBD repair	BYD	F6		
OBD repair	BYD	Si Rui		
OBD repair	BYD	Speed sharp		
OBD repair	BYD	M6		
OBD repair	BYD	S6		
OBD repair	BYD	S7		
OBD repair	BYD	S8		
OBD repair	BYD	L3		
OBD repair	BYD	G3		
OBD repair	BYD	G5		

OBD repair	BYD	G6		
OBD repair	BYD	E6A		
OBD repair	BYD	E6B		
OBD repair	BYD	E6Y		
Adapter repair				
OBD repair	American model	Buick	95080	9037091
OBD repair	American model	Buick	95080	1.00577E+13
OBD repair	American model	Buick	95080	96406712
OBD repair	American model	Buick	95160	9042475(Types of 1)
OBD repair	American model	Buick	95160	9042475(Types of 2)
OBD repair	American model	Buick	95160	9012526
OBD repair	American model	Buick	95160	9012455
OBD repair	American model	Buick	95160	5499985
OBD repair	American model	Ford	95080	4M5T-14B056
OBD repair	American model	Ford	95080	4M5T-14B056-BJ
OBD repair	American model	Ford	95080	4M5T-14B056-CA
OBD repair	American model	Ford	95160	4S7T-14B056-AC
OBD repair	American model	Ford	95160	5L84-14B321-DC
OBD repair	American model	Ford	95160	6C1T-14B056-AE
OBD repair	American model	Ford	95160	7M2T-14B056-AB
OBD repair	American model	Ford	95160	7S7T-14B056-BB
OBD repair	American model	Ford	95160	7S7T-14B056-BC
OBD repair	American model	Ford	95160	8M5T-14B321-BD
OBD repair	American model	Ford	95160	8M5T-14B321-BF
OBD repair	American model	Ford	95160	9M5T-14B321-BA
OBD repair	American model	Ford	95160	9M5T-14B321-BB
OBD repair	American model	Ford	95160	9M5T-14B321-CA
OBD repair	American model	Ford	95320	8V51-14B321-AG
OBD repair	American model	Ford	95320	8V51-14B321-AH
OBD repair	American model	Ford	95320	8V59-14B321-BA
OBD repair	American model	Ford	95320	8V59-14B321-CA
OBD repair	American model	Ford	95320	AA6T-14B321-AA
OBD repair	American model	Ford	95320	AA6T-14B321-BA
OBD repair	American model	Ford	95320	AA6T-14B321-CA
OBD repair	American model	Ford	95320	AS7T-14B321-BA
OBD repair	American model	Ford	95320	BS7T-14B32-AC

OBD repair	American model	Ford	95320	BS7T-14B321-AC
OBD repair	American model	Ford	95320	CM5T-14B321-CA
OBD repair	American model	Ford	95640	DV4T-14B321-DG
OBD repair	American model	Chrysler	95256	P68148040AA
OBD repair	American model	Chevrolet	95080	24514261
OBD repair	American model	Chevrolet	95080	24522270
OBD repair	American model	Chevrolet	95080	24522720
OBD repair	American model	Chevrolet	95080	24544647
OBD repair	American model	Chevrolet	95080	96406534
OBD repair	American model	Chevrolet	95080	96644507
OBD repair	American model	Chevrolet	95080	P2406-10007
OBD repair	American model	Chevrolet	95160	9012494
OBD repair	American model	Chevrolet	95160	9012526
OBD repair	American model	Chevrolet	95160	9012527
OBD repair	American model	Chevrolet	95160	9012528
OBD repair	American model	Chevrolet	95160	9018740(Types of 1)
OBD repair	American model	Chevrolet	95160	9018740(Types of 2)
OBD repair	American model	Chevrolet	95160	9024821
OBD repair	American model	Chevrolet	95160	9029660
OBD repair	American model	Chevrolet	95160	9033235
OBD repair	American model	Chevrolet	95160	9035025
OBD repair	American model	Chevrolet	95160	9039025
OBD repair	American model	Chevrolet	95160	9070418
OBD repair	American model	Chevrolet	95160	96940365
OBD repair	American model	Chevrolet	95160	Music -9029659
OBD repair	American model	Chevrolet	95160	Music style -9029659
OBD repair	American model	Chevrolet	95320	96866798
OBD repair	European model	Audi	95640	8E0959655G
OBD repair	European model	Audi	95640	8K0959655J
OBD repair	European model	Audi	95640	4FD959655
OBD repair	European model	Audi	95160	4F0959655B
OBD repair	European model	Audi	95160	4L0959655C
OBD repair	European model	BMW	25128	65779118749
OBD repair	European model	BMW	95128	611158000K
OBD repair	European model	BMW	95640	65779184432-01
OBD repair	European model	Peugeot	95080	206-9661872980

OBD repair	European model	Peugeot	95080	307-9661872980
OBD repair	European model	Peugeot	95080	600237200
OBD repair	European model	Peugeot	95080	9652712180
OBD repair	European model	Peugeot	95080	9660349980
OBD repair	European model	Peugeot	95320	9653493380
OBD repair	European model	Peugeot	95320	9654491180
OBD repair	European model	Peugeot	95320	9654491280
OBD repair	European model	Peugeot	95320	9659847880
OBD repair	European model	Peugeot	95320	9665355680
OBD repair	European model	Peugeot	95320	9673626980
OBD repair	European model	Peugeot	95320	9673628880
OBD repair	European model	Peugeot	95320	9673786980
OBD repair	European model	Peugeot	95320	9673787080
OBD repair	European model	Peugeot	95320	9802958480
OBD repair	European model	Peugeot	95640	9678656880
OBD repair	European model	public	24C08	6Q0909601E
OBD repair	European model	public	24C08	6Q0909601E(With switch)
OBD repair	European model	public	24C08	6Q0909601F
OBD repair	European model	public	24C08	6Q0909601F(With switch)
OBD repair	European model	public	95160	Touran -1T0909605D
OBD repair	European model	public	95160	Tiqvan -1T0909605D
OBD repair	European model	public	95320	65D959655A
OBD repair	European model	public	95320	65D959655B
OBD repair	European model	public	95320	6R0959655
OBD repair	European model	public	95320	6RD959655
OBD repair	European model	public	95320	6RD959655D
OBD repair	European model	public	95320	6RD959655F
OBD repair	European model	public	95320	Bora -6R0959655B
OBD repair	European model	public	95320	Bora -6RD959655A
OBD repair	European model	public	95320	Bora -6RD959655B
OBD repair	European model	public	95320	Bora -6RD959655C
OBD repair	European model	public	95320	Lavender -6R0959655B

OBD repair	European model	public	95320	Lavender - 6RD959655A
OBD repair	European model	public	95320	Lavender - 6RD959655B
OBD repair	European model	public	95320	Lavender - 6RD959655C
OBD repair	European model	public	95640	3CD959655
OBD repair	European model	public	95640	3CD959655A
OBD repair	European model	public	95640	5ND959655
OBD repair	European model	public	95640	CC-5ND959655A
OBD repair	European model	public	95640	Magotan - 5ND959655B
OBD repair	European model	public	95640	Magotan - 5ND959655C
OBD repair	European model	public	95640	Tiguan -5ND959655A
OBD repair	European model	public	95640	Tiguan -5ND959655B
OBD repair	European model	public	95640	Tiguan -5ND959655C
OBD repair	European model	Fiat	24C04	46765164
OBD repair	European model	Fiat	24C04	46765165
OBD repair	European model	Fiat	24C04	51718981
OBD repair	European model	Fiat	95080	5WK43823
OBD repair	European model	Renault	95080	600-63-95-00
OBD repair	European model	Renault	95160	605-49-01-00
OBD repair	European model	Renault	95320	98820-JY10A
OBD repair	European model	Land Rover	95080	5WK4-3117- 22050312
OBD repair	European model	Land Rover	95320	9H52-14D374-AD
OBD repair	European model	Opel	95160	13-227-920
OBD repair	European model	Opel	95160	13-246-041
OBD repair	European model	Opel	95160	13-246-046
OBD repair	European model	Opel	95160	13-251-081
OBD repair	European model	Opel	95160	13-288-174
OBD repair	European model	Skoda	95320	6R0-959-655-B
OBD repair	European model	Skoda	95320	6RD-959-655
OBD repair	European model	Skoda	95320	6RD-959-655-A
OBD repair	European model	Citroen	25320	610-79-95-00

OBD repair	European model	Citroen	93C66	601-95-17-00
OBD repair	European model	Citroen	93C66	601-95-18-00
OBD repair	European model	Citroen	95080	600-23-76-00
OBD repair	European model	Citroen	95080	9652276980
OBD repair	European model	Citroen	95080	9659111980
OBD repair	European model	Citroen	95080	9661872980
OBD repair	European model	Citroen	95080	ZQ00731180-5WK43855
OBD repair	European model	Citroen	95080	ZQ00731280-5WK43856
OBD repair	European model	Citroen	95080	ZQ00811180-5WK44152
OBD repair	European model	Citroen	95080	ZQ00811280-5WK44153
OBD repair	European model	Citroen	95080	ZQ00885680-5WK44325
OBD repair	European model	Citroen	95080	ZQ00885780
OBD repair	European model	Citroen	95320	4YC94953
OBD repair	European model	Citroen	95320	9662643980
OBD repair	European model	Citroen	95320	9665354880
OBD repair	European model	Citroen	95320	9665355080
OBD repair	European model	Citroen	95320	9665495580
OBD repair	European model	Citroen	95320	9665495680
OBD repair	European model	Citroen	95320	9673624880
OBD repair	European model	Citroen	95320	9673787480
OBD repair	European model	Citroen	95320	9676739380
OBD repair	European model	Citroen	95320	9676739480
OBD repair	European model	Citroen	95320	9805062680
OBD repair	European model	Citroen	95640	9804502280
OBD repair	Asian model	Honda	24C01A	77960-S3N-N93
OBD repair	Asian model	Honda	24C01A	77960-S84-A86
OBD repair	Asian model	Honda	24C01A	77960-SV4-A95
OBD repair	Asian model	Honda	25320	77960-SDA-Y614-M1
OBD repair	Asian model	Honda	25320	77960-SDA-Y615-M1
OBD repair	Asian model	Honda	25320	77960-SDA-Y630-M1
OBD repair	Asian model	Honda	25320	77960-SDA-Y631-M1

OBD repair	Asian model	Honda	25320	77960-SDA-Y840-M1
OBD repair	Asian model	Honda	25320	77960-SDA-Y915-M1
OBD repair	Asian model	Honda	25320	77960-SDA-Y930-M1
OBD repair	Asian model	Honda	25320	SDA-A615-M1(Accord CM5)
OBD repair	Asian model	Honda	93C46	77960-SV4-308
OBD repair	Asian model	Honda	93C66	77960-SFJ-W910-M2
OBD repair	Asian model	Honda	93C86	77960-TF0-H420-M3
OBD repair	Asian model	Honda	93C86	77960-TF0-H620-M3
OBD repair	Asian model	Honda	93C86	77960-SLE-H012-M3
OBD repair	Asian model	Honda	93C86	77960-SLE-H812-M3
OBD repair	Asian model	Honda	93C86	77960-TF0-H621-M3
OBD repair	Asian model	Honda	93C86	77960-TF0-H820-M3
OBD repair	Asian model	Honda	93C86	77960-TM0-H421-M3
OBD repair	Asian model	Honda	93C86	77960-TM0-H821-M3
OBD repair	Asian model	Honda	93C86	77960-TM0-X621-M3
OBD repair	Asian model	Honda	95320	77960-S9A-Y412-M1
OBD repair	Asian model	Honda	95320	77960-S9A-Y413-M1
OBD repair	Asian model	Honda	95320	77960-S9A-Y414-M1
OBD repair	Asian model	Honda	95320	77960-T6P-H411-M1
OBD repair	Asian model	Honda	95320	77960-T6P-H611-M1
OBD repair	Asian model	Honda	95320	77960-TR0-H714-M1
OBD repair	Asian model	Honda	95320	77960-TR0-H715-M1
OBD repair	Asian model	Honda	95320	77960-TR0-H720-M1
OBD repair	Asian model	Honda	95320	77960-TS6-H711-M1
OBD repair	Asian model	Honda	95640	77960-TC0-H211-M
OBD repair	Asian model	Honda	95640	77960-SNA-H010-M1
OBD repair	Asian model	Honda	95640	77960-SNA-H020-M1
OBD repair	Asian model	Honda	95640	77960-SNA-H211-M1
OBD repair	Asian model	Honda	95640	77960-SNA-H222-M1
OBD repair	Asian model	Honda	95640	77960-SNA-H811-M1
OBD repair	Asian model	Honda	95640	77960-SNA-H821-M1
OBD repair	Asian model	Honda	95640	77960-SNA-H822-M1
OBD repair	Asian model	Honda	95640	77960-SNA-H830-M1
OBD repair	Asian model	Honda	95640	77960-SWA-H010-M4
OBD repair	Asian model	Honda	95640	77960-SWA-H213-M4

OBD repair	Asian model	Honda	95640	77960-SWA-H811-M4
OBD repair	Asian model	Honda	95640	77960-SWA-H812-M4
OBD repair	Asian model	Honda	95640	77960-SYJ-H111-M4
OBD repair	Asian model	Honda	95640	77960-T0A-H911-M4
OBD repair	Asian model	Honda	95640	77960-T0A-H912-M4
OBD repair	Asian model	Honda	95640	77960-T0A-H920-M4
OBD repair	Asian model	Honda	95640	77960-T2A-H911-M1
OBD repair	Asian model	Honda	95640	77960-T4N-H711-M1
OBD repair	Asian model	Honda	95640	77960-T5A-H611-M1
OBD repair	Asian model	Honda	95640	77960-TC0-H012-M1
OBD repair	Asian model	Honda	95640	77960-TC0-H212-M1
OBD repair	Asian model	Honda	95640	77960-TFC-H910-M4
OBD repair	Asian model	Honda	95640	77960-TP5-H111-M1
OBD repair	Asian model	Toyota	25040	89170-0D360
OBD repair	Asian model	Toyota	25040	89170-0D500
OBD repair	Asian model	Toyota	93C46	89170-30060
OBD repair	Asian model	Toyota	93C56	89170-02A90
OBD repair	Asian model	Toyota	93C66	89170-06340
OBD repair	Asian model	Toyota	93C66	89170-0D400
OBD repair	Asian model	Toyota	93C66	89170-0E040
OBD repair	Asian model	Toyota	93C66	89170-0P010
OBD repair	Asian model	Toyota	93C66	89170-0P012
OBD repair	Asian model	Toyota	93C66	89170-0R030
OBD repair	Asian model	Toyota	93C66	89170-0R040
OBD repair	Asian model	Toyota	93C66	89170-0R041
OBD repair	Asian model	Toyota	93C66	89170-0R050
OBD repair	Asian model	Toyota	93C66	89170-42230
OBD repair	Asian model	Toyota	93C66	89170-42640
OBD repair	Asian model	Toyota	93C66	89170-48260
OBD repair	Asian model	Toyota	93C66	89170-60170
OBD repair	Asian model	Toyota	93C66	89170-60650
OBD repair	Asian model	Toyota	93C66	LS460-89170-50260
OBD repair	Asian model	Toyota	LC56	89170-02700
OBD repair	Asian model	Toyota	93LC56	89170-02430
OBD repair	Asian model	Toyota	93LC56	89170-06190
OBD repair	Asian model	Toyota	93LC56	89170-06330

OBD repair	Asian model	Toyota	93LC56	89170-0N010
OBD repair	Asian model	Toyota	93LC56	89170-0N020
OBD repair	Asian model	Toyota	93LC56	89170-33260
OBD repair	Asian model	Toyota	93LC56	89170-60110
OBD repair	Asian model	Toyota	93LC56	89170-60200
OBD repair	Asian model	Toyota	93LC66	89170-02770
OBD repair	Asian model	Toyota	93LC66	89170-06430
OBD repair	Asian model	Toyota	93LC66	ES350-89170-33560
OBD repair	Asian model	Toyota	95160	89170-02F40
OBD repair	Asian model	Toyota	95160	89170-0D650
OBD repair	Asian model	Toyota	95160	89170-0F200
OBD repair	Asian model	Suzuki	24C16	38910-77J00
OBD repair	Asian model	Suzuki	25160	38910-C14B0
OBD repair	Asian model	Suzuki	93C46	38910-65D1
OBD repair	Asian model	Suzuki	93C56	38910-82J0
OBD repair	Asian model	Suzuki	95080	38910-59J70
OBD repair	Asian model	Suzuki	95160	38910-56K00
OBD repair	Asian model	Suzuki	95160	38910-56K01-000
OBD repair	Asian model	Suzuki	95160	38910-56K02-000
OBD repair	Asian model	Suzuki	95160	38910-56K10-000
OBD repair	Asian model	Suzuki	95160	38910-56K11-000
OBD repair	Asian model	Suzuki	95160	38910-56K12
OBD repair	Asian model	Suzuki	95160	38910-56K12-000
OBD repair	Asian model	Suzuki	95160	38910-56K21-000
OBD repair	Asian model	Suzuki	95160	38910-77J00-000
OBD repair	Asian model	Suzuki	95160	38910-77J01
OBD repair	Asian model	Suzuki	95160	38910-77J01-000
OBD repair	Asian model	Suzuki	95160	38910-77J02-000
OBD repair	Asian model	Suzuki	95160	38910-77J20-000
OBD repair	Asian model	Suzuki	95160	38910-C1100
OBD repair	Asian model	Mazda	24C04	B30K-57-K30-B-5F24B
OBD repair	Asian model	Mazda	24C04	C175-57-K30-B-5J11B
OBD repair	Asian model	Mazda	24C04	C176-57-K30-B-3G09A

OBD repair	Asian model	Mazda	24C04	C176-57-K30-B-4A13E
OBD repair	Asian model	Mazda	24C04	C176-57-K30-B-6H21A
OBD repair	Asian model	Mazda	93C86	W2T80271
OBD repair	Asian model	Mazda	95080	BP4-M57-K30
OBD repair	Asian model	Mazda	95080	BR9-N57-K30
OBD repair	Asian model	Mazda	95080	FA11-57-K30-M1
OBD repair	Asian model	Mazda	95080	FA11-57-K30-M2
OBD repair	Asian model	Mazda	95080	GJ6A-57-K30C
OBD repair	Asian model	Mazda	95080	GJ6A-57-K30D
OBD repair	Asian model	Mazda	95080	GJ6R-57-K30D
OBD repair	Asian model	Mazda	95080	HMCA-57-K30
OBD repair	Asian model	Mazda	95080	Familia 323-HMCA-57-K30-M1A
OBD repair	Asian model	Mazda	95080	Haifuxing -HMCA-57-K30-M1A
OBD repair	Asian model	Mazda	95080	HMFA-57-K30
OBD repair	Asian model	Mazda	95160	FA03-57-K30-M2
OBD repair	Asian model	Mazda	95160	L20-657-K30
OBD repair	Asian model	Mazda	95320	DG80-57-K30-A
OBD repair	Asian model	Mazda	95320	DG80-57-K30-B
OBD repair	Asian model	Mazda	95320	EH62-57-K30A-K0273
OBD repair	Asian model	Mazda	95320	G31A-57-K30B
OBD repair	Asian model	Mazda	95320	G31F-57-K30A
OBD repair	Asian model	Mazda	95640	BFF4-57-K30
OBD repair	Asian model	Mazda	95640	BHL6-57-K30-A
OBD repair	Asian model	Mazda	95640	GS1D-57K30
OBD repair	Asian model	Mazda	95640	GS1D-57K30B
OBD repair	Asian model	Mazda	95640	KR12-57K30
OBD repair	Asian model	idea	93C56	77960-S0L-H410-M2
OBD repair	Asian model	Acura	93C86	77960-STX-H010-M1
OBD repair	Asian model	Kia	25256	95910-1X000
OBD repair	Asian model	Kia	25320	95910-0S600
OBD repair	Asian model	Kia	25320	95910-2F100

OBD repair	Asian model	Kia	25320	95910-2F200
OBD repair	Asian model	Kia	25320	95910-4T000
OBD repair	Asian model	Kia	25320	95910-4T250
OBD repair	Asian model	Kia	25640	95910-0C300
OBD repair	Asian model	Kia	25640	95910-0C400
OBD repair	Asian model	Kia	25640	95910-1G000
OBD repair	Asian model	Kia	95080	95960-3E100
OBD repair	Asian model	Kia	95128	95910-4X000
OBD repair	Asian model	Kia	95128	95910-B5000
OBD repair	Asian model	Kia	95128	95910-B5100
OBD repair	Asian model	Kia	95256	95910-1M000
OBD repair	Asian model	Kia	95256	95910-4M300
OBD repair	Asian model	Kia	95256	95910-4M400
OBD repair	Asian model	Kia	95256	95910-4M450
OBD repair	Asian model	Kia	95256	95910-D1400
OBD repair	Asian model	Kia	95320	95910-0S500
OBD repair	Asian model	Kia	95320	95910-4T200
OBD repair	Asian model	Kia	95640	95910-2X000
OBD repair	Asian model	Nissan	93C46	28556-8M52E
OBD repair	Asian model	Nissan	93C46	28556-8M605
OBD repair	Asian model	Nissan	93C46	285569S60A
OBD repair	Asian model	Nissan	93C46	5E910
OBD repair	Asian model	Nissan	93C46	5E911
OBD repair	Asian model	Nissan	93C46	7M605
OBD repair	Asian model	Nissan	93C46	7M60E
OBD repair	Asian model	Nissan	93C46	VK000
OBD repair	Asian model	Nissan	93C46	Aeolus bluebird - 9S600
OBD repair	Asian model	Nissan	93C46	Paladin -9S600
OBD repair	Asian model	Nissan	93C56	28556-EW32E
OBD repair	Asian model	Nissan	93C56	28556-EW33E
OBD repair	Asian model	Nissan	93C56	285561HD1A
OBD repair	Asian model	Nissan	93C56	285561YP0A
OBD repair	Asian model	Nissan	93C56	28556CJ00A
OBD repair	Asian model	Nissan	93C56	28556CJ00D
OBD repair	Asian model	Nissan	93C56	28556JX03B

OBD repair	Asian model	Nissan	93C56	98820-3L400
OBD repair	Asian model	Nissan	93C56	988201AH3A
OBD repair	Asian model	Nissan	95160	28556-JC20A
OBD repair	Asian model	Nissan	95160	28556-1DE0A
OBD repair	Asian model	Nissan	95160	28556-1DE0B
OBD repair	Asian model	Nissan	95160	28556-2FJ0A
OBD repair	Asian model	Nissan	95160	28556-3ZA0A
OBD repair	Asian model	Nissan	95160	28556-JC20B
OBD repair	Asian model	Nissan	95160	28556-JE20A
OBD repair	Asian model	Nissan	95160	28556-JE40B
OBD repair	Asian model	Nissan	95160	98820-1DF0A
OBD repair	Asian model	Nissan	95160	98820-1DF0B
OBD repair	Asian model	Nissan	95160	98820-3ZB0A
OBD repair	Asian model	Nissan	95160	98820-JE30A
OBD repair	Asian model	Nissan	95160	98820-JE50A
OBD repair	Asian model	Nissan	95160	98820-JE50B
OBD repair	Asian model	Nissan	95160	98820-JN30B
OBD repair	Asian model	Nissan	95160	Scorpio -98820-JN30A
OBD repair	Asian model	Nissan	95160	Hacker -98820-JN30A
OBD repair	Asian model	Nissan	LC56	98820-EX70A
OBD repair	Asian model	Nissan	LC56	28556-EW32C
OBD repair	Asian model	Nissan	LC56	6EU10A
OBD repair	Asian model	Nissan	LC56	98820-1NC0A
OBD repair	Asian model	Nissan	LC56	9W100
OBD repair	Asian model	Nissan	LC56	9W10E
OBD repair	Asian model	Nissan	LC56	EW300
OBD repair	Asian model	Nissan	LC56	EW32D
OBD repair	Asian model	Mitsubishi	25160	8635A154
OBD repair	Asian model	Mitsubishi	25160	8635A183L
OBD repair	Asian model	Mitsubishi	25160	MN141170
OBD repair	Asian model	Mitsubishi	25160	Golan -MN141536
OBD repair	Asian model	Mitsubishi	25160	Outlander -MN141536
OBD repair	Asian model	Mitsubishi	25640	8635A055
OBD repair	Asian model	Mitsubishi	25640	P8635A062
OBD repair	Asian model	Mitsubishi	25640	P8635A206

OBD repair	Asian model	Mitsubishi	25640	P8635A207
OBD repair	Asian model	Mitsubishi	25640	P8635A247
OBD repair	Asian model	Mitsubishi	25640	TCJME1368J
OBD repair	Asian model	Mitsubishi	25640	TGBMH161000945
OBD repair	Asian model	Mitsubishi	25640	TGBMH348901005
OBD repair	Asian model	Mitsubishi	93C46	MR268-157
OBD repair	Asian model	Mitsubishi	93C56	MB953-175
OBD repair	Asian model	Mitsubishi	93C56	MN141-499-DPB
OBD repair	Asian model	Mitsubishi	93C56	W2T65271
OBD repair	Asian model	Mitsubishi	93C66	8635A160
OBD repair	Asian model	Mitsubishi	93C76	8635A123
OBD repair	Asian model	Mitsubishi	93LC56	MN141-499-DPB-2
OBD repair	Asian model	Mitsubishi	95640	8635A215
OBD repair	Asian model	Mitsubishi	95640	8635A303
OBD repair	Asian model	Mitsubishi	95640	TGBMH293902189
OBD repair	Asian model	Subaru	93C56	98221SA140
OBD repair	Asian model	Subaru	93C86	98221SC030
OBD repair	Asian model	Subaru	93C86	98221XA05A
OBD repair	Asian model	modern	25256	95910-B3300
OBD repair	Asian model	modern	25320	95910-2Z000
OBD repair	Asian model	modern	25320	95910-2Z200
OBD repair	Asian model	modern	25640	95910-0M000
OBD repair	Asian model	modern	25640	95910-0Q000
OBD repair	Asian model	modern	25640	95910-0R100
OBD repair	Asian model	modern	25640	95910-1E000
OBD repair	Asian model	modern	25640	95910-1Z000
OBD repair	Asian model	modern	95080	95910-09100
OBD repair	Asian model	modern	95080	95910-26200
OBD repair	Asian model	modern	95080	95910-26600
OBD repair	Asian model	modern	95080	95910-3D000
OBD repair	Asian model	modern	95080	95910-3D100
OBD repair	Asian model	modern	95080	95910-3D200
OBD repair	Asian model	modern	95128	95910-0U100
OBD repair	Asian model	modern	95128	95910-4V100
OBD repair	Asian model	modern	95256	95910-4Q100
OBD repair	Asian model	modern	95256	95910-4Q300

OBD repair	Asian model	modern	95320	95910-2B170
OBD repair	Asian model	modern	95320	95910-2B200
OBD repair	Asian model	modern	95320	95910-3J200
OBD repair	Asian model	modern	95640	95910-0R200
OBD repair	Asian model	modern	95640	95910-2B180
OBD repair	Asian model	modern	95640	95910-3M250
OBD repair	Asian model	Infiniti	93C56	988201NC0A
OBD repair	Asian model	Infiniti	LC56	988201NC1A
OBD repair	China model	Baojun 630	95320	24537297/5WK44411
OBD repair	China model	Beijing Auto	25160	B6260180AA
OBD repair	China model	Beijing Auto	95160	113658010
OBD repair	China model	Beiqi	95160	58240100-B01
OBD repair	China model	Beiqi	95160	5824100-B21-000
OBD repair	China model	BYD	24C02	3658-1A
OBD repair	China model	BYD	24C04	3569-1C
OBD repair	China model	BYD	24C04	3658-1B
OBD repair	China model	BYD	24C04	3658100-A1
OBD repair	China model	BYD	24C04	3658100-A2
OBD repair	China model	BYD	24C04	LK-3658100B
OBD repair	China model	BYD	24C16	3658100-C1
OBD repair	China model	BYD	24C16	3658100A
OBD repair	China model	BYD	24C16	3658100B
OBD repair	China model	BYD	24C16	5A-3658100
OBD repair	China model	BYD	24C16	5A-3658100B
OBD repair	China model	BYD	24C16	6AP-3658100
OBD repair	China model	BYD	24C16	EG-3658100
OBD repair	China model	BYD	24C16	F6-3658100
OBD repair	China model	BYD	24C16	L3-3658100
OBD repair	China model	Changhe	93C46	38910-75FA0
OBD repair	China model	Changhe	95080	38910-59J70-000
OBD repair	China model	Dongfeng	25160	28556-2ZS70
OBD repair	China model	Dongfeng	25160	82MK-14150
OBD repair	China model	Dongfeng	95080	28556W6600
OBD repair	China model	Dongfeng	95080	B-5824050
OBD repair	China model	Dongfeng	95080	B-5824150
OBD repair	China model	Dongfeng	95080	U410010JB0100

OBD repair	China model	Dongfeng	95080	U410010JB0101
OBD repair	China model	Dongfeng	95080	U410010JB0107
OBD repair	China model	Dongfeng	95160	28556-2ZS00
OBD repair	China model	Dongfeng	95160	B12-5824010
OBD repair	China model	Dongfeng	95160	B20-5824010
OBD repair	China model	Dongfeng	95160	BX5A-5824020
OBD repair	China model	Dongfeng	95320	BX5A-5824010
OBD repair	China model	southeast	93C66	W2T65672-8635A159
OBD repair	China model	southeast	95080	5WK44161
OBD repair	China model	southeast	95080	SW803814
OBD repair	China model	southeast	95080	SW803815
OBD repair	China model	southeast	95080	Ling -SW806408
OBD repair	China model	southeast	95080	SW806408/J3858172
OBD repair	China model	southeast	95320	J3858207
OBD repair	China model	southeast	95320	J3858209
OBD repair	China model	southeast	95320	J3858210
OBD repair	China model	Guangqi Chuanqi	95640	222426-147
OBD repair	China model	Hafei	93C56	MR551-800
OBD repair	China model	Seahorse	25320	SA00-57-K30M1
OBD repair	China model	Seahorse	95080	FA02-57-K30M1
OBD repair	China model	Seahorse	95080	FA11-57-K30-M2
OBD repair	China model	Seahorse	95080	HMFA-A57-30
OBD repair	China model	Seahorse	95080	MA10-57-K30M1
OBD repair	China model	Seahorse	95080	MA20-57-K30M1
OBD repair	China model	Seahorse	95160	FA30-57-K30-M2
OBD repair	China model	Seahorse	95160	FE12-57-K30
OBD repair	China model	Seahorse	95160	PA10-57-K30M1(Types of 1)
OBD repair	China model	Seahorse	95160	PA10-57-K30M1(Types of 2)
OBD repair	China model	Seahorse	95320	FA03-57-K30M1
OBD repair	China model	Seahorse	95320	FA13-57-K30M1
OBD repair	China model	Seahorse	95320	MA30-57-K30M1
OBD repair	China model	Maple	25160	A0200059796
OBD repair	China model	Huatai	95320	36581000S09
OBD repair	China model	auspicious	25160	1703533B

OBD repair	China model	auspicious	25160	611286500
OBD repair	China model	auspicious	25160	620432200
OBD repair	China model	auspicious	25160	620432400
OBD repair	China model	auspicious	25160	A0200030180
OBD repair	China model	auspicious	25160	A020005158V
OBD repair	China model	auspicious	25160	A020006311N
OBD repair	China model	auspicious	25160	A020011368V
OBD repair	China model	auspicious	25160	A020053633W
OBD repair	China model	auspicious	25160	A020082830X
OBD repair	China model	auspicious	25160	A0201001221
OBD repair	China model	auspicious	25160	A020102343P
OBD repair	China model	auspicious	25160	A020111137Q
OBD repair	China model	auspicious	25160	J3858048
OBD repair	China model	auspicious	95040	1709536
OBD repair	China model	auspicious	95160	0285-010
OBD repair	China model	auspicious	95160	1703577(Types of 1)
OBD repair	China model	auspicious	95160	1703577(Types of 2)
OBD repair	China model	auspicious	95160	1709516(Types of 1)
OBD repair	China model	auspicious	95160	1709516(Types of 2)
OBD repair	China model	auspicious	95160	611286501
OBD repair	China model	auspicious	95160	620432200B
OBD repair	China model	auspicious	95160	620432400B
OBD repair	China model	auspicious	95160	625564900
OBD repair	China model	auspicious	95160	A020024044Q
OBD repair	China model	auspicious	95160	A020089989J
OBD repair	China model	auspicious	95640	222425-127
OBD repair	China model	auspicious	95640	222426
OBD repair	China model	auspicious	95640	611172500
OBD repair	China model	auspicious	95640	611172500D
OBD repair	China model	auspicious	95640	611172600
OBD repair	China model	auspicious	95640	611172600D
OBD repair	China model	Jianghuai	95080	5824901U7150
OBD repair	China model	Jianghuai	95080	5824901U8010
OBD repair	China model	Jianghuai	95080	5824901U8015
OBD repair	China model	Jianghuai	95160	5824901U1010

OBD repair	China model	Jianghuai	95160	5824901U2010(Types of 1)
OBD repair	China model	Jianghuai	95160	5824901U2010(Types of 2)
OBD repair	China model	Jianghuai	95160	5824901U2011(Types of 1)
OBD repair	China model	Jianghuai	95160	5824901U2011(Types of 2)
OBD repair	China model	Jianghuai	95160	5824901U7101
OBD repair	China model	Jianghuai	95160	5824901U7101B
OBD repair	China model	Jiangling	25160	3414070-B01
OBD repair	China model	Jiangling	25160	5820011LC/J3858107
OBD repair	China model	Jiangling	25160	J3858106
OBD repair	China model	Jiangling	25320	J3858126
OBD repair	China model	Gold cup	95080	3414070-F01/J3858038
OBD repair	China model	Gold cup	95080	605726000
OBD repair	China model	Gold cup	95080	3023317/J3858022
OBD repair	China model	Gold cup	95080	3023318/J3858023
OBD repair	China model	Lifan	25160	J3858044/L3658100A1
OBD repair	China model	Lifan	25160	LAX3658100D1
OBD repair	China model	Lifan	25160	other
OBD repair	China model	Lifan	95080	F3658100
OBD repair	China model	Lifan	95160	B3658100(Types of 1)
OBD repair	China model	Lifan	95160	B3658100(Types of 2)
OBD repair	China model	Lifan	95160	LAX3658100B1
OBD repair	China model	lotus	95080	PW851834
OBD repair	China model	lotus	95160	EC5824106N
OBD repair	China model	mg	25160	400000092
OBD repair	China model	mg	25640	10043844-05
OBD repair	China model	mg	25640	10043844-06
OBD repair	China model	mg	95080	609-90-97-00-AA
OBD repair	China model	mg	95080	610-39-64-00B

OBD repair	China model	mg	95080	610-40-05-00
OBD repair	China model	mg	95320	10001800
OBD repair	China model	mg	95640	10104454-01
OBD repair	China model	mg	95640	10104458-01
OBD repair	China model	Na Zhijie	95320	28556SU110
OBD repair	China model	Chery	25160	M11-36060VB
OBD repair	China model	Chery	25160	T11-3606011
OBD repair	China model	Chery	25160	T11-3606011BA
OBD repair	China model	Chery	25320	M11-3606010NB
OBD repair	China model	Chery	25640	M11-3606010
OBD repair	China model	Chery	95080	A21-3606010
OBD repair	China model	Chery	95160	A13-3606010GA
OBD repair	China model	Chery	95160	J52-3606010FL
OBD repair	China model	Chery	95160	J52-3658010
OBD repair	China model	Chery	95160	QQ6-A13-3606010
OBD repair	China model	Chery	95160	Storm clouds 2-A13-3606010
OBD repair	China model	Chery	95320	B21-3606010BB
OBD repair	China model	Chery	95320	T11-3606011PD
OBD repair	China model	Chery	95320	T21-3658070BA
OBD repair	China model	Roewe	25640	1004384405
OBD repair	China model	Roewe	95040	5001935406
OBD repair	China model	Roewe	95040	5001935806
OBD repair	China model	Roewe	95080	1000395301
OBD repair	China model	Roewe	95080	10008700
OBD repair	China model	Roewe	95080	YWC91161
OBD repair	China model	Roewe	95320	1000180001
OBD repair	China model	Roewe	95640	1010078401
OBD repair	China model	Dawn	25160	J3858226
OBD repair	China model	Ssangyong	95080	86250-08121
OBD repair	China model	Ssangyong	95080	86250-09041
OBD repair	China model	Ssangyong	95080	86251-31010
OBD repair	China model	Ssangyong	95080	86251-31040
OBD repair	China model	Tianjin FAW	25160	89170-52K70
OBD repair	China model	Tianjin FAW	25160	89170-TBA00
OBD repair	China model	Tianjin FAW	25160	89170-TKA00

OBD repair	China model	Wuling	25160	24557699
OBD repair	China model	Wuling	95080	5496016
OBD repair	China model	Wuling	95080	24519199
OBD repair	China model	Wuling	95160	24557700
OBD repair	China model	FAW Daihatsu	93C56	89170-BZ070
OBD repair	China model	FAW Daihatsu	93C56	89170-BZ080
OBD repair	China model	Changan	25160	3414070-Q01
OBD repair	China model	Changan	25160	3414070-W01
OBD repair	China model	Changan	93C56	38910-843A0S
OBD repair	China model	Changan	95080	3402200-C01
OBD repair	China model	Changan	95080	3414070-A01
OBD repair	China model	Changan	95080	3414070-F01
OBD repair	China model	Changan	95080	3414070-F02
OBD repair	China model	Changan	95080	38910-C80E00-000
OBD repair	China model	Changan	95160	3414070-K02
OBD repair	China model	Changan	95160	3414070-W01-AA
OBD repair	China model	Changan	95160	38910-62L00
OBD repair	China model	Changan	95320	3414700-N03
OBD repair	China model	Changan	95320	3414700-U03(Without side airbag)
OBD repair	China model	Changan	95320	3414700-U03(Side airbag)
OBD repair	China model	Changan	95640	BKC3-57K30
OBD repair	China model	Great Wall	25160	3658110-J08
OBD repair	China model	Great Wall	25160	3658110XKZ16A
OBD repair	China model	Great Wall	95080	3658110-M16-B1
OBD repair	China model	Great Wall	95080	3658110-Y08
OBD repair	China model	Great Wall	95080	3658110A-G08
OBD repair	China model	Great Wall	95080	3658110A-V08
OBD repair	China model	Great Wall	95080	3658120-P00
OBD repair	China model	Great Wall	95080	3658120-S08
OBD repair	China model	Great Wall	95080	3658120-Y08
OBD repair	China model	Great Wall	95080	3658130-S08
OBD repair	China model	Great Wall	95080	3658160-K00
OBD repair	China model	Great Wall	95160	3658100XS56XA
OBD repair	China model	Great Wall	95160	3658110-J08-B

OBD repair	China model	Great Wall	95160	3658110A-J08
OBD repair	China model	Great Wall	95160	3658110XJZ08A
OBD repair	China model	Great Wall	95160	3658110XJZ08B
OBD repair	China model	Great Wall	95160	3658110XJZ08C
OBD repair	China model	Great Wall	95160	3658110XKZ16B
OBD repair	China model	Great Wall	95160	3658120-S08
OBD repair	China model	Great Wall	95160	3658120XKZ16B
OBD repair	China model	Great Wall	95160	3658120XKZ16C
OBD repair	China model	Great Wall	95160	3658130XS08XB
OBD repair	China model	Great Wall	95160	3658160-K18-B1
OBD repair	China model	Great Wall	95160	3658160-K84
OBD repair	China model	Great Wall	95320	3658110XSZ08A
OBD repair	China model	Great Wall	95320	3658160XK88XA
OBD repair	China model	Great Wall	95640	3658160AK80XA
OBD repair	China model	Changfeng Cheetah	25160	CA110182
OBD repair	China model	Changfeng Cheetah	25160	CA800216
OBD repair	China model	Changfeng Cheetah	25160	J3858059
OBD repair	China model	Changfeng Cheetah	95080	CH800017
OBD repair	China model	Changfeng Cheetah	95080	CH800307
OBD repair	China model	Changfeng Cheetah	95160	CA800278
OBD repair	China model	China FAW	95040	5CA0-57K30
OBD repair	China model	China FAW	95040	FA01-57K30-A
OBD repair	China model	China FAW	95040	FA03-57K30
OBD repair	China model	China FAW	95040	FA03-57K30-A
OBD repair	China model	Zhonghua	25160	3084107
OBD repair	China model	Zhonghua	25160	3091819
OBD repair	China model	Zhonghua	25160	J3858028
OBD repair	China model	Zhonghua	25160	Junjie -3491017
OBD repair	China model	Zhonghua	25160	Zunchi -3491017
OBD repair	China model	Zhonghua	95080	3051183
OBD repair	China model	Zhonghua	95080	3051187
OBD repair	China model	Zhonghua	95080	3101850
OBD repair	China model	Zhonghua	95080	3291018
OBD repair	China model	Zhonghua	95080	FRV 3491027
OBD repair	China model	Zhonghua	95320	J3858214
OBD repair	China model	Zhonghua	95320	J3858232

OBD repair	China model	Zhonghua	95320	J3858233
OBD repair	China model	ZTE	25160	3685010-0000
OBD repair	China model	Zhongtai	25160	3658010-06
OBD repair	China model	Zhongtai	95160	3658010-A01
OBD repair	China model	Zhongtai	95160	3658010BA-A01
Beijing Hyundai	ix25(GC)	2014-2016	G 1.6 MPI	
Beijing Hyundai	ix25(GC)	2014-2016	G 2.0 MPI	
Beijing Hyundai	SONATA Hybrid (LFCHEV)	2016	G 2.0 HEV	
Beijing Hyundai	Sonata (LFC)	2015-2016	G 2.0 MPI	
Beijing Hyundai	Sonata (LFC)	2015-2016	G 2.4 GDI	
Beijing Hyundai	Sonata (LFC)	2015-2016	G 1.6T GDI	
Beijing Hyundai	Sonata (YFC)	2011-2016	G 2.0 MPI	
Beijing Hyundai	New winda (DMC)	2012-2016	G 2.0 GDI	
Beijing Hyundai	New winda (DMC)	2012-2016	G 2.4 GDI	
Beijing Hyundai	New Tucson (TLC)	2015-2016	G 1.6 GDI	
Beijing Hyundai	New Tucson (TLC)	2015-2016	G 2.0 GDI	
Beijing Hyundai	Lead (ADC)	2016	G 1.6 MPI	
Beijing Hyundai	Lead (ADC)	2016	G 1.6 GDI	
Beijing Hyundai	Lead (ADC)	2016	G 1.4 GDI	
Beijing Hyundai	Name map (CF)	2016	G 2.0 MPI	
Beijing Hyundai	Name map (CF)	2016	G 1.8 MPI	
Beijing Hyundai	Name map (CF)	2016	G 1.6 GDI	
Beijing Hyundai	Name map (CF)	2014-2015	G 2.0 MPI	
Beijing Hyundai	Name map (CF)	2014-2015	G 1.8 MPI	

OBD repair General pu Seo 5490636
OBD repair Audi 4B0959655 Clear collision record
OBD repair Audi 4B0959655 Clear ECU Internal fault
OBD repair Audi 4B0959655 Clear collision record
OBD repair Audi 4B0959655 Clear ECU Internal fault
OBD repair Honda Fit
OBD repair Honda Sidi
OBD repair public VW5
OBD repair public VW6
OBD repair public VW3
OBD repair BYD Qin
OBD repair BYD Tang
OBD repair BYD new F3
OBD repair BYD F3
OBD repair BYD F3R
OBD repair BYD F3CK
OBD repair BYD F3DM
OBD repair BYD F0
OBD repair BYD F6
OBD repair BYD Si Rui
OBD repair BYD Speed sharp
OBD repair BYD M6
OBD repair BYD S6
OBD repair BYD S7
OBD repair BYD S8
OBD repair BYD L3
OBD repair BYD G3
OBD repair BYD G5
OBD repair BYD G6
OBD repair BYD E6A
OBD repair BYD E6B
OBD repair BYD E6Y

Adapter repair

OBD repair American nBuick 95080 9037091
OBD repair American nBuick 95080 1.01E+13
OBD repair American nBuick 95080 96406712
OBD repair American nBuick 95160 9042475(Types of 1)
OBD repair American nBuick 95160 9042475(Types of 2)
OBD repair American nBuick 95160 9012526
OBD repair American nBuick 95160 9012455
OBD repair American nBuick 95160 5499985
OBD repair American nFord 95080 4M5T-14B056
OBD repair American nFord 95080 4M5T-14B056-BJ
OBD repair American nFord 95080 4M5T-14B056-CA
OBD repair American nFord 95160 4S7T-14B056-AC
OBD repair American nFord 95160 5L84-14B321-DC
OBD repair American nFord 95160 6C1T-14B056-AE
OBD repair American nFord 95160 7M2T-14B056-AB
OBD repair American nFord 95160 7S7T-14B056-BB
OBD repair American nFord 95160 7S7T-14B056-BC
OBD repair American nFord 95160 8M5T-14B321-BD
OBD repair American nFord 95160 8M5T-14B321-BF
OBD repair American nFord 95160 9M5T-14B321-BA
OBD repair American nFord 95160 9M5T-14B321-BB
OBD repair American nFord 95160 9M5T-14B321-CA
OBD repair American nFord 95320 8V51-14B321-AG

OBD repair American nFord	95320 8V51-14B321-AH
OBD repair American nFord	95320 8V59-14B321-BA
OBD repair American nFord	95320 8V59-14B321-CA
OBD repair American nFord	95320 AA6T-14B321-AA
OBD repair American nFord	95320 AA6T-14B321-BA
OBD repair American nFord	95320 AA6T-14B321-CA
OBD repair American nFord	95320 AS7T-14B321-BA
OBD repair American nFord	95320 BS7T-14B32-AC
OBD repair American nFord	95320 BS7T-14B321-AC
OBD repair American nFord	95320 CM5T-14B321-CA
OBD repair American nFord	95640 DV4T-14B321-DG
OBD repair American nChrysler	95256 P68148040AA
OBD repair American nChevrolet	95080 24514261
OBD repair American nChevrolet	95080 24522270
OBD repair American nChevrolet	95080 24522720
OBD repair American nChevrolet	95080 24544647
OBD repair American nChevrolet	95080 96406534
OBD repair American nChevrolet	95080 96644507
OBD repair American nChevrolet	95080 P2406-10007
OBD repair American nChevrolet	95160 9012494
OBD repair American nChevrolet	95160 9012526
OBD repair American nChevrolet	95160 9012527
OBD repair American nChevrolet	95160 9012528
OBD repair American nChevrolet	95160 9018740(Types of 1)
OBD repair American nChevrolet	95160 9018740(Types of 2)
OBD repair American nChevrolet	95160 9024821
OBD repair American nChevrolet	95160 9029660
OBD repair American nChevrolet	95160 9033235
OBD repair American nChevrolet	95160 9035025
OBD repair American nChevrolet	95160 9039025
OBD repair American nChevrolet	95160 9070418
OBD repair American nChevrolet	95160 96940365
OBD repair American nChevrolet	95160 Music -9029659
OBD repair American nChevrolet	95160 Music style -9029659
OBD repair American nChevrolet	95320 96866798
OBD repair European rAudi	95640 8E0959655G
OBD repair European rAudi	95640 8K0959655J
OBD repair European rAudi	95640 4FD959655
OBD repair European rAudi	95160 4F0959655B
OBD repair European rAudi	95160 4L0959655C
OBD repair European rBMW	25128 6.58E+10
OBD repair European rBMW	95128 611158000K
OBD repair European rBMW	95640 65779184432-01
OBD repair European rPeugeot	95080 206-9661872980
OBD repair European rPeugeot	95080 307-9661872980
OBD repair European rPeugeot	95080 6E+08
OBD repair European rPeugeot	95080 9.65E+09
OBD repair European rPeugeot	95080 9.66E+09
OBD repair European rPeugeot	95320 9.65E+09
OBD repair European rPeugeot	95320 9.65E+09
OBD repair European rPeugeot	95320 9.65E+09
OBD repair European rPeugeot	95320 9.66E+09
OBD repair European rPeugeot	95320 9.67E+09
OBD repair European rPeugeot	95320 9.67E+09
OBD repair European rPeugeot	95320 9.67E+09
OBD repair European rPeugeot	95320 9.67E+09

OBD repair European r Peugeot	95320	9.67E+09
OBD repair European r Peugeot	95320	9.8E+09
OBD repair European r Peugeot	95640	9.68E+09
OBD repair European r public	24C08	6Q0909601E
OBD repair European r public	24C08	6Q0909601E(With switch)
OBD repair European r public	24C08	6Q0909601F
OBD repair European r public	24C08	6Q0909601F(With switch)
OBD repair European r public	95160	Touran -1T0909605D
OBD repair European r public	95160	Tiguan -1T0909605D
OBD repair European r public	95320	65D959655A
OBD repair European r public	95320	65D959655B
OBD repair European r public	95320	6R0959655
OBD repair European r public	95320	6RD959655
OBD repair European r public	95320	6RD959655D
OBD repair European r public	95320	6RD959655F
OBD repair European r public	95320	Bora -6R0959655B
OBD repair European r public	95320	Bora -6RD959655A
OBD repair European r public	95320	Bora -6RD959655B
OBD repair European r public	95320	Bora -6RD959655C
OBD repair European r public	95320	Lavender -6R0959655B
OBD repair European r public	95320	Lavender -6RD959655A
OBD repair European r public	95320	Lavender -6RD959655B
OBD repair European r public	95320	Lavender -6RD959655C
OBD repair European r public	95640	3CD959655
OBD repair European r public	95640	3CD959655A
OBD repair European r public	95640	5ND959655
OBD repair European r public	95640	CC-5ND959655A
OBD repair European r public	95640	Magotan -5ND959655B
OBD repair European r public	95640	Magotan -5ND959655C
OBD repair European r public	95640	Tiguan -5ND959655A
OBD repair European r public	95640	Tiguan -5ND959655B
OBD repair European r public	95640	Tiguan -5ND959655C
OBD repair European r Fiat	24C04	46765164
OBD repair European r Fiat	24C04	46765165
OBD repair European r Fiat	24C04	51718981
OBD repair European r Fiat	95080	5WK43823
OBD repair European r Renault	95080	600-63-95-00
OBD repair European r Renault	95160	605-49-01-00
OBD repair European r Renault	95320	98820-JY10A
OBD repair European r Land Rover	95080	5WK4-3117-22050312
OBD repair European r Land Rover	95320	9H52-14D374-AD
OBD repair European r Opel	95160	13-227-920
OBD repair European r Opel	95160	13-246-041
OBD repair European r Opel	95160	13-246-046
OBD repair European r Opel	95160	13-251-081
OBD repair European r Opel	95160	13-288-174
OBD repair European r Skoda	95320	6R0-959-655-B
OBD repair European r Skoda	95320	6RD-959-655
OBD repair European r Skoda	95320	6RD-959-655-A
OBD repair European r Citroen	25320	610-79-95-00
OBD repair European r Citroen	93C66	601-95-17-00
OBD repair European r Citroen	93C66	601-95-18-00
OBD repair European r Citroen	95080	600-23-76-00
OBD repair European r Citroen	95080	9.65E+09
OBD repair European r Citroen	95080	9.66E+09
OBD repair European r Citroen	95080	9.66E+09

OBD repair European r Citroen	95080 ZQ00731180-5WK43855
OBD repair European r Citroen	95080 ZQ00731280-5WK43856
OBD repair European r Citroen	95080 ZQ00811180-5WK44152
OBD repair European r Citroen	95080 ZQ00811280-5WK44153
OBD repair European r Citroen	95080 ZQ00885680-5WK44325
OBD repair European r Citroen	95080 ZQ00885780
OBD repair European r Citroen	95320 4YC94953
OBD repair European r Citroen	95320 9.66E+09
OBD repair European r Citroen	95320 9.67E+09
OBD repair European r Citroen	95320 9.67E+09
OBD repair European r Citroen	95320 9.67E+09
OBD repair European r Citroen	95320 9.67E+09
OBD repair European r Citroen	95320 9.67E+09
OBD repair European r Citroen	95320 9.67E+09
OBD repair European r Citroen	95320 9.68E+09
OBD repair European r Citroen	95320 9.68E+09
OBD repair European r Citroen	95320 9.81E+09
OBD repair European r Citroen	95640 9.8E+09
OBD repair Asian modt Honda	24C01A 77960-S3N-N93
OBD repair Asian modt Honda	24C01A 77960-S84-A86
OBD repair Asian modt Honda	24C01A 77960-SV4-A95
OBD repair Asian modt Honda	25320 77960-SDA-Y614-M1
OBD repair Asian modt Honda	25320 77960-SDA-Y615-M1
OBD repair Asian modt Honda	25320 77960-SDA-Y630-M1
OBD repair Asian modt Honda	25320 77960-SDA-Y631-M1
OBD repair Asian modt Honda	25320 77960-SDA-Y840-M1
OBD repair Asian modt Honda	25320 77960-SDA-Y915-M1
OBD repair Asian modt Honda	25320 77960-SDA-Y930-M1
OBD repair Asian modt Honda	25320 SDA-A615-M1(Accord CM5)
OBD repair Asian modt Honda	93C46 77960-SV4-308
OBD repair Asian modt Honda	93C66 77960-SFJ-W910-M2
OBD repair Asian modt Honda	93C86 77960-TF0-H420-M3
OBD repair Asian modt Honda	93C86 77960-TF0-H620-M3
OBD repair Asian modt Honda	93C86 77960-SLE-H012-M3
OBD repair Asian modt Honda	93C86 77960-SLE-H812-M3
OBD repair Asian modt Honda	93C86 77960-TF0-H621-M3
OBD repair Asian modt Honda	93C86 77960-TF0-H820-M3
OBD repair Asian modt Honda	93C86 77960-TM0-H421-M3
OBD repair Asian modt Honda	93C86 77960-TM0-H821-M3
OBD repair Asian modt Honda	93C86 77960-TM0-X621-M3
OBD repair Asian modt Honda	95320 77960-S9A-Y412-M1
OBD repair Asian modt Honda	95320 77960-S9A-Y413-M1
OBD repair Asian modt Honda	95320 77960-S9A-Y414-M1
OBD repair Asian modt Honda	95320 77960-T6P-H411-M1
OBD repair Asian modt Honda	95320 77960-T6P-H611-M1
OBD repair Asian modt Honda	95320 77960-TR0-H714-M1
OBD repair Asian modt Honda	95320 77960-TR0-H715-M1
OBD repair Asian modt Honda	95320 77960-TR0-H720-M1
OBD repair Asian modt Honda	95320 77960-TS6-H711-M1
OBD repair Asian modt Honda	95640 77960-TC0-H211-M
OBD repair Asian modt Honda	95640 77960-SNA-H010-M1
OBD repair Asian modt Honda	95640 77960-SNA-H020-M1
OBD repair Asian modt Honda	95640 77960-SNA-H211-M1
OBD repair Asian modt Honda	95640 77960-SNA-H222-M1
OBD repair Asian modt Honda	95640 77960-SNA-H811-M1
OBD repair Asian modt Honda	95640 77960-SNA-H821-M1

OBD repair Asian mod	Honda	95640	77960-SNA-H822-M1
OBD repair Asian mod	Honda	95640	77960-SNA-H830-M1
OBD repair Asian mod	Honda	95640	77960-SWA-H010-M4
OBD repair Asian mod	Honda	95640	77960-SWA-H213-M4
OBD repair Asian mod	Honda	95640	77960-SWA-H811-M4
OBD repair Asian mod	Honda	95640	77960-SWA-H812-M4
OBD repair Asian mod	Honda	95640	77960-SYJ-H1111-M4
OBD repair Asian mod	Honda	95640	77960-T0A-H911-M4
OBD repair Asian mod	Honda	95640	77960-T0A-H912-M4
OBD repair Asian mod	Honda	95640	77960-T0A-H920-M4
OBD repair Asian mod	Honda	95640	77960-T2A-H911-M1
OBD repair Asian mod	Honda	95640	77960-T4N-H711-M1
OBD repair Asian mod	Honda	95640	77960-T5A-H611-M1
OBD repair Asian mod	Honda	95640	77960-TC0-H012-M1
OBD repair Asian mod	Honda	95640	77960-TC0-H212-M1
OBD repair Asian mod	Honda	95640	77960-TFC-H910-M4
OBD repair Asian mod	Honda	95640	77960-TP5-H1111-M1
OBD repair Asian mod	Toyota	25040	89170-0D360
OBD repair Asian mod	Toyota	25040	89170-0D500
OBD repair Asian mod	Toyota	93C46	89170-30060
OBD repair Asian mod	Toyota	93C56	89170-02A90
OBD repair Asian mod	Toyota	93C66	89170-06340
OBD repair Asian mod	Toyota	93C66	89170-0D400
OBD repair Asian mod	Toyota	93C66	89170-0E040
OBD repair Asian mod	Toyota	93C66	89170-0P010
OBD repair Asian mod	Toyota	93C66	89170-0P012
OBD repair Asian mod	Toyota	93C66	89170-0R030
OBD repair Asian mod	Toyota	93C66	89170-0R040
OBD repair Asian mod	Toyota	93C66	89170-0R041
OBD repair Asian mod	Toyota	93C66	89170-0R050
OBD repair Asian mod	Toyota	93C66	89170-42230
OBD repair Asian mod	Toyota	93C66	89170-42640
OBD repair Asian mod	Toyota	93C66	89170-48260
OBD repair Asian mod	Toyota	93C66	89170-60170
OBD repair Asian mod	Toyota	93C66	89170-60650
OBD repair Asian mod	Toyota	93C66	LS460-89170-50260
OBD repair Asian mod	Toyota	LC56	89170-02700
OBD repair Asian mod	Toyota	93LC56	89170-02430
OBD repair Asian mod	Toyota	93LC56	89170-06190
OBD repair Asian mod	Toyota	93LC56	89170-06330
OBD repair Asian mod	Toyota	93LC56	89170-0N010
OBD repair Asian mod	Toyota	93LC56	89170-0N020
OBD repair Asian mod	Toyota	93LC56	89170-33260
OBD repair Asian mod	Toyota	93LC56	89170-60110
OBD repair Asian mod	Toyota	93LC56	89170-60200
OBD repair Asian mod	Toyota	93LC66	89170-02770
OBD repair Asian mod	Toyota	93LC66	89170-06430
OBD repair Asian mod	Toyota	93LC66	ES350-89170-33560
OBD repair Asian mod	Toyota	95160	89170-02F40
OBD repair Asian mod	Toyota	95160	89170-0D650
OBD repair Asian mod	Toyota	95160	89170-0F200
OBD repair Asian mod	Suzuki	24C16	38910-77J00
OBD repair Asian mod	Suzuki	25160	38910-C14B0
OBD repair Asian mod	Suzuki	93C46	38910-65D1
OBD repair Asian mod	Suzuki	93C56	38910-82J0
OBD repair Asian mod	Suzuki	95080	38910-59J70

OBD repair Asian mod Suzuki	95160 38910-56K00
OBD repair Asian mod Suzuki	95160 38910-56K01-000
OBD repair Asian mod Suzuki	95160 38910-56K02-000
OBD repair Asian mod Suzuki	95160 38910-56K10-000
OBD repair Asian mod Suzuki	95160 38910-56K11-000
OBD repair Asian mod Suzuki	95160 38910-56K12
OBD repair Asian mod Suzuki	95160 38910-56K12-000
OBD repair Asian mod Suzuki	95160 38910-56K21-000
OBD repair Asian mod Suzuki	95160 38910-77J00-000
OBD repair Asian mod Suzuki	95160 38910-77J01
OBD repair Asian mod Suzuki	95160 38910-77J01-000
OBD repair Asian mod Suzuki	95160 38910-77J02-000
OBD repair Asian mod Suzuki	95160 38910-77J20-000
OBD repair Asian mod Suzuki	95160 38910-C1100
OBD repair Asian mod Mazda	24C04 B30K-57-K30-B-5F24B
OBD repair Asian mod Mazda	24C04 C175-57-K30-B-5J11B
OBD repair Asian mod Mazda	24C04 C176-57-K30-B-3G09A
OBD repair Asian mod Mazda	24C04 C176-57-K30-B-4A13E
OBD repair Asian mod Mazda	24C04 C176-57-K30-B-6H21A
OBD repair Asian mod Mazda	93C86 W2T80271
OBD repair Asian mod Mazda	95080 BP4-M57-K30
OBD repair Asian mod Mazda	95080 BR9-N57-K30
OBD repair Asian mod Mazda	95080 FA11-57-K30-M1
OBD repair Asian mod Mazda	95080 FA11-57-K30-M2
OBD repair Asian mod Mazda	95080 GJ6A-57-K30C
OBD repair Asian mod Mazda	95080 GJ6A-57-K30D
OBD repair Asian mod Mazda	95080 GJ6R-57-K30D
OBD repair Asian mod Mazda	95080 HMCA-57-K30
OBD repair Asian mod Mazda	95080 Familia 323-HMCA-57-K30-M1A
OBD repair Asian mod Mazda	95080 Haifuxing -HMCA-57-K30-M1A
OBD repair Asian mod Mazda	95080 HMFA-57-K30
OBD repair Asian mod Mazda	95160 FA03-57-K30-M2
OBD repair Asian mod Mazda	95160 L20-657-K30
OBD repair Asian mod Mazda	95320 DG80-57-K30-A
OBD repair Asian mod Mazda	95320 DG80-57-K30-B
OBD repair Asian mod Mazda	95320 EH62-57-K30A-K0273
OBD repair Asian mod Mazda	95320 G31A-57-K30B
OBD repair Asian mod Mazda	95320 G31F-57-K30A
OBD repair Asian mod Mazda	95640 BFF4-57-K30
OBD repair Asian mod Mazda	95640 BHL6-57-K30-A
OBD repair Asian mod Mazda	95640 GS1D-57K30
OBD repair Asian mod Mazda	95640 GS1D-57K30B
OBD repair Asian mod Mazda	95640 KR12-57K30
OBD repair Asian mod idea	93C56 77960-S0L-H410-M2
OBD repair Asian mod Acura	93C86 77960-STX-H010-M1
OBD repair Asian mod Kia	25256 95910-1X000
OBD repair Asian mod Kia	25320 95910-0S600
OBD repair Asian mod Kia	25320 95910-2F100
OBD repair Asian mod Kia	25320 95910-2F200
OBD repair Asian mod Kia	25320 95910-4T000
OBD repair Asian mod Kia	25320 95910-4T250
OBD repair Asian mod Kia	25640 95910-0C300
OBD repair Asian mod Kia	25640 95910-0C400
OBD repair Asian mod Kia	25640 95910-1G000
OBD repair Asian mod Kia	95080 95960-3E100
OBD repair Asian mod Kia	95128 95910-4X000

OBD repair Asian mod	Kia	95128	95910-B5000
OBD repair Asian mod	Kia	95128	95910-B5100
OBD repair Asian mod	Kia	95256	95910-1M000
OBD repair Asian mod	Kia	95256	95910-4M300
OBD repair Asian mod	Kia	95256	95910-4M400
OBD repair Asian mod	Kia	95256	95910-4M450
OBD repair Asian mod	Kia	95256	95910-D1400
OBD repair Asian mod	Kia	95320	95910-0S500
OBD repair Asian mod	Kia	95320	95910-4T200
OBD repair Asian mod	Kia	95640	95910-2X000
OBD repair Asian mod	Nissan	93C46	28556-8M52E
OBD repair Asian mod	Nissan	93C46	28556-8M605
OBD repair Asian mod	Nissan	93C46	285569S60A
OBD repair Asian mod	Nissan	93C46	5E910
OBD repair Asian mod	Nissan	93C46	5E911
OBD repair Asian mod	Nissan	93C46	7M605
OBD repair Asian mod	Nissan	93C46	7M60E
OBD repair Asian mod	Nissan	93C46	VK000
OBD repair Asian mod	Nissan	93C46	Aeolus bluebird -9S600
OBD repair Asian mod	Nissan	93C46	Paladin -9S600
OBD repair Asian mod	Nissan	93C56	28556-EW32E
OBD repair Asian mod	Nissan	93C56	28556-EW33E
OBD repair Asian mod	Nissan	93C56	285561HD1A
OBD repair Asian mod	Nissan	93C56	285561YP0A
OBD repair Asian mod	Nissan	93C56	28556CJ00A
OBD repair Asian mod	Nissan	93C56	28556CJ00D
OBD repair Asian mod	Nissan	93C56	28556JX03B
OBD repair Asian mod	Nissan	93C56	98820-3L400
OBD repair Asian mod	Nissan	93C56	988201AH3A
OBD repair Asian mod	Nissan	95160	28556-JC20A
OBD repair Asian mod	Nissan	95160	28556-1DE0A
OBD repair Asian mod	Nissan	95160	28556-1DE0B
OBD repair Asian mod	Nissan	95160	28556-2FJ0A
OBD repair Asian mod	Nissan	95160	28556-3ZA0A
OBD repair Asian mod	Nissan	95160	28556-JC20B
OBD repair Asian mod	Nissan	95160	28556-JE20A
OBD repair Asian mod	Nissan	95160	28556-JE40B
OBD repair Asian mod	Nissan	95160	98820-1DF0A
OBD repair Asian mod	Nissan	95160	98820-1DF0B
OBD repair Asian mod	Nissan	95160	98820-3ZB0A
OBD repair Asian mod	Nissan	95160	98820-JE30A
OBD repair Asian mod	Nissan	95160	98820-JE50A
OBD repair Asian mod	Nissan	95160	98820-JE50B
OBD repair Asian mod	Nissan	95160	98820-JN30B
OBD repair Asian mod	Nissan	95160	Scorpio -98820-JN30A
OBD repair Asian mod	Nissan	95160	Hacker -98820-JN30A
OBD repair Asian mod	Nissan	LC56	98820-EX70A
OBD repair Asian mod	Nissan	LC56	28556-EW32C
OBD repair Asian mod	Nissan	LC56	6EU10A
OBD repair Asian mod	Nissan	LC56	98820-1NC0A
OBD repair Asian mod	Nissan	LC56	9W100
OBD repair Asian mod	Nissan	LC56	9W10E
OBD repair Asian mod	Nissan	LC56	EW300
OBD repair Asian mod	Nissan	LC56	EW32D
OBD repair Asian mod	Mitsubishi	25160	8635A154
OBD repair Asian mod	Mitsubishi	25160	8635A183L

OBD repair Asian mod Mitsubishi	25160	MN141170
OBD repair Asian mod Mitsubishi	25160	Golan -MN141536
OBD repair Asian mod Mitsubishi	25160	Outlander -MN141536
OBD repair Asian mod Mitsubishi	25640	8635A055
OBD repair Asian mod Mitsubishi	25640	P8635A062
OBD repair Asian mod Mitsubishi	25640	P8635A206
OBD repair Asian mod Mitsubishi	25640	P8635A207
OBD repair Asian mod Mitsubishi	25640	P8635A247
OBD repair Asian mod Mitsubishi	25640	TCJME1368J
OBD repair Asian mod Mitsubishi	25640	TGBMH161000945
OBD repair Asian mod Mitsubishi	25640	TGBMH348901005
OBD repair Asian mod Mitsubishi	93C46	MR268-157
OBD repair Asian mod Mitsubishi	93C56	MB953-175
OBD repair Asian mod Mitsubishi	93C56	MN141-499-DPB
OBD repair Asian mod Mitsubishi	93C56	W2T65271
OBD repair Asian mod Mitsubishi	93C66	8635A160
OBD repair Asian mod Mitsubishi	93C76	8635A123
OBD repair Asian mod Mitsubishi	93LC56	MN141-499-DPB-2
OBD repair Asian mod Mitsubishi	95640	8635A215
OBD repair Asian mod Mitsubishi	95640	8635A303
OBD repair Asian mod Mitsubishi	95640	TGBMH293902189
OBD repair Asian mod Subaru	93C56	98221SA140
OBD repair Asian mod Subaru	93C86	98221SC030
OBD repair Asian mod Subaru	93C86	98221XA05A
OBD repair Asian mod modern	25256	95910-B3300
OBD repair Asian mod modern	25320	95910-2Z000
OBD repair Asian mod modern	25320	95910-2Z200
OBD repair Asian mod modern	25640	95910-0M000
OBD repair Asian mod modern	25640	95910-0Q000
OBD repair Asian mod modern	25640	95910-0R100
OBD repair Asian mod modern	25640	95910-1E000
OBD repair Asian mod modern	25640	95910-1Z000
OBD repair Asian mod modern	95080	95910-09100
OBD repair Asian mod modern	95080	95910-26200
OBD repair Asian mod modern	95080	95910-26600
OBD repair Asian mod modern	95080	95910-3D000
OBD repair Asian mod modern	95080	95910-3D100
OBD repair Asian mod modern	95080	95910-3D200
OBD repair Asian mod modern	95128	95910-0U100
OBD repair Asian mod modern	95128	95910-4V100
OBD repair Asian mod modern	95256	95910-4Q100
OBD repair Asian mod modern	95256	95910-4Q300
OBD repair Asian mod modern	95320	95910-2B170
OBD repair Asian mod modern	95320	95910-2B200
OBD repair Asian mod modern	95320	95910-3J200
OBD repair Asian mod modern	95640	95910-0R200
OBD repair Asian mod modern	95640	95910-2B180
OBD repair Asian mod modern	95640	95910-3M250
OBD repair Asian mod Infiniti	93C56	988201NC0A
OBD repair Asian mod Infiniti	LC56	988201NC1A
OBD repair Domestic n Baojun 630	95320	24537297/5WK44411
OBD repair Domestic n Beijing Aut	25160	B6260180AA
OBD repair Domestic n Beijing Aut	95160	1.14E+08
OBD repair Domestic n Beiqi	95160	58240100-B01
OBD repair Domestic n Beiqi	95160	5824100-B21-000
OBD repair Domestic n BYD	24C02	3658-1A

OBD repair Domestic nBYD	24C04	3569-1C
OBD repair Domestic nBYD	24C04	3658-1B
OBD repair Domestic nBYD	24C04	3658100-A1
OBD repair Domestic nBYD	24C04	3658100-A2
OBD repair Domestic nBYD	24C04	LK-3658100B
OBD repair Domestic nBYD	24C16	3658100-C1
OBD repair Domestic nBYD	24C16	3658100A
OBD repair Domestic nBYD	24C16	3658100B
OBD repair Domestic nBYD	24C16	5A-3658100
OBD repair Domestic nBYD	24C16	5A-3658100B
OBD repair Domestic nBYD	24C16	6AP-3658100
OBD repair Domestic nBYD	24C16	EG-3658100
OBD repair Domestic nBYD	24C16	F6-3658100
OBD repair Domestic nBYD	24C16	L3-3658100
OBD repair Domestic nChanghe	93C46	38910-75FA0
OBD repair Domestic nChanghe	95080	38910-59J70-000
OBD repair Domestic nDongfeng	25160	28556-2ZS70
OBD repair Domestic nDongfeng	25160	82MK-14150
OBD repair Domestic nDongfeng	95080	28556W6600
OBD repair Domestic nDongfeng	95080	B-5824050
OBD repair Domestic nDongfeng	95080	B-5824150
OBD repair Domestic nDongfeng	95080	U410010JB0100
OBD repair Domestic nDongfeng	95080	U410010JB0101
OBD repair Domestic nDongfeng	95080	U410010JB0107
OBD repair Domestic nDongfeng	95160	28556-2ZS00
OBD repair Domestic nDongfeng	95160	B12-5824010
OBD repair Domestic nDongfeng	95160	B20-5824010
OBD repair Domestic nDongfeng	95160	BX5A-5824020
OBD repair Domestic nDongfeng	95320	BX5A-5824010
OBD repair Domestic nsoutheast	93C66	W2T65672-8635A159
OBD repair Domestic nsoutheast	95080	5WK44161
OBD repair Domestic nsoutheast	95080	SW803814
OBD repair Domestic nsoutheast	95080	SW803815
OBD repair Domestic nsoutheast	95080	Ling -SW806408
OBD repair Domestic nsoutheast	95080	SW806408/J3858172
OBD repair Domestic nsoutheast	95320	J3858207
OBD repair Domestic nsoutheast	95320	J3858209
OBD repair Domestic nsoutheast	95320	J3858210
OBD repair Domestic nGuangqi Ci	95640	222426-147
OBD repair Domestic nHafei	93C56	MR551-800
OBD repair Domestic nSeahorse	25320	SA00-57-K30M1
OBD repair Domestic nSeahorse	95080	FA02-57-K30M1
OBD repair Domestic nSeahorse	95080	FA11-57-K30-M2
OBD repair Domestic nSeahorse	95080	HMFA-A57-30
OBD repair Domestic nSeahorse	95080	MA10-57-K30M1
OBD repair Domestic nSeahorse	95080	MA20-57-K30M1
OBD repair Domestic nSeahorse	95160	FA30-57-K30-M2
OBD repair Domestic nSeahorse	95160	FE12-57-K30
OBD repair Domestic nSeahorse	95160	PA10-57-K30M1(Types of 1)
OBD repair Domestic nSeahorse	95160	PA10-57-K30M1(Types of 2)
OBD repair Domestic nSeahorse	95320	FA03-57-K30M1
OBD repair Domestic nSeahorse	95320	FA13-57-K30M1
OBD repair Domestic nSeahorse	95320	MA30-57-K30M1
OBD repair Domestic nMaple	25160	A0200059796
OBD repair Domestic nHuatai	95320	36581000S09
OBD repair Domestic nauspicious	25160	1703533B

OBD repair Domestic nauspicious	25160 6.11E+08
OBD repair Domestic nauspicious	25160 6.2E+08
OBD repair Domestic nauspicious	25160 6.2E+08
OBD repair Domestic nauspicious	25160 A0200030180
OBD repair Domestic nauspicious	25160 A020005158V
OBD repair Domestic nauspicious	25160 A020006311N
OBD repair Domestic nauspicious	25160 A020011368V
OBD repair Domestic nauspicious	25160 A020053633W
OBD repair Domestic nauspicious	25160 A020082830X
OBD repair Domestic nauspicious	25160 A0201001221
OBD repair Domestic nauspicious	25160 A020102343P
OBD repair Domestic nauspicious	25160 A020111137Q
OBD repair Domestic nauspicious	25160 J3858048
OBD repair Domestic nauspicious	95040 1709536
OBD repair Domestic nauspicious	95160 0285-010
OBD repair Domestic nauspicious	95160 1703577(Types of 1)
OBD repair Domestic nauspicious	95160 1703577(Types of 2)
OBD repair Domestic nauspicious	95160 1709516(Types of 1)
OBD repair Domestic nauspicious	95160 1709516(Types of 2)
OBD repair Domestic nauspicious	95160 6.11E+08
OBD repair Domestic nauspicious	95160 620432200B
OBD repair Domestic nauspicious	95160 620432400B
OBD repair Domestic nauspicious	95160 6.26E+08
OBD repair Domestic nauspicious	95160 A020024044Q
OBD repair Domestic nauspicious	95160 A020089989J
OBD repair Domestic nauspicious	95640 222425-127
OBD repair Domestic nauspicious	95640 222426
OBD repair Domestic nauspicious	95640 6.11E+08
OBD repair Domestic nauspicious	95640 611172500D
OBD repair Domestic nauspicious	95640 6.11E+08
OBD repair Domestic nauspicious	95640 611172600D
OBD repair Domestic nJianghuai	95080 5824901U7150
OBD repair Domestic nJianghuai	95080 5824901U8010
OBD repair Domestic nJianghuai	95080 5824901U8015
OBD repair Domestic nJianghuai	95160 5824901U1010
OBD repair Domestic nJianghuai	95160 5824901U2010(Types of 1)
OBD repair Domestic nJianghuai	95160 5824901U2010(Types of 2)
OBD repair Domestic nJianghuai	95160 5824901U2011(Types of 1)
OBD repair Domestic nJianghuai	95160 5824901U2011(Types of 2)
OBD repair Domestic nJianghuai	95160 5824901U7101
OBD repair Domestic nJianghuai	95160 5824901U7101B
OBD repair Domestic nJiangling	25160 3414070-B01
OBD repair Domestic nJiangling	25160 5820011LC/J3858107
OBD repair Domestic nJiangling	25160 J3858106
OBD repair Domestic nJiangling	25320 J3858126
OBD repair Domestic nGold cup	95080 3414070-F01/J3858038
OBD repair Domestic nGold cup	95080 6.06E+08
OBD repair Domestic nGold cup	95080 3023317/J3858022
OBD repair Domestic nGold cup	95080 3023318/J3858023
OBD repair Domestic nLifan	25160 J3858044/L3658100A1
OBD repair Domestic nLifan	25160 LAX3658100D1
OBD repair Domestic nLifan	25160 other
OBD repair Domestic nLifan	95080 F3658100
OBD repair Domestic nLifan	95160 B3658100(Types of 1)
OBD repair Domestic nLifan	95160 B3658100(Types of 2)
OBD repair Domestic nLifan	95160 LAX3658100B1

OBD repair Domestic nlotus	95080 PW851834
OBD repair Domestic nlotus	95160 EC5824106N
OBD repair Domestic nmg	25160 4E+08
OBD repair Domestic nmg	25640 10043844-05
OBD repair Domestic nmg	25640 10043844-06
OBD repair Domestic nmg	95080 609-90-97-00-AA
OBD repair Domestic nmg	95080 610-39-64-00B
OBD repair Domestic nmg	95080 610-40-05-00
OBD repair Domestic nmg	95320 10001800
OBD repair Domestic nmg	95640 10104454-01
OBD repair Domestic nmg	95640 10104458-01
OBD repair Domestic nNa Zhijie	95320 28556SU110
OBD repair Domestic nChery	25160 M11-36060VB
OBD repair Domestic nChery	25160 T11-3606011
OBD repair Domestic nChery	25160 T11-3606011BA
OBD repair Domestic nChery	25320 M11-3606010NB
OBD repair Domestic nChery	25640 M11-3606010
OBD repair Domestic nChery	95080 A21-3606010
OBD repair Domestic nChery	95160 A13-3606010GA
OBD repair Domestic nChery	95160 J52-3606010FL
OBD repair Domestic nChery	95160 J52-3658010
OBD repair Domestic nChery	95160 QQ6-A13-3606010
OBD repair Domestic nChery	95160 Storm clouds 2-A13-3606010
OBD repair Domestic nChery	95320 B21-3606010BB
OBD repair Domestic nChery	95320 T11-3606011PD
OBD repair Domestic nChery	95320 T21-3658070BA
OBD repair Domestic nRoewe	25640 1E+09
OBD repair Domestic nRoewe	95040 5E+09
OBD repair Domestic nRoewe	95040 5E+09
OBD repair Domestic nRoewe	95080 1E+09
OBD repair Domestic nRoewe	95080 10008700
OBD repair Domestic nRoewe	95080 YWC91161
OBD repair Domestic nRoewe	95320 1E+09
OBD repair Domestic nRoewe	95640 1.01E+09
OBD repair Domestic nDawn	25160 J3858226
OBD repair Domestic nSsangyong	95080 86250-08121
OBD repair Domestic nSsangyong	95080 86250-09041
OBD repair Domestic nSsangyong	95080 86251-31010
OBD repair Domestic nSsangyong	95080 86251-31040
OBD repair Domestic nTianjin FAV	25160 89170-52K70
OBD repair Domestic nTianjin FAV	25160 89170-TBA00
OBD repair Domestic nTianjin FAV	25160 89170-TKA00
OBD repair Domestic nWuling	25160 24557699
OBD repair Domestic nWuling	95080 5496016
OBD repair Domestic nWuling	95080 24519199
OBD repair Domestic nWuling	95160 24557700
OBD repair Domestic nFAW Daihε93C56	89170-BZ070
OBD repair Domestic nFAW Daihε93C56	89170-BZ080
OBD repair Domestic nChangan	25160 3414070-Q01
OBD repair Domestic nChangan	25160 3414070-W01
OBD repair Domestic nChangan 93C56	38910-843A0S
OBD repair Domestic nChangan	95080 3402200-C01
OBD repair Domestic nChangan	95080 3414070-A01
OBD repair Domestic nChangan	95080 3414070-F01
OBD repair Domestic nChangan	95080 3414070-F02
OBD repair Domestic nChangan	95080 38910-C80E00-000

OBD repair Domestic nChangan	95160 3414070-K02
OBD repair Domestic nChangan	95160 3414070-W01-AA
OBD repair Domestic nChangan	95160 38910-62L00
OBD repair Domestic nChangan	95320 3414700-N03
OBD repair Domestic nChangan	95320 3414700-U03(Without side airbag)
OBD repair Domestic nChangan	95320 3414700-U03(Side airbag)
OBD repair Domestic nChangan	95640 BKC3-57K30
OBD repair Domestic nGreat Wall	25160 3658110-J08
OBD repair Domestic nGreat Wall	25160 3658110XKZ16A
OBD repair Domestic nGreat Wall	95080 3658110-M16-B1
OBD repair Domestic nGreat Wall	95080 3658110-Y08
OBD repair Domestic nGreat Wall	95080 3658110A-G08
OBD repair Domestic nGreat Wall	95080 3658110A-V08
OBD repair Domestic nGreat Wall	95080 3658120-P00
OBD repair Domestic nGreat Wall	95080 3658120-S08
OBD repair Domestic nGreat Wall	95080 3658120-Y08
OBD repair Domestic nGreat Wall	95080 3658130-S08
OBD repair Domestic nGreat Wall	95080 3658160-K00
OBD repair Domestic nGreat Wall	95160 3658100XS56XA
OBD repair Domestic nGreat Wall	95160 3658110-J08-B
OBD repair Domestic nGreat Wall	95160 3658110A-J08
OBD repair Domestic nGreat Wall	95160 3658110XJZ08A
OBD repair Domestic nGreat Wall	95160 3658110XJZ08B
OBD repair Domestic nGreat Wall	95160 3658110XJZ08C
OBD repair Domestic nGreat Wall	95160 3658110XKZ16B
OBD repair Domestic nGreat Wall	95160 3658120-S08
OBD repair Domestic nGreat Wall	95160 3658120XKZ16B
OBD repair Domestic nGreat Wall	95160 3658120XKZ16C
OBD repair Domestic nGreat Wall	95160 3658130XS08XB
OBD repair Domestic nGreat Wall	95160 3658160-K18-B1
OBD repair Domestic nGreat Wall	95160 3658160-K84
OBD repair Domestic nGreat Wall	95320 3658110XSZ08A
OBD repair Domestic nGreat Wall	95320 3658160XK88XA
OBD repair Domestic nGreat Wall	95640 3658160AK80XA
OBD repair Domestic nChangfeng	25160 CA110182
OBD repair Domestic nChangfeng	25160 CA800216
OBD repair Domestic nChangfeng	25160 J3858059
OBD repair Domestic nChangfeng	95080 CH800017
OBD repair Domestic nChangfeng	95080 CH800307
OBD repair Domestic nChangfeng	95160 CA800278
OBD repair Domestic nChina FAW	95040 5CA0-57K30
OBD repair Domestic nChina FAW	95040 FA01-57K30-A
OBD repair Domestic nChina FAW	95040 FA03-57K30
OBD repair Domestic nChina FAW	95040 FA03-57K30-A
OBD repair Domestic nZhonghua	25160 3084107
OBD repair Domestic nZhonghua	25160 3091819
OBD repair Domestic nZhonghua	25160 J3858028
OBD repair Domestic nZhonghua	25160 Junjie -3491017
OBD repair Domestic nZhonghua	25160 Zunchi -3491017
OBD repair Domestic nZhonghua	95080 3051183
OBD repair Domestic nZhonghua	95080 3051187
OBD repair Domestic nZhonghua	95080 3101850
OBD repair Domestic nZhonghua	95080 3291018
OBD repair Domestic nZhonghua	95080 FRV 3491027
OBD repair Domestic nZhonghua	95320 J3858214
OBD repair Domestic nZhonghua	95320 J3858232

OBD repair Domestic nZhonghua	95320 J3858233
OBD repair Domestic nZTE	25160 3685010-0000
OBD repair Domestic nZhongtai	25160 3658010-06
OBD repair Domestic nZhongtai	95160 3658010-A01
OBD repair Domestic nZhongtai	95160 3658010BA-A01
Beijing Hyuix25(GC) 2014-2016 G 1.6 MPI	
Beijing Hyuix25(GC) 2014-2016 G 2.0 MPI	
Beijing HyuSONATA F 2016 G 2.0 HEV	
Beijing HyuSonata (LF 2015-2016 G 2.0 MPI	
Beijing HyuSonata (LF 2015-2016 G 2.4 GDI	
Beijing HyuSonata (LF 2015-2016 G 1.6T GDI	
Beijing HyuSonata (YF 2011-2016 G 2.0 MPI	
Beijing HyuNew winda 2012-2016 G 2.0 GDI	
Beijing HyuNew winda 2012-2016 G 2.4 GDI	
Beijing HyuNew Tucso2015-2016 G 1.6 GDI	
Beijing HyuNew Tucso2015-2016 G 2.0 GDI	
Beijing HyuLead (ADC 2016 G 1.6 MPI	
Beijing HyuLead (ADC 2016 G 1.6 GDI	
Beijing HyuLead (ADC 2016 G 1.4 GDI	
Beijing HyuName map 2016 G 2.0 MPI	
Beijing HyuName map 2016 G 1.8 MPI	
Beijing HyuName map 2016 G 1.6 GDI	
Beijing HyuName map 2014-2015 G 2.0 MPI	
Beijing HyuName map 2014-2015 G 1.8 MPI	